PH Chart

Parameter reading in Chart · built Nov 12, 2026

Parameter reading in Chart

The different parameters of chart are

1. pressure,

2. enthalpy,

3. temperature,

4. Quality

Pressure : It is represented by vertical axis. Pressure is measure either in psi or MPa or other pressure unit. In this chart we use MPa as a standard unit.

Enthalpy :


It represents the head in the system. Enthalpy is represented along the horizontal axis. The unit of enthalpy is taken as KJ/Kg(Kilo joule per kg).

Temperature:

It is represented by vertical lines in liquid and vapour section, and by horizontal lines in liquid vapour dome.

Quality :

This line exist inside the dome, and varies in terms of percentage(%).


Temperature lines
Pressure P[MPa]
Enthalpy h[KJ/kg]
Liquid region
Liquid-vapour region
Vapour region
Critical point
Quality lines
516°C
484°C
453°C
421°C
358°C
327°C
295°C
263°C
232°C
200°C
169°C
137°C
106°C
73°C
42°C
10 %
20 %
30 %
40 %
50 %
60 %
70 %
80 %
90 %
100
10
0.1
0.01
0.001
0
200
400
600
800
1000
1200
1400
1600
1800
2000
2200
2400
2600
2800
3000
3200
3400
3600
3800
4000