
Port Forwarding

*Port Forwarding


Following are the steps for port forwarding:

Step1. Set port forward for router:TCP 502(modbus TCP);UDP 47808(BIP port); UDP 1234(Temco private scan).


Step2.Click to show the tab as below,select “Remote Device”protocol.



Step3.It will show the tab as below, click to fil outer net IP or domain name.



Step4.Scan via T3000 software,the remote device can be connected.


T3000 Scanning
T3000 is scanning, please wait...
Exit
Scanning Mode
Skip
Status
Reply
Notes
Ethernet Scan
No
Finished
0
Network scan finished.
Remote IP Device
No
Running
1
Found remote device.


T3000 Building Automation System 2017.5.31
File
Tools
View
Database
Control
Miscellaneous
Help
Building View
aaa
Remote Network Device
T3-BB/LB/TB:90023
Virtual Device