Members:

Enes Taştan, 2068989, 0543 683 4336 Halil Temurtaş, 2094522, 0531 632 2194 Sarper Sertel, 2094449, 0542 515 6039 Erdem Tuna, 2167419, 0535 256 3320 İlker Sağlık, 2094423, 0541 722 9573



## March 19 - March 25 Weekly Report

## 1 Progress

- A pair of new DC motors were purchased and assembled to the chassis. New driving tests with these motors were done.
- Some problems in lane detection algorithm were noticed. Possible solutions were discussed.
- Initial attempts to control the longitudinal speed with lane angle information were attempted.
- Migration off python code of handshake protocol to C++ was started.

## 2 Plans

- Further PID controller design parameter tuning for controller subsystem with varying base speed (with Speed Subsystem).
- Improvements in Lane detection algorithm will be done.

