Enes Taştan, 2068989, 0543 683 4336 Halil Temurtaş, 2094522, 0531 632 2194

Sarper Sertel, 2094449, 0542 515 6039 Erdem Tuna, 2167419, 0535 256 3320 İlker Sağlık, 2094423, 0541 722 9573



February 12 - 19 Weekly Report

1 Progress

• Possible problematic cases on the path are analyzed. Some of them are shown in *Figure 1* and *Figure 1*. The image processing is improved according to studying cases.




Figure 1: Possible Problems on the Path - 1.




Figure 2: Possible Problems on the Path - 2.

• Racecourse is constructed.



Duayenler Ltd. Şti. Members :

February 17, 2019

Enes Taştan, 2068989, 0543 683 4336 Halil Temurtaş, 2094522, 0531 632 2194 Sarper Sertel, 2094449, 0542 515 6039 Erdem Tuna, 2167419, 0535 256 3320 İlker Sağlık, 2094423, 0541 722 9573

- Testing and Implementation of new motor-wheel pair and Li-Po battery is completed on current chassis.
- The measurements for new chassis were taken.
- The hotspot connection on Linux machines were studied.
- Measurement tests for ToF distance measurement sensor Polulu VL6180X are conducted.

2 Plans

- Internal communication subsystem will be studied.
- New chassis design will be drawn in 3D CAD software.

