

Preventative Maintenance Schedule

Document No: PM

Revision 0

Effective 03.2.20

Number	Machine Number	MONTHS OF THE YEAR											
		JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC
1	Recyling 01						X						X
2	Recyling 02	BREAKING FOR SPARES											
3	Recyling 03				X							X	
4	Recyling 04			X									
5	EX01	X											
6	EX02						X			X			
7	EX03		X										X
8	EX04					X						X	
9	EX05		X						X				
10	EX06										X		
11	EX07						X						
12	EX08				X						X		
13	EX09			X									X
14	EX10			X						X			
15	EX11					X							
16	EX12	MACHINE NOT ERECTED											
17	EX13							X					
18	EX14	X										X	
19	EX15				X						X		
20	EX16							X					
21	Mixer 01	X								X			
22	Mixer 02		X								X		
23	Core Cutter 01					X							
24	Core Cutter 02							X					
25	PR 01	X							X				
26	PR 02				X						X		
27	PR 03	X											
28	BM02		X										X
29	BM03					X							
30	BM04	BREAKING FOR SPARES											
31	BM05		X									X	
32	BM06					X							X
33	BM07								X				
34	BM08								X				
35	BM09				X						X		
36	BM10						X						
37	BM11	X											
38	BM12	BREAKING FOR SPARES											
39	BM13							X					
40	BM14	X											
41	BM15											X	
42	Slitter 01						X						
43	Slitter 02				X					X			
44	Slitter 03		X										
45	Puncher 01			X									
46	Puncher 02			X									
47	Puncher 03				X								
47	Core M/C 01					X							
48	PLANT ROOM	Compressor 01	X										
		Compressor 02							X				
		Compressor 3&4	BREAKING FOR SPARES										
		Generator	TO BE SERVICED AFTER 1000HOURS. TO JOG IT AFTER ONE MONTH OF BEING NOT USED										
		Chiller						X		X			

THIS PLANNED PREVETATIVE MAINTENANCE SCHEDULE WAS FORMULATED AFTER CONSIDERING THE FOLLOWING:
 machine usage, machine age, machine type/brand, production pick period, machine history and service history.