

norge
Search
About 11,400 results (0.24
Web
Images
Maps
Videos
News
More
Stavanger
Change location
Show search tools
Ad related to norsok d-010
Tilgang til standarder | st
www.standard.no/
Print on Demand og abonne
Kampanjer - Fagområder - K
NORSOK D-010
www.standard.no/en/sectors/
D-010 Well integrity in drilling
make this NORSOK standar
(PDF) NORSOK STANDA
www.standard.no/PageFiles/
File Format: PDF/Adobe
NORSOK Standard
Foreword. 4. In
11
NORSOK D
www.standard.no
Revision of NOR
started. Your input and comm
NORSOK D-010
www.standard.no/en/sectors/
Cart icon. No product(s) in c

NORSOK STANDARD

D-010
Rev. 3, August 2004

Well integrity in drilling and well operations


This NORSOK standard is developed with broad petroleum industry participation by interested parties in the Norwegian petroleum industry and is owned by the Norwegian petroleum industry represented by The Norwegian Oil Industry Association (OLF) and Federation of Norwegian Manufacturing Industries (TBL). Please note that whilst every effort has been made to ensure the accuracy of this NORSOK standard, neither OLF nor TBL or any of their members will assume liability for any use thereof. Standards Norway is responsible for the administration and publication of this NORSOK standard.

Standards Norway
Strandveien 18, P.O. Box 242
N-1326 Lysaker
NORWAY


Telephone: +47 67 83 86 00
Fax: +47 67 83 86 01
Email: petroleum@standard.no
Website: www.standard.no/petroleum

Copyrights reserved









To:

Oil & Gas Companies operating on the Norwegian Continental Shelf

Drilling Contractors operating on the Norwegian Continental Shelf


POST MACONDO RECOMMENDATION LETTER No. 1

Deepwater Horizon Follow-Up
OLF Joint Industry Project

OLF The Norwegian Oil Industry Association
Vassbotnen 1, P.O.Box 8065, N-4068 Stavanger
Telephone 51 84 65 00, Fax 51 84 65 01
Organisation no: NO 956 685 818 VAT
firmapost@olf.no

En landsforening i NHO





Category	Principle
Red	One barrier failure and the other is degraded/not verified, or leak to surface
Orange	One barrier failure and the other is intact, or a single failure may lead to leak to surface
Yellow	One barrier degraded, the other is intact
Green	Healthy well - no or minor issue