



(a) Calibration: closure + cracking



(b) Zero-refit prediction



(c) drag phase; markers = measured @72 h

