

Public Records

License Plate Report For:

7VNH893

California

Prepared On:

May 13, 2026

[Report Link](#)

YOU MAY NOT USE OUR SERVICE OR THE INFORMATION IT PROVIDES TO MAKE DECISIONS ABOUT CONSUMER CREDIT, EMPLOYMENT, INSURANCE OR TENANT SCREENING. BECAUSE ERRORS CAN OCCUR WITH ANY DATA SOURCES, SOME RECORDS MAY NOT BE ACCURATE OR UP TO DATE.

VEHICLE HISTORY REPORT

REPORT NUMBER:	11
REPORT DATE:	5/13/2026
STATUS:	COMPLETE
REFERENCE:	1

VIN: 1C4PJLDB6GW233283

VEHICLE:	JEEP CHEROKEE 2016
ASSEMBLED:	FCA US LLC
VEHICLE AGE:	10 YEARS



OVERVIEW

LAST ODOMETER:	181,573 MILES
TOTAL OWNERS:	3 OWNERS
ACCIDENT COUNT:	NONE
DETAILED HISTORY:	11 RECORDS
AUCTIONS & INSIGHTS:	NONE
LAST TITLE STATE:	CA
HISTORICAL SALES LISTINGS:	NONE
HISTORICAL OWNER RECORDS:	3 RECORDS
NHTSA RECALLS:	9 RECALLS

PRIOR VEHICLE USAGE

PERSONAL:	YES
FLEET:	NO
RENTAL:	YES
LEASE:	NO
TAXI:	NO
POLICE:	NO
GOVERNMENT:	NO
COMMERCIAL:	NO

TITLE BRAND CHECKS

LEMON:	NO ISSUES
MANUFACTURER:	NO ISSUES
ODOMETER:	NO ISSUES
SALVAGE:	NO ISSUES
LOAN/LIEN:	REPORTED
FIRE:	NO ISSUES
JUNK:	NO ISSUES
HAIL:	NO ISSUES
REBUILT:	NO ISSUES
FLOOD:	NO ISSUES
TITLED TO INSURANCE COMPANY:	NO ISSUES
INSURANCE LOSS:	NO ISSUES
REBUILT/REBUILDABLE:	NO ISSUES
NOT ACTUAL MILEAGE:	NO ISSUES
ODOMETER EXCEEDS MECHANICAL LIMITS/NOT ACTUAL MILEAGE:	NO ISSUES
THEFT:	NO ISSUES
RECYCLED:	NO ISSUES
JUNK/SCRAPPED:	NO ISSUES
DUPLICATE TITLES:	NO ISSUES

ESTIMATED MARKET VALUE

VEHICLE CONDITION	PRIVATE SALE	TRADE IN
PERFECT	\$9,000	–
VERY GOOD	\$7,700	\$7,805
AVERAGE	\$5,900	\$6,005
ROUGH	\$4,200	\$3,990

HISTORICAL INCIDENTS

NO HISTORICAL INCIDENTS FOUND

HISTORICAL OWNER RECORDS

USAGE:	RENTAL
STATUS:	FIRST
OWNED SINCE:	12/2015
LOCATION:	OK

USAGE:	PERSONAL
STATUS:	PREVIOUS
OWNED SINCE:	11/2016
LOCATION:	CA

USAGE:	PERSONAL
STATUS:	CURRENT
OWNED SINCE:	06/2025
LOCATION:	CA

DETAILED VEHICLE HISTORY

DATE:	12/30/2015
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	CALIFORNIA
ODOMETER:	7 MILES
DETAILS:	TITLE ISSUED OR UPDATED, REGISTRATION ISSUED OR RENEWED, TITLED OR REGISTERED AS A RENTAL VEHICLE, OR PART OF A RENTAL FLEET

DATE:	10/12/2016
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	CALIFORNIA
ODOMETER:	20,487 MILES
DETAILS:	PASSED EMISSION INSPECTION

DATE:	10/29/2016
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	CALIFORNIA
ODOMETER:	20,521 MILES
DETAILS:	ODOMETER READING FROM MOTOR VEHICLE DEPARTMENT

DATE:	11/08/2016
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	LIVERMORE, CA
DETAILS:	TITLE ISSUED OR UPDATED LIEN REPORTED, REGISTRATION ISSUED OR RENEWED

DATE:	06/28/2017
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	LIVERMORE, CA
DETAILS:	TITLE ISSUED OR UPDATED LIEN REPORTED

DATE:	07/06/2017
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	LIVERMORE, CA
DETAILS:	REGISTRATION ISSUED OR RENEWED

DATE:	12/06/2023
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	CALIFORNIA
ODOMETER:	165,441 MILES
DETAILS:	PASSED EMISSION INSPECTION

DATE:	11/08/2024
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	LIVERMORE, CA
DETAILS:	TITLE ISSUED OR UPDATED LIEN REPORTED, REGISTRATION ISSUED OR RENEWED

DATE:	02/23/2025
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	CALIFORNIA
ODOMETER:	175,354 MILES
DETAILS:	ODOMETER READING FROM MOTOR VEHICLE DEPARTMENT

DATE:	05/21/2025
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	CALIFORNIA
ODOMETER:	181,573 MILES
DETAILS:	PASSED EMISSION INSPECTION

DATE:	06/24/2025
SOURCE:	MOTOR VEHICLE DEPARTMENT
LOCATION:	MARYSVILLE, CA
DETAILS:	TITLE ISSUED OR UPDATED, REGISTRATION ISSUED OR RENEWED

HISTORICAL SALES LISTINGS

NO HISTORICAL SALES LISTINGS FOUND

SERVICE HISTORY RECORDS

DATE:	07/30/2024
LOCATION:	CALIFORNIA
ODOMETER:	174,153 MILES
DETAILS:	VEHICLE INSPECTED, VEHICLE RECALL SERVICE PERFORMED, TIRES OR WHEELS SERVICE PERFORMED

VEHICLE SPECIFICATIONS

MAKE:	JEEP
MANUFACTURER NAME:	FCA US LLC
MODEL:	CHEROKEE
MODEL YEAR:	2016
PLANT CITY:	TOLEDO
SERIES:	KL
TRIM:	LIMITED
VEHICLE TYPE:	MULTIPURPOSE PASSENGER VEHICLE (MPV)
PLANT COUNTRY:	UNITED STATES (USA)
PLANT COMPANY NAME:	TOLEDO NORTH ASSEMBLY
PLANT STATE:	OHIO
BODY CLASS:	SPORT UTILITY VEHICLE (SUV)/MULTI-PURPOSE VEHICLE (MPV)
DOORS:	4
GROSS VEHICLE WEIGHT RATING FROM:	CLASS 1D: 5,001 - 6,000 LB (2,268 - 2,722 KG)
STEERING LOCATION:	LEFT-HAND DRIVE (LHD)
DRIVE TYPE:	4X2
BRAKE SYSTEM TYPE:	HYDRAULIC
ENGINE NUMBER OF CYLINDERS:	4
DISPLACEMENT (CC):	2400.0
DISPLACEMENT (CI):	146.45698582735
DISPLACEMENT (L):	2.4
FUEL TYPE - PRIMARY:	GASOLINE
OTHER ENGINE INFO:	SALES CODE : ED3,ED7,EDD,EDE,ED6,ED8
TURBO:	NO
SEAT BELT TYPE:	MANUAL
OTHER RESTRAINT SYSTEM INFO:	ACTIVE SEAT BELT
FRONT AIR BAG LOCATIONS:	1ST ROW (DRIVER AND PASSENGER)
SIDE AIR BAG LOCATIONS:	ALL ROWS
TIRE PRESSURE MONITORING SYSTEM (TPMS) TYPE:	DIRECT

NCSA BODY TYPE:	COMPACT UTILITY (UTILITY VEHICLE CATEGORIES "SMALL" AND "MIDSIZE")
NCSA MAKE:	JEEP / KAISER JEEP / WILLEYS JEEP
NCSA MODEL:	CHEROKEE (1984-ON) (FOR GRAND CHEROKEE FOR 2014 ON USE 02-422.)

NHTSA CRASH TEST RATINGS

2016 JEEP CHEROKEE SUV 2WD

OVERALL:	4 STARS
OVERALL FRONT:	4 STARS
FRONT DRIVER SIDE:	4 STARS
FRONT PASSENGER SIDE:	4 STARS
OVERALL SIDE:	5 STARS
SIDE DRIVER SIDE:	5 STARS
SIDE PASSENGER SIDE:	5 STARS
FRONT SIDE BARRIER AND POLE RATING:	5 STARS
REAR SIDE BARRIER AND POLE RATING:	5 STARS
SIDE BARRIER RATING:	5 STARS
ROLLOVER RATING:	4 STARS
ROLLOVER POSSIBILITY:	0.174
DYNAMIC TIP RESULT:	NO TIP
SIDE POLE CRASH RATING:	5 STARS
ELECTRONIC STABILITY CONTROL:	STANDARD
FORWARD COLLISION WARNING:	OPTIONAL
LANE DEPARTURE WARNING:	OPTIONAL

2016 JEEP CHEROKEE SUV 4WD

OVERALL:	4 STARS
OVERALL FRONT:	4 STARS
FRONT DRIVER SIDE:	4 STARS

FRONT PASSENGER SIDE:	4 STARS
OVERALL SIDE:	5 STARS
SIDE DRIVER SIDE:	5 STARS
SIDE PASSENGER SIDE:	5 STARS
FRONT SIDE BARRIER AND POLE RATING:	5 STARS
REAR SIDE BARRIER AND POLE RATING:	5 STARS
SIDE BARRIER RATING:	5 STARS
ROLLOVER RATING:	4 STARS
ROLLOVER POSSIBILITY:	0.169
DYNAMIC TIP RESULT:	NO TIP
SIDE POLE CRASH RATING:	5 STARS
ELECTRONIC STABILITY CONTROL:	STANDARD
FORWARD COLLISION WARNING:	OPTIONAL
LANE DEPARTURE WARNING:	OPTIONAL

RECALLS

ELECTRICAL SYSTEM:WIRING

REPORT RECEIPT DATE: 17/05/2018

NHTSA CAMPAIGN: 18V332000

SUMMARY:

CHRYSLER (FCA US LLC) IS RECALLING CERTAIN 2014-2018 DODGE JOURNEY, CHARGER AND DURANGO, RAM 2500, 3500, 3500 CAB CHASSIS (MORE THAN 10,000LB), 4500 CAB CHASSIS AND 5500 CAB CHASSIS, JEEP CHEROKEE AND GRAND CHEROKEE AND CHRYSLER 300, 2014-2019 RAM 1500, 2015-2018 DODGE CHALLENGER, 2015-2017 CHRYSLER 200, 2016-2018 RAM 3500 CAB CHASSIS (LESS THAN 10,000 LB), 2017-2018 CHRYSLER PACIFICA AND 2018 JEEP WRANGLER VEHICLES. THESE VEHICLES ARE BEING RECALLED TO ADDRESS A DEFECT THAT COULD PREVENT THE CRUISE CONTROL SYSTEM FROM DISENGAGING. IF, WHEN USING CRUISE CONTROL, THERE IS A SHORT CIRCUIT WITHIN THE VEHICLE'S WIRING, THE DRIVER MAY NOT BE ABLE TO SHUT OFF THE CRUISE CONTROL EITHER BY DEPRESSING THE BRAKE PEDAL OR MANUALLY TURNING THE SYSTEM OFF ONCE IT HAS BEEN ENGAGED, RESULTING IN EITHER THE VEHICLE MAINTAINING ITS CURRENT SPEED OR POSSIBLY ACCELERATING.

CONSEQUENCE:

IF THE VEHICLE MAINTAINS ITS SPEED OR ACCELERATES DESPITE ATTEMPTS TO DEACTIVATE THE CRUISE CONTROL, THERE WOULD BE AN INCREASED RISK OF A CRASH.

REMEDY:

CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE SOFTWARE, AND PERFORM A SOFTWARE FLASH ON THE ENGINE OR POWERTRAIN CONTROL MODULE, FREE OF CHARGE. THE RECALL BEGAN JUNE 4, 2018. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. NOTE: OWNERS ARE ADVISED TO STOP USING CRUISE CONTROL UNTIL THE SOFTWARE UPDATE HAS BEEN PERFORMED. IN THE EVENT THAT CRUISE CONTROL CANNOT BE DISENGAGED WHILE DRIVING, OWNERS SHOULD FIRMLY AND STEADILY APPLY THE BRAKES AND SHIFT THE TRANSMISSION TO NEUTRAL, PLACING THE VEHICLE IN PARK ONCE IT HAS STOPPED.

ELECTRICAL SYSTEM:WIRING: REAR COMPARTMENT/TRUNK

REPORT RECEIPT DATE: 09/12/2015

NHTSA CAMPAIGN: 15V826000

SUMMARY:

CHRYSLER (FCA US LLC) IS RECALLING CERTAIN MODEL YEAR 2015-2016 JEEP CHEROKEE VEHICLES MANUFACTURED FEBRUARY 18, 2015, TO SEPTEMBER 10, 2015 AND EQUIPPED WITH THE POWER LIFTGATE OPTION. IN THE AFFECTED VEHICLES, WATER MAY LEAK INTO THE POWER LIFTGATE CONTROL MODULE AND RESULT IN A HIGH RESISTANCE SHORT CIRCUIT.

CONSEQUENCE:

A SHORT CIRCUIT IN THE MODULE INCREASES THE RISK OF A FIRE.

REMEDY:

CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE MODULE AND CONNECTORS FOR CORROSION, REPLACING THE DAMAGED COMPONENTS AS NECESSARY. THE MASTIC SHIELD WILL BE REMOVED AND THE MODULE WILL BE COVERED WITH A WATER SHIELD. THESE REPAIRS WILL BE PERFORMED FREE OF CHARGE. THE RECALL BEGAN ON FEBRUARY 1, 2016. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S NUMBER FOR THIS RECALL IS R67. THIS RECALL IS SUPERSEDED BY NHTSA RECALL 23V-338.

EQUIPMENT

REPORT RECEIPT DATE: 21/12/2017

NHTSA CAMPAIGN: 17V824000

SUMMARY:

CHRYSLER (FCA US LLC) IS RECALLING VARIOUS DODGE, CHRYSLER, AND RAM VEHICLES EQUIPPED WITH KIDDE PLASTIC-HANDLE OR PUSH BUTTON 'PINDICATOR' FIRE EXTINGUISHERS. A LIST OF THE AFFECTED TRAILER MODELS IS AVAILABLE AT: [HTTPS://STATIC.NHTSA.GOV/ODI/RCL/2017/RMISC-17V824-0103.PDF](https://static.nhtsa.gov/odi/rcl/2017/rmisc-17v824-0103.pdf). THESE EXTINGUISHERS MAY BECOME CLOGGED, PREVENTING THE EXTINGUISHER FROM DISCHARGING AS EXPECTED OR REQUIRING EXCESSIVE FORCE TO ACTIVATE THE EXTINGUISHER. ADDITIONALLY, IN CERTAIN MODELS, THE NOZZLE MAY DETACH FROM THE VALVE ASSEMBLY WITH ENOUGH FORCE THAT IT COULD CAUSE INJURY AND ALSO RENDER THE PRODUCT INOPERABLE. FOR A FULL LIST OF THE AFFECTED FIRE EXTINGUISHER MODELS VISIT: [HTTPS://STATIC.NHTSA.GOV/ODI/RCL/2017/RMISC-17E062-5427.PDF](https://static.nhtsa.gov/odi/rcl/2017/rmisc-17e062-5427.pdf)

CONSEQUENCE:

IF THE FIRE EXTINGUISHER DOES NOT FUNCTION PROPERLY, IT CAN INCREASE THE

RISK OF INJURY IN THE EVENT OF A FIRE.

REMEDY:

CHRYSLER WILL NOTIFY OWNERS INSTRUCTING THEM TO CONTACT KIDDE FOR A REPLACEMENT FIRE EXTINGUISHER, FREE OF CHARGE. THE RECALL BEGAN FEBRUARY 14, 2018. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403 OR KIDDE CUSTOMER SERVICE SERVICE TOLL-FREE AT 1-855-262-3540, OR ONLINE AT WWW.KIDDE.COM AND CLICK ON "PRODUCT SAFETY RECALL" FOR MORE INFORMATION. CHRYSLER'S NUMBER FOR THIS RECALL IS T82.

SEATS

REPORT RECEIPT DATE: 10/08/2016

NHTSA CAMPAIGN: 16V590000

SUMMARY:

CHRYSLER (FCA US LLC) IS RECALLING CERTAIN MODEL YEAR 2014-2016 JEEP CHEROKEE VEHICLES MANUFACTURED JULY 29, 2013, TO FEBRUARY 5, 2016. THE SEAT FASTENERS ON THE FIRST OR SECOND ROW SEATS MAY NOT HAVE BEEN TIGHTENED TO THE PROPER TORQUE SPECIFICATION.

CONSEQUENCE:

LOOSE FASTENERS MAY ALLOW THE SEATS TO MOVE, INCREASING THE RISK OF INJURY TO THE SEAT OCCUPANTS IN THE EVENT OF A CRASH.

REMEDY:

CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE SEATS OR SEAT SETS, FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING SEPTEMBER 2016. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S NUMBER FOR THIS RECALL S63.

POWER TRAIN:AXLE ASSEMBLY:AXLE SHAFT

REPORT RECEIPT DATE: 11/05/2016

NHTSA CAMPAIGN: 16V287000

SUMMARY:

CHRYSLER GROUP LLC (CHRYSLER) IS RECALLING CERTAIN MODEL YEAR 2016 JEEP CHEROKEE VEHICLES MANUFACTURED SEPTEMBER 30, 2015, TO OCTOBER 2, 2015.

THE LEFT HALFSHAFT MAY HAVE BEEN INCORRECTLY MANUFACTURED CAUSING IT TO FRACTURE WITHOUT WARNING.

CONSEQUENCE:

A FRACTURED HALFSHAFT MAY DISCONNECT FROM THE DRIVE AXLE, INCREASING THE RISK OF A CRASH.

REMEDY:

CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE LEFT HALFSHAFT, FREE OF CHARGE. THE RECALL BEGAN ON JUNE 30, 2016. OWNERS MAY CONTACT CHRYSLER'S CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S RECALL NUMBER IS S38.

POWER TRAIN:AXLE ASSEMBLY:AXLE SHAFT

REPORT RECEIPT DATE: 11/05/2016

NHTSA CAMPAIGN: 16V284000

SUMMARY:

CHRYSLER GROUP LLC (CHRYSLER) IS RECALLING CERTAIN MODEL YEAR 2016 JEEP CHEROKEE VEHICLES MANUFACTURED OCTOBER 3, 2015, TO MARCH 22, 2016. THE RIGHT HALFSHAFT MAY HAVE BEEN INCORRECTLY MANUFACTURED CAUSING IT TO FRACTURE WITHOUT WARNING.

CONSEQUENCE:

A FRACTURED HALFSHAFT MAY DISCONNECT FROM THE DRIVE AXLE, INCREASING THE RISK OF A CRASH.

REMEDY:

CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE RIGHT HALFSHAFT, FREE OF CHARGE. THE RECALL BEGAN ON JUNE 30, 2016. OWNERS MAY CONTACT CHRYSLER'S CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S RECALL NUMBER IS S39.

POWER TRAIN:DRIVELINE:DIFFERENTIAL UNIT

REPORT RECEIPT DATE: 11/06/2020

NHTSA CAMPAIGN: 20V343000

SUMMARY:

CHRYSLER (FCA US LLC) IS RECALLING CERTAIN 2014-2017 JEEP CHEROKEE VEHICLES EQUIPPED WITH A TWO-SPEED POWER TRANSFER UNIT (PTU). RELATIVE MOVEMENT IN THE POWER TRANSFER UNIT (PTU) BETWEEN THE DIFFERENTIAL INPUT SPLINES AND THE TRANSMISSION OUTPUT SHAFT MAY CAUSE SOME INPUT SPLINE TEETH TO WEAR OFF, WHICH MAY EVENTUALLY CAUSE A LOSS OF ENGAGEMENT BETWEEN THE TRANSMISSION AND THE DIFFERENTIAL INSIDE THE PTU. IF THIS OCCURS, POWER CANNOT BE TRANSFERRED BETWEEN THE FRONT WHEELS AND THE TRANSMISSION WHICH RESULTS IN A LOSS OF DRIVE WHILE THE VEHICLE IS IN MOTION AND A LOSS OF THE PARK FUNCTION WHILE STATIONARY.

CONSEQUENCE:

A LOSS OF DRIVE CAN CAUSE A VEHICLE CRASH WITHOUT PRIOR WARNING. A LOSS OF THE PARK FUNCTION CAN CAUSE UNINTENDED VEHICLE ROLLAWAY WHICH CAN INCREASE THE RISK OF A CRASH OR INJURY.

REMEDY:

FCA US LLC WILL NOTIFY OWNERS, AND DEALERS WILL PERFORM A SOFTWARE UPDATE THAT WILL MAINTAIN VEHICLE PROPULSION BY ENGAGING REAR WHEEL DRIVE AND PREVENT ROLLING IN PARK BY ACTIVATING THE ELECTRONIC PARKING BRAKE IF A FAILED INPUT SPLINE OCCURS. THIS RECALL BEGAN JULY 14, 2020. OWNERS MAY CONTACT FCA USA LLC CUSTOMER SERVICE AT 1-800-853-1403. FCA'S NUMBER FOR THIS RECALL IS W47.

POWER TRAIN:AUTOMATIC TRANSMISSION

REPORT RECEIPT DATE: 27/04/2023

NHTSA CAMPAIGN: 23V302000

SUMMARY:

CHRYSLER (FCA US, LLC) IS RECALLING CERTAIN 2016-2017 JEEP CHEROKEE VEHICLES. THE POWER TRANSFER UNIT (PTU) MAY BECOME DAMAGED AND DISENGAGE THE TRANSMISSION AND DIFFERENTIAL, RESULTING IN A LOSS OF DRIVE POWER OR LOSS OF PARK FUNCTION.

CONSEQUENCE:

A LOSS OF DRIVE POWER CAN INCREASE THE RISK OF A CRASH. A LOSS OF PARK FUNCTION CAN CAUSE AN UNINTENDED VEHICLE ROLLAWAY WHICH CAN INCREASE THE RISK OF A CRASH OR INJURY.

REMEDY:

FCA US LLC WILL NOTIFY OWNERS, AND DEALERS WILL PERFORM A SOFTWARE UPDATE, FREE OF CHARGE. OWNER NOTIFICATION LETTERS WERE MAILED MAY 11, 2023. OWNERS MAY CONTACT FCA USA LLC CUSTOMER SERVICE AT 1-800-853-1403. FCA'S NUMBER FOR THIS RECALL IS 45A. THIS RECALL EXPANDS PREVIOUS RECALL NUMBER 20V-343.

ELECTRICAL SYSTEM:WIRING: REAR COMPARTMENT/TRUNK

REPORT RECEIPT DATE: 11/05/2023

NHTSA CAMPAIGN: 23V338000

SUMMARY:

CHRYSLER (FCA US, LLC) IS RECALLING CERTAIN 2014-2016 JEEP CHEROKEE VEHICLES EQUIPPED WITH A POWER LIFTGATE. AN ELECTRICAL SHORT IN THE POWER LIFTGATE MODULE MAY LEAD TO A VEHICLE FIRE WITH THE IGNITION ON OR OFF.

CONSEQUENCE:

A FIRE WHILE PARKED OR DRIVING CAN INCREASE THE RISK OF INJURY.

REMEDY:

OWNERS ARE ADVISED TO PARK OUTSIDE AND AWAY FROM STRUCTURES UNTIL THE RECALL REPAIR IS COMPLETE. DEALERS WILL RELOCATE THE POWER LIFTGATE MODULE AND ADD A WATER SHIELD. IN ADDITION, DEALERS WILL INSPECT FOR CORROSION AND REPLACE THE MODULE AND ELECTRICAL CONNECTORS, IF NECESSARY. REPAIRS WILL BE PERFORMED FREE OF CHARGE. OWNER LETTERS WERE MAILED MARCH 1, 2024. OWNERS MAY CONTACT FCA US, LLC CUSTOMER SERVICE AT 1-800-853-1403. FCA US, LLC'S NUMBER FOR THIS RECALL IS 49A. THIS RECALL SUPERSEDES RECALLS 15V-393 AND 15V-826. VEHICLES REPAIRED UNDER THE PRIOR RECALLS WILL STILL NEED TO HAVE THE NEW REMEDY PERFORMED.

WE DO NOT PROVIDE CONSUMER REPORTS AND ARE NOT A CONSUMER REPORTING OR GOVERNMENT AGENCY. YOU MAY NOT USE OUR SERVICE OR THE INFORMATION IT PROVIDES TO MAKE DECISIONS ABOUT CONSUMER CREDIT, EMPLOYMENT, INSURANCE, TENANT SCREENING, OR ANY OTHER PURPOSE THAT WOULD REQUIRE FCRA COMPLIANCE.

END OF REPORT
