

Shop Drawings

The purpose of these instructions is to help the Engineers understand how certain features are correctly used in shop drawings and why it is important to Walteks workflow process.



IMPORTANT! "FIELDEVAL" System variable should = 31

This will tell all fields to update on Regen/Plot/ or Save. It is recommended that you setup the System Variable monitor (SYSVARMONITOR) to include this setting. If you notice fields are not updating after Regen or Save then this setting is the most likely cause.

AREA LEFT BLANK INTENTIONALLY FOR FUTURE NOTES



Fab Drawings


The purpose of these instructions is to help the Engineers understand how certain features are correctly used in fab drawings and why it is important to Walteks workflow process.


In the following pages you will find CAD screen views of some standard fabs with Comments on important features that are used. If you are unfamiliar with fields please reference the below link for instructions on their use and capabilities.

IMPORTANT! "FIELDEVAL" System variable should = 31

This will tell all fields to update on Regen/Plot/ or Save. It is recommended that you setup the System Variable monitor (SYSVARMONITOR) to include this setting. If you notice fields are not updating after Regen or Save then this setting is the most likely cause.

AREA LEFT BLANK INTENTIONALLY FOR FUTURE NOTES





AREA LEFT BLANK INTENTIONALLY FOR FUTURE NOTES

