Lab 14 — Dimensions, Multileaders and Part-List Tables

WSQ Technical Drawing with AutoCAD (TGS-2021005538) · Topic 05: Design Documentation

Tertiary Infotech Academy Pte Ltd · UEN: 201200696W · Version v12 · 18 August 2026

Objective

LO3/LO4 — dimension drawings and produce part lists (A5, K5)

Goal

Fully dimension practice drawing EX-8 with a metric dimension style — linear, aligned, radial, diameter, angular, continue and baseline — add multileader callouts, and create the part-list table from the Lab 11 balloon attributes.

You'll produce

A fully dimensioned EX-8 sheet with leader notes and a parts table (part no · description · qty).

Commands / tools: DIMSTYLE, DIM, DIMLINEAR/ALIGNED/RADIUS/DIAMETER/ANGULAR, DIMCONTINUE, DIMBASELINE, MLEADER, TABLE, DATAEXTRACTION

Files in this lab

- ex8.dwg
- ex8-drawing-sheet.pdf
- ex8.png

Step-by-step

1. Open ex8.dwg and create dimension style MECH-25 (ISO, 2.5mm text, closed-filled arrows)

   ```
   D (DIMSTYLE) → New → fit/text
   ```

2. Place linear and aligned dimensions on the main edges

   ```
   DLI · DAL
   ```

3. Dimension the circles and arcs with diameter, radius and angular dimensions

```
DDI · DRA · DAN
```

4. Chain related dimensions with Continue, and datum-reference them with Baseline

```
DCO · DBA
```

5. Add multileader callouts for the hole notes and edge finishes

```
MLD → arrow point → landing → note
```

6. Insert a table for the part list and populate it from the Lab 11 attribute extraction

```
TB (TABLE) · DATAEXTRACTION
```

7. Add a revision cloud around one detail to flag it for checking, then save

```
REVCLOUD → drag around detail
```

Check your work

Every dimension on the EX-8 sheet is reproduced with the MECH-25 style (no overridden text), leaders land neatly, and the table rows match the balloons one-for-one.

© 2026 Tertiary Infotech Academy Pte Ltd (UEN: 201200696W)