TERTIARY INFOTECH ACADEMY PTE LTD

Activity 02

Define the Process with SIPOC and PDCA

Continuous Process Improvement with FMEA · TGS-2021009031

Scenario

The team disagrees about whether stencil preparation, printing, placement or reflow belongs in scope.

Objective

Set a process boundary and convert the improvement goal into a testable PDCA plan.

Deliverable

SIPOC, five-stage SMT process map, stakeholder needs and PDCA experiment canvas

Scenario questions

1. What is deliberately out of scope?

2. Which requirement will later appear as a function in the PFMEA?

Submission checklist

✓	Check
■	Workbook complete
■	Formulas retained
■	Evidence and assumptions recorded
■	Questions answered
■	Acceptance criterion applied

Acceptance criterion: The SIPOC boundary is unambiguous and the PDCA hypothesis contains change, predicted outcome, measure and guardrail.