

Scenario - Activity 6: Root Cause with 5 Whys and Fishbone

CNC-2 generates intermittent surface marks after changeovers. The first response was to retrain operators, but the problem returned.

Questions

- 1. Where does the causal chain rely on an assumption?
- 2. Which cause category is under-investigated?
- 3. What evidence would disconfirm the leading hypothesis?
- 4. How could GenAI help without fabricating a cause?

Known facts versus assumptions

Statement	Fact / calculation / report / assumption	Evidence source	Confidence