

Scenario - Activity 8: Predictive-maintenance Decision Design

CNC-2 shows rising vibration and spindle temperature. A vendor model gives a failure-risk score but does not explain the required maintenance action.

Questions

1. What failure mode is plausible?
2. Does the trend cross an engineering limit?
3. What action follows each risk band?
4. Who may defer maintenance and on what evidence?

Known facts versus assumptions

Statement	Fact / calculation / report / assumption	Evidence source	Confidence