





Distraught
Miners

What happened last Friday?


Oh goodness, buckle up for this one...



Basically, the terrain is completely controlling our residual gravity anomaly response.... we need to get DEM data to correct for this and then we'll be fine, right?



Soooooooooooo..... We had some technical difficulties




This was the
LiDAR data
coverage...

LOLLL

RuntimeError: Some gravity stations are outside the DEM coverage or still sample NaN DEM cells:

station	longitude	latitude	easting_m	northing_m
1.0	-106.835495	40.478666	344418.058854	4.482505e+06
2.0	-106.835498	40.478675	344417.830475	4.482506e+06
3.0	-106.835500	40.478684	344417.640938	4.482507e+06
4.0	-106.835503	40.478692	344417.436458	4.482508e+06
5.0	-106.835504	40.478702	344417.349965	4.482509e+06
6.0	-106.835506	40.478711	344417.201845	4.482510e+06
7.0	-106.835508	40.478721	344417.061740	4.482511e+06
8.0	-106.835512	40.478730	344416.771637	4.482512e+06
9.0	-106.835512	40.478738	344416.758564	4.482513e+06
10.0	-106.835513	40.478747	344416.684254	4.482514e+06
11.0	-106.835516	40.478755	344416.521928	4.482515e+06
12.0	-106.835518	40.478763	344416.309345	4.482515e+06
12.5	-106.835519	40.478771	344416.271703	4.482516e+06
13.0	-106.835520	40.478772	344416.187697	4.482516e+06
13.5	-106.835520	40.478780	344416.184325	4.482517e+06
14.0	-106.835523	40.478780	344415.958190	4.482517e+06
14.5	-106.835524	40.478782	344415.842008	4.482518e+06
15.0	-106.835524	40.478791	344415.856520	4.482519e+06
15.0	-106.835524	40.478791	344415.856520	4.482519e+06
15.5	-106.835526	40.478796	344415.690919	4.482519e+06
16.0	-106.835526	40.478801	344415.746137	4.482520e+06
17.0	-106.835528	40.478808	344415.582913	4.482520e+06
18.0	-106.835532	40.478815	344415.283266	4.482521e+06
19.0	-106.835531	40.478826	344415.365788	4.482522e+06
20.0	-106.835532	40.478835	344415.284104	4.482524e+06
21.0	-106.835539	40.478844	344414.771518	4.482525e+06
22.0	-106.835538	40.478853	344414.858646	4.482525e+06
23.0	-106.835542	40.478863	344414.519346	4.482527e+06
24.0	-106.835542	40.478868	344414.514656	4.482527e+06
25.0	-106.835543	40.478878	344414.478984	4.482528e+06
26.0	-106.835546	40.478888	344414.231619	4.482529e+06
27.0	-106.835548	40.478896	344414.126164	4.482530e+06
28.0	-106.835549	40.478904	344414.029356	4.482531e+06
29.0	-106.835552	40.478911	344413.824488	4.482532e+06

But then..





And then the best thing happened!

.. I just didn't grab the right tiles and as I just figured out... there was a bug in the plotting code


Matt found the actual data we needed! just send me coordinate region you need (lon lat is fine) and the data shall be yours.

Then we could do gravity corrections, so everything should be fine!





SIKE

Advanced terrain corrections using DEM data didn't change much.... WHY?




But wait we have GPR!!!!



SIKEEEEEEEEE

Our desired depth of investigation to even possibly get reflections from the ceiling of the mine shaft would be 80-200 ns and we only have data to 100 ns... (after that is noise or silty/clayey minerals ate up our signals) :(((



To Dos

- Interpret methods together with corrections
- Go back to Joe to interpret gravity anomalies better with new corrections applied
- Meeting with Jeff to discuss gpr data viability in new context
- Finalize abstract (we worked on it before morning meeting today)
- Can we still be the miners?!

