

## v.2 changelog

- BATTERY Tabs swapped (polarity, same position)
- SMT Components Moved, won't affect mechanical
- D1 package changed (was SMB, is SMA)

v.3 changelog (see schematic for signal changes)

- Added mounting hole
- Added fuse, moved SMT components to fit
- Adjustments for JLC DRU, pad override was 40%, reduced to 25%
- Silk cleanup
- Changed Battery Tab package to round pads (was square)

## v.4

- Board is 2mm wider on right side
- DC power out is now BNC