Simplification (Minimization) of Logical Functions

A logic function has many algebraic expressions (see canonical forms and simplified expressions).

The purpose of simplification is to choose the most appropriate expression (with the minimum cost) from the set of all possible expressions according to a cost criterion.

The cost criterion may change and depend on the application.

For example, the design criteria may require the expression to have a minimum number of products (or sums), a minimum number of variables in each product, using only one type of gate (such as NAND), using the gates that are at our disposal.

Objectives of simplification:

- · Decreasing the size of the circuit
- Decreasing power consumption (battery, cooling problem)
- Decreasing the delay (increasing the speed) (See 3.21: Propagation Delay)
- · Decreasing the cost

http://akademi.itu.edu.tr/en/buzluca/



2011-2019 Feza BUZLUCA

4 1

Digital Circuits

Simplification Related Definitions: Prime Implicant

Implicant of a function F is a product P that is covered by this function $P \le F$ (2.9). Reminder: Each minterm (product) of 1st canonical form corresponds to a single 1-generating ("true") point. The minterms are implicants of the function ($m \le F$).

Example:

Α	В	С	F
0	0	0	0
0	0	1	1
0	1	0	0
0	1	1	1
1	0	0	0
1	0	1	1
1	1	0	1
1	1	1	1

$$F(A, B, C) = \Sigma m(1,3,5,6,7)$$
: 1st canonical form
= A'B'C + A'BC + ABC' + ABC'

These products can be simplified into products that have fewer variables, which still cover together all the 1s of the function.

This function was simplified previously (slide 2.33):

While the minterms in the canonical form cover only a single 1, the AB product covers two 1s and C covers four 1s.

Note that, products with fewer variables cover more 1s.

Prime implicant:

Implicants that cannot be simplified any further (i.e., cannot be combined with another term to eliminate a variable) are called prime implicants.

For example, products AB and C are prime implicants of this function but minterms are not.

http://akademi.itu.edu.tr/en/buzluca/

http://www.buzluca.info

Prime Implicant (cont'd)

A prime implicant is a product that cannot be simplified.

A **prime implicant** of F is an implicant that is minimal - that is, the removal of any literal from P results in a non-implicant for F (*Willard Van Orman Quine*).

Example (cont'd):

 $F(A, B, C) = \Sigma m(1,3,5,6,7) : 1st canonical form$ = A'B'C + A'BC + AB'C + ABC' + ABC' = AB + C

- For the given function above, the minterms are not prime implicants.
 For example, ABC' and ABC are NOT prime implicants, because they can be combined together to form AB, which includes fewer literals and covers more 1s.
 If we remove C from ABC the new product AB is still an implicant of F (AB ≤ F).
- AB is a prime implicant because it cannot be simplified as A and B because the function does not have 1s in all the places A and B would require $(A \le F, B \le F)$.
- If we remove A or B from AB the new expression (A or B) is not an implicant of F.

Simplification process of a Boolean function:

- 1. Finding the complete set of all prime implicants.
- 2. Selection of the "most appropriate" subset of the prime implicants that covers all the 1s of the function.

http://akademi.itu.edu.tr/en/buzluca/

2011-2019 Feza BUZLUCA

43

Digital Circuits

Finding Prime Implicants:

Using Boolean algebra, we can combine minterms to obtain products that have fewer variables and cover more 1s.

It is hard to perform these simplifications manually, especially for complicated function (with many variables). Therefore, a computer program can be used.

A practical procedure (without using the logical expression of the function):


- Investigate the 1s (output = 1) in the truth table,
- Combine 1- generating input combinations with one or more constant variables (Hamming distance = 1).
- Retain the constant variables and remove the rest (variables with changing values).

Example:

Algebraic combining:

F = A'B' + AB' = (A' + A)B' = B'

These input combinations are adjacent. Hamming distance =1



B is constant. For both lines B=0. Hence, B will be retained in the new product.


The value of A is changing.
Hence, it will be removed from the new product.


Since B=0, the new product will be B'.


http://akademi.itu.edu.tr/en/buzluca/


Translated by Dr. Mustafa KAMAŞAK

2011-2019 Feza BUZLUCA










Example: Find the prime implicants of the following function.

 $F(A,B,C,D) = \Sigma_1(0,2,5,8,9,10,11,12,13,14,15)$



Prime implicants: A, B'D', BC'D

Method for finding prime implicants (grouping 1s):

- The groups must be rectangular and must have an area that is a power of two (i.e. 1, 2, 4, 8...).
- •"True" points (1s) are placed into the largest groups possible.
- Two points within a larger group (or groups) cannot be combined into a smaller subgroup.

For example, 2 points within different groups of 4 points cannot be combined to form another 2-point group. It is possible to form a new 4-point group.

 However, if one of the points is not contained by any groups (such as 0101 above), that point can be grouped using another point which is already in another group.

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info



Digital Circuits

The Set of All Prime Implicants and The Sufficient Base:

In logic circuit design, the simplification process starts with finding the set of all prime implicants.

In the second step of the simplification, most appropriate prime implicants are selected from the set of all prime implicants.


The minimum set of prime implicants that covers all true points (1s) of a function is called sufficient base (sufficient covering sum or minimal covering sum).

If any of the prime implicants in the sufficient base is removed, some of the true points of the function will not be covered.

Therefore, simplification of a function is the selection of the most appropriate (with minimum cost) sufficient base (minimal covering sum).

For example: Find the set of all prime implicants of the function.

Prime implicants:




BC', A'B, A'C, AB', B'C, AC'

http://akademi.itu.edu.tr/en/buzluca/



2011-2019 Feza BUZLUCA



$$F(A,B,C)=A'B+B'C+AC'$$

$$F(A,B,C) = A'B + BC' + B'C + AB'$$

$$F(A,B,C)=BC'+A'C+AB'$$

- 1. The minimal covering sum covers all 1s.
- 2. If any of the prime implicants is removed from the minimal covering sum, some of the 1s will not be covered.

$$F(A,B,C) = BC' + A'C + B'C + AC'$$

Distinguished Points and Essential Prime Implicants:


Some true points (1s) of a function may be covered only by a single prime implicant. These 1s are called distinguished points.

The prime implicant that covers a distinguished point is called an essential prime implicant.

Essential prime implicants must be included in the minimal covering sum. Otherwise, it is not possible to cover all true points of a function.

Example:

Set of all prime implicants:



С

				,A'CD'	
רוים ו	RC'	ΔC'	RD'	A'C:D'	AR'D
UD	, 50	, , , , ,	, 00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, , , , , ,

Distinguished points Essential prime implicants C'D A'CD' AC' BD' AB'D

Here, essential prime implicants cover all true points of the function. This is a specific case.

F = C'D + A'CD' + AC' + BD' + AB'D


http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info

Translated by Dr. Mustafa KAMAŞAK

2011-2019 Feza BUZLUCA

License: https://creativecommons.org/licenses/by-nc-nd/4.0/

Example: Finding the set of all prime implicants, distinguished points and essential prime implicants.



Set of all prime implicants:

CD , AB , A'C , BC , A'D' , BD'

Distinguished points

Essential prime implicants

0000 1101 1011

AB CD

http://akademi.itu.edu.tr/en/buzluca/

Translated by Dr. Mustafa KAMAŞAK

2011-2019 Feza BUZLUCA

4.13

Digital Circuits



Simplification: Selection of the Most Appropriate Prime Implicants

Reminder: Simplification process has two steps:


- 1. Finding the set of all prime implicants
- 2. Selection of a subset of prime implicants with minimum cost that covers the function (minimal covering sum).


Prime implicant charts are used to select the sufficient base with the minimum cost.

Prime Implicant Chart:

- Simple symbols are assigned to each prime implicant such as A, B, C, ...
- Using the given cost criteria, the cost of each prime implicant is calculated.
 Prime implicant chart is similar to a matrix:
- The symbols of prime implicants are placed to the rows of the chart.
- Number corresponding to the true points of the function are placed to the columns of the chart.
- The costs of the particular prime implicants are placed in the last column.
- If a prime implicant covers a true point their intersection is marked with an 'X'.

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info





Simplification of Prime Implicant Chart:

- 1. Distinguished points are determined. If there is a single X in a column, that is a distinguished point.
 - The prime implicant that covers the distinguished point (essential prime implicant) is necessarily selected.
 - The row of this essential prime implicant and columns that are covered by this implicant are removed from the chart.
- 2. If there is an X in the ith row for each X in the jth row, then row i covers row j. In other words, all points covered by row j are also covered by row i.



- If row i covers row j AND the cost at row i is smaller or equal to the cost at row j, then row j (covered row) is removed from the chart.
- 3. If a column covers another column, the covering column (with more X) is removed from the chart.



These rules are applied successively until all true points are covered with the least

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info



2011-2019 Feza BUZLUCA

Digital Circuits

Example: Simplification of prime implicant chart of the following function $f(x_1, x_2, x_3, x_4) = \Sigma m(2, 4, 6, 8, 9, 10, 12, 13, 15)$

True points of the function

				•											
		2	4	6	8	3	Ç		10	12	1	3	15	5	Cost
1 x x L	Λ				,	,		/				,			_
√ x ₁ x ₃ '-	А				Χ		Z	J		X	1	Υ.			n
X ₂ X ₃ ' X ₄ ' X ₁ 'X ₂ X ₄ '	В		X							X					8
X ₁ 'X ₂ X ₄ '	С		X	X											8
$\sqrt{x_1 x_2 x_4}$	D										_	7	7	7	6
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D										4	-		Đ	0
x ₁ 'x ₃ x ₄ '	Е	X		X											8
x ₁ 'x ₃ x ₄ ' x ₂ ' x ₃ x ₄ '	F	X							X						8
x ₁ x ₂ ' x ₄ '	G				2	X			X						8

1. step: In this chart 9 and 15 are the distinguished points.

As A and D are essential prime implicants, their rows and the columns that they cover are removed from the chart.

These products are marked to show their inclusion into the final set.

	2	4	6	10	Cost
В		Х			8
		^			0
С		Χ	Χ		8
E F	Χ		Χ		8
	Χ			Χ	8
G				v	8
- u				X	U


2. step: In this chart, C covers B. As the cost of C is equal to B, B (as the covered row) is removed from the chart.

Similarly, F covers G and they have the same cost. So the row of G is removed from the chart. These products (B and G) will not be in the final set.

		2	4	6	10	Cost
1	С		X	Χ		8
	Е	Χ		Χ		8
1	F	Χ			X	8

3. step: In this chart 4 and 10 are distinguished points. Therefore, C and F are selected (and marked). With this selection all true points of the function are covered.

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info



Digital Circuits

Result:


Marked prime implicants for the expression of the function with the least cost.

Selected prime implicants: A + D + C + F

Total cost = 5 + 6 + 8 + 8 = 27

$$f(X_1, X_2, X_3, X_4) = X_1 X_3' + X_1 X_2 X_4 + X_1' X_2 X_4' + X_2' X_3 X_4'$$

It is possible to see selected prime implicants using the Karnaugh map.



Selected prime implicants should cover all true points and there should be no redundancy.

Selected prime implicants should form a sufficient base. Therefore, removal of any implicant should result in uncovered true point(s).

 $X_1 X_3'$

 $x_1'x_2 x_4'$ $X_1 X_2 X_4$ $x_{2}' x_{3} x_{4}'$

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info


2011-2019 Feza BUZLUCA

Simplification of Incomplete Functions

Reminder: In incomplete functions, for some input combinations the function result is undetermined (we do not care about it).

These combinations may never appear in the circuit or they are prohibited by the designer.

Example: BCD incrementer circuit



For these input combinations, the output of the circuit (function) is undetermined. The symbols X or Φ are used to show the undetermined (don't care) outputs.

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info

2011-2019 Feza BUZLUCA

I1

X

 08 04 02 01

XXXX X

X

X

X

X

X

X

Digital Circuits

Selection of Undetermined (Don't Care) Values (Φ):

Undetermined (don't care) values (Φ) can be chosen to be 0 or 1 in order to utilize the least costly expression in the simplification process.

- While searching for the set of all prime implicants, undetermined values are taken as 1 in order to have (larger groups in the Karnaugh map) simpler products ($\Phi = 1$).
- While forming the prime implicant chart, undetermined values are taken as 0 because there is no need to cover these points ($\Phi = 0$).


Example: Implement the following incomplete function with the least possible

$$f(x_1, x_2, x_3, x_4) = \Sigma_m(2, 4, 8, 9, 13, 15) + \Sigma_{\Phi}(6, 10, 12)$$

Remark: it can also be written as

$$f(x_1, x_2, x_3, x_4) = \bigcup_1 (2, 4, 8, 9, 13, 15) + \bigcup_{\Phi} (6, 10, 12)$$

Cost criteria: 2 units for each variable and 1 unit for each complement.



Digital Circuits Forming the prime implicant chart: Set of all prime implicants: $x_2 x_3' x_4'$ X₁'X₂ X₄' $X_1 X_2 X_4$ $x_{2}' x_{3} x_{4}'$ $x_1 x_2' x_4'$ $X_1 X_3'$ $x_1'x_3 x_4'$ Symbols: Α В С D Ε F G Costs: 5 8 8 6 8 8 8 Points covered: 8,9,13 4 13,15 2 8 True points of the function Φ 's are assumed to be 0, 2 4 8 9 13 15 Cost when we are forming the Α X Prime implicants prime implicant chart. В X 8 С X 8 D $X \mid X$ 6 As there is no need to cover the Ε 8 X points with undetermined values, F 8 X these points are not placed into G X 8 the prime implicant chart. http://akademi.itu.edu.tr/en/buzluca/ 2011-2019 Feza BUZLUCA 4.24

http://www.buzluca.info

True points of the function



Step 1: In this chart, points 9 and 15 are distinguished points.

As A and D are the essential prime implicants, they are selected. The rows and columns covered by A and D are removed.

A and D are marked to show that they will be in the final set of prime implicants.

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info



Digital Circuits

	2	4	Cost
В		Χ	8
С		Χ	8
E	Χ		8
F	Χ		8

Step 2: B and C are covering the same points and they have the same cost. Therefore, it is not possible to make a choice between B and C. One of B and C can be selected.

Same situation exists for prime implicants E and F.

At the end, the same function can be implemented using any of the following expressions which have the same (lowest) cost.

$$f = A + D + B + E = x_1 x_3' + x_1 x_2 x_4 + x_2 x_3' x_4' + x_1' x_3 x_4'$$

$$f = A + D + B + F = x_1 x_3' + x_1 x_2 x_4 + x_2 x_3' x_4' + x_2' x_3 x_4'$$

$$f = A + D + C + E = x_1 x_3' + x_1 x_2 x_4 + x_1' x_2 x_4' + x_1' x_3 x_4'$$


 $f = A + D + C + F = x_1 x_3' + x_1 x_2 x_4 + x_1' x_2 x_4' + x_2' x_3 x_4'$

All designs have the same cost (27).

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info

Simplification of General Functions

Remark: General functions have more than one output.



During the simplification of general functions, set of prime implicants for each output is found independently, and prime implicants are selected from these sets.

An important point is to select the common prime implicants of both outputs. Simplification of general functions is not in the scope of this course.

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info

2011-2019 Feza BUZLUCA

4.27

Digital Circuits

Finding the Set of All Prime Implicants Using Tabular (Quine-McCluskey) Method

It is hard to use Karnaugh maps for the functions with too many variables as it becomes harder to visualize.

Especially for the functions with 5 or more variables, it is hard to draw and visualize the adjacency of the points.

In tabular method (Quine-McCluskey), systematic (algorithmic) operations are performed successively.

Performing these operations manually may be time consuming. However, it is possible to implement this method as a computer program.

Tabular (Quine-McCluskey) Method:

Remember, to find the set of all prime implicants, true points (minterms) of the function are merged (grouped). Adjacent minterms where a single variable changes are taken into the same group (See the figure at 4.4).

In the tabular method, minterms (corresponding to 1-generating input combinations) are compared to all other minterms.

If a single variable (input) changes between two minterms, they are merged.

The variable with the changing value is removed, and a new term is obtained.

This process is repeated until no further groups can be formed.

Terms that cannot be grouped are the prime implicants.

Willard Van Orman Quine (1908-2000), Philosophy, logic Edward J. McCluskey (1929-2016) Electric engineer.

Method (Algorithm):

1st Step: Finding the set of all prime implicants:

- Consider 1-generating input combinations (true points) in the truth table.
- Cluster the 1-generating input combinations depending on the number of 1s included in the combination. For example, 1011 has three 1s.

This will shorten the running time of the algorithm.

- · Compare combinations that are in the neighboring clusters. Merge the combinations where a single variable changes.
- Variable with changing value will be removed.
- · Mark the combinations that are grouped.
- Repeat the grouping on the newly formed combinations until no further groups can be formed.
- · Combinations that are not grouped (items that are not signed) form the set of all prime implicants.

2nd Step: Finding the minimal covering sum

The prime implicant chart is used to select the subset of prime implicants with minimum cost that covers the function (minimal covering sum) (See 4.14).

http://akademi.itu.edu.tr/en/buzluca/ http://www.buzluca.info




@ 0 0 0 2011-2019 Feza BUZLUCA

Digital Circuits

Example: Find the set of all prime implicants of the following function using Quine-McCluskey method.

 $f(x_1, x_2, x_3, x_4) = \Sigma_m(0, 1, 2, 8, 10, 11, 14, 15)$



Set of all prime implicants (Not marked):

To find the minimal covering sum (lowest cost), prime implicant chart is used.

http://akademi.itu.edu.tr/en/buzluca/

@ ⊕ ⊕ ⊜

2011-2019 Feza BUZLUCA