3935 Hwy. 20 N. . Conyers, GA 30012

Email: superseptic@gmail.com

Time Received:

Cross Street:

county: walton

770-483-7802 Fax 770-483-9864 Admin 770-884-7175

Invoice # Utility Locate #: Tech Date: 1-27-16 Truck # Tech. Quoting: Performing: Customer Name: Home Phone: Address: Work Phone: City: State: Zip: 3005 Cell Phone: Bill to: Fax#: Address Contact: City: State: Zip: Email: Payment Type: Check: Credit Card ☐ Magazine Ad ☐ Flyer ☐ Post Card How Did You Hear About Us? ☐ Referral **Job & Services Description** uncovered Crossover Reason For Inspection Blockage in inlet Tee 2 plugs, 3 plugs, or big lids Replace mainline bet. Hs & tank Install 4" PVC T, Filter, hook up Real Estate Transfer: Refinance: Chemical/Bact/Enz. Treatment Alternative or Pump System Adoption: Age of tank/field lines les Grease in Tank Other:_ Install inlet and/or outlet riser Reason for call maint. Inspection Report 3 # of bedrooms Drainfield problem No Leakages At Time of Inspection □ JOB SOURCE Depth System OK At Time of Inspection **Cost Summary Section:** Pumping Charge: **Satisfactory Completion Section:** Mainline Jetting Fee: Field Jetting Fee: I have inspected and acknowledge the satisfactory completion of the work that was performed as per the work authorization section, the job and service Digging fee (over 1ft): Riser (s) description section, the schedule of terms and conditions section, and also I have reviewed the charges as shown in the cost summary section and Additives calculated same, and they are correct. Outlet T, Filter, Hook to field Other Authorized Customer Signature: Date: