www.bowensseptictank.com 3935 Hwy. 20 N. • Conyers, GA 30012

**Cross Street:** 

Time Received:

County:

770-483-7802 Fax 770-483-9864

Admin 77	0-884-7175		Utility Loca	ite #:	egman.c	OH		Inv	voice #	44	8 1 8
Date:	1-27-16	Map: GPS	Truck #:	Tech. Quotin	g: Cha	id	Tech Performing:	Ch	ad +	Joh	Λ
Custome	r Name:	lanice	Batch	relor	Home	Phone:	770-4	f66-	6258		
Address:	545	Harold	Gower	「VY	Work	Phone:					
City:	Loganu	11190 1911	State: Ga	Zip: 3005	Cell I	Phone:					
Bill to:											
Address:	ss:						g. 25				
City:			State:	Zip:	En	nail:	ZIP 3005	2	1000	QeA.	A Stap
Payment '	Type: Che	eck:	Cre	edit Card	( )	26 8	START		<b>*</b>		
How Did	You Hear Abou	t Us?	☐ Magazine Ad	☐ Flyer ☐ Post	Card	-Other V	Repla	A V		8 2	10 4: 10 4:
Job & Services Description ESTIMATE ACTUAL											
Dumped 1000 gal									37500	3	50°°
0-6	V	F. 14-20		2 0 1 (4 (4))		G.,			219°°	E	9500
Installed Risers on outlet + inlet Ends									190000	\$3-	700°°
Installed fisers on outlet Timlet Ends									1000	-	
											2
										1	
								13"	-		
											V
* Gutters need to be resouted *											#1 (*)
* Check toulets for running *											¥
4		<u> </u>		71							
		Reason For Ir	spection	A THE	Yes	Blockage	in inlet Tee (	2 pluge, 3	plugs, or big lids	pl	495
Real Estate Transfer:				1 1	Yes	Install 4" F	PVC T, Filter, hook up	Replace ma	ainline bet. Hs & tan	N .	_
Refinance: □				-	Alternative	or Pump System	Chemical/E	Bact/Enz. Treatment	R	2COMM	
Adoption:					-	Grease in	Tank	Age of tank	/field Ines	11	115
Other:			<u>.                                    </u>	Ves	Install inle	t and/or outlet riser	Reason for	call	n	aint.	
*/			Satura	rainfield		# of bedro	oms	2	f		
No Leakages At Time of Inspection □				-	21.	2 <sup>1</sup> Depth		JOB SOURCE			
System C	OK At Time of In	spection	ay b					Cost Summary Section:			
Satisfactory Completion Section: Pumpin									g Charge:		
									line Jetting Fee:		
, , , , , , , , , , , , , , , , , , , ,								Jetting Fee: ing fee (over 1ft):			
was perfo	was performed as per the work authorization section, the job and service description section, the schedule of terms and conditions section, and also I have reviewed the charges as shown in the cost summary section and							Riser (s			
have revi								Additive			li di
calculated	dsame, and they a	are correct.					Outlet T, Filter, Hook to field				
				( <del>-</del>	Oth						
Authorize	Customer Sig					Date:	1		Oh	-	
Late: Date:   Inition							Initial	NO TOTAL	1/,-	2450	