

IM-500 — Preventive Maintenance SOP

Standard Operating Procedure | Rev 1.1

Daily Checks

Inspect hydraulic oil level (must be above MIN mark). Verify cooling water flow reads above 8 L/min. Check for oil leaks around pump and hoses. Confirm all safety gates and E-stop function.

Weekly Checks

Clean inline cooling water filter. Grease tie-bars and check clamp alignment. Inspect heater bands and thermocouple connections for E-101 prevention.

Monthly Checks

Purge and inspect injection screw for wear (relates to E-210). Replace worn ejector pins (relates to E-512). Sample hydraulic oil quality; replace ISO VG46 oil if degraded.

Escalation Rule

If the same error code appears 3 times in one shift, escalate to the Bay-3 maintenance lead immediately and take the machine offline.

Spare Parts On-Hand

Heater bands, thermocouples, ejector pins, cooling filters, ISO VG46 hydraulic oil, pump seal kit.