

Exp No: 3 STEPPER MOTOR USING AT89C51 USING PROTEUS

PROGRAM:

ORG 0000H UP:

MOV P2,

#09H ACALL DELAY MOV P2,

#0CH ACALL DELAY MOV P2,

#06H ACALL DELAY MOV P2,

#03H ACALL DELAY

SJMP UP DELAY:

MOV R4,

#18 H1:

MOV R3,

#255 H2:

DJNZ R3,

H2 DJNZ R4,

H1 RET

END

CIRCUIT DIAGRAM:

