PROCESS DESIGN QUALIFICATION					
Procedure: 4-Pr-007	Version: 39	Page: 1/14			
110000410. 411 007	Version. 33	. ago,	4-PR-007/39		

I. Purpose

This procedure provides guidelines responsibility for controlling of process design qualification for new products transferring from FJK/ Customer to FOV or internal transferring between sections in FOV, supplier changing and change control.


And, this guidance outlines the procedure of monitoring and measuring the characteristics of the product.

II. Application

- 1. This procedure is applied to all type of products have been qualified by customer or FOV design section follow to: 8-Pr-0001.
- 2. This procedure concerns to all sections in FOV.

III. Reference documents:

1. 0-QEM-001: Quality and Environmental Manual



PIC: Person In Charge

DR: Design Review

QC: Quality Control

OP: Operation Procedure

PQ: Process qualification

Man

Machine; Tool; Jig

4M are: Method (including related documents)

Material

IQ: Installation Qualification

OQ: Operation Qualification

PQ: Process Qualification


Q-Condition: Quality Conditions to assure good product's quality and safety for operators. It's including condition of 4M and E of process.

MSA: Measurement System Analysis

V. Content:

			FILIIKURA FIBER OPTICS VIETNAM LTD. PROCESS DESIGN QUALIFICATION	
Proce	dure: 4-Pr-007		Version: 39	Page: 2/14
A - Pro	ocess design qualification Flow chart	All concerned section	Description	Relative document/Record
	Demand of process	_ ^	+ New product transfering from customer apply follow this procedure.	
1	design qualification t	Customer 38	+ Transfering manufacturing production line between different factories in FJK group of company also follow this procedure.	
2	No Review Information Yes	MDP/ PRE/ QAE	+ Manufacturing division manager will asign the project belong to which PRE sections. The PRE section manager will asign project leader for this project to review Input - Product specification or purchase specification. - Bill of materials - Forecast & market - Machine & equipment list and critical spare parts (if any) - Workshop & facility requirement: space areas, environmental (temperature, Humidity, particle, ESD), gas, water, lighting - Referent production data for bench mark such as: first yield, final yield, productively, Cpk - Any needs of managever arrangement (fasts knowledge) and/ or specific training such as On job training & qualifying. - All relative quality documentation, others the requirement from Customer and production data (if any).	
			PIC review special affect to environment from operation, material, or product that out significant aspects of company. + Concerned sections asign PIC to join the project.	
3	Master plan	Project leader	+ concerned sections asign PrUs op in the project. + Project leader make Master Plan and get confirmed by his/her manager. Then the master plan shall be informed to all concerned sections. + Note: all DR meeting must be pined and consulted by at least one executive position upward. + DR-0 to share all information of project, assigned PIC of each relative sections, setup target & finalized the Master Plan (if any) Input - Share all informations as step 2 of project to concerned PIC	+ Form: 4-Pr-007-4-Fo-0003 Master Plan.
4	No DR-0	All concern sections	Review the Master Plan. Discuss & setup the target about QCD for production line. Output. Finalize master plan with target QCD, Result of confirmation with customer what kind of property and document can be disclosed with outside (supplier, subcontractor, visitor) if any. DRO meeting minutes.	+ Form: 4-Pr-007-4-Fo-0004 meeting minutes
5	No DR-1 Revise Master plan	All concern sections Project leader to revise plan (if any)	PRE-1: to review 4M preparation before Trial run Input: - Customer specification - Will or FNEA from customer if any - Other requirements - Draft CC Flow - DR-0 meeting minute - Review in DR-1 - List out requirements from specification and other requirements into customer requirement break down sheet - Review detail requirement with content of draft version of CC flow chart, Operation procedure, FNEA and PS - Confirm progress of Machine, Tue Isigout, Material preparation and Manpower arrangement Review status of action items in DR-0 - Output: - Finish checking draft version of QC flow chart, OP, FMEA, PS, Check sheet and concerning document for trial run	+ Form: 4-Pt-007-4-Fo-0005 Customer requirement break down sheet
			Finish review 4M for trial run Issue Trial run plan Besue Trial run plan Define which process need to run PQ, following Appendix A-Process qualification requirement, and is documented in QC flowchart	+ Form: 4-Pr-007-4-Fo-0002 Trial run request.
			Define which measuring process need to apply MSA, refer to Appendix E-MSA requirement.	+ Refer to MSA flow chart in S-Pr-007 Equipment control activities
			- DR-1 meeting minutes + In case the preparation can not finish on time, the team shall re-consider to postpone the DR-1 or not and revise Master Plan again if any. The project leader shall update & send latest updated Master Plan to the all concerns.	+ Form: 4-Pr-007-4-Fo-0004 meeting minutes
6	Triel run	All concern sections	+ Trial run: to evaluate effectiveness of process design, process control and training operator. Input: - Trial run plan: - Quality document: OP, CC, FMEA, PS, check sheet, template DR-1 meeting minutes - Review during Trial run - Process productivity, Process yield ratio, Process trouble - Machine, tool jig accurancy and reliability Risk from processing, inspection and packing design method - Evaluate propertor aperation and skill Note: In urgent cases, trial run period can be accepted to use temporary tool, jig approved by executive upward. Output - Confirm actual process compliance with process specification and concerning quality documents - Production data: Yield, Protectivity, defect ratio of material. - Machine, tool jip performance, data record on daily check sheet - Product data follow customer and internal requirement: correct and enough data - Training record.	+ Training record: 1-Pr-008-1-Fo-0009
7	DR-2 Yes	All concern sections	+ DR-2: to evaluate variance between the result and the larget, review Q-condition & review product compliance input: - Review the target achievement of trial run Record all requirements had been reviewed to "Customer requirement break down sheet" Production data: "Yeld, Productivity, offect ratio of material Machine, tool jay performance: data record on daily check sheet Product data follow outsomer and infearl requirement: correct and enough data Review to DR2 - Analysis data during trial run in Technical Report - Review the result of trial run compare with target setup in DR-0 step Review concerned lears implemented from Customer requirement break down sheet to confirm product compliance - Evaluate risk to setup C-condition & set counter spec (Plany) Consider the impact to cost and delevey - Review dnst CC flow chart, Operation procedure, FMEA, PS with customer requirement and actual trial run - Output - Confirm product compliance with all requirements - Update quality document (PC flow chart, Operation procedure, FMEA, PS)	+ Form: 4-Pr-007-4-Fo-0006 Technical report.
8	Customer Evaluation	Project leader	- Confirm process capacity to prepare Machine and Man for mass production - DR2 meeting minutes + Trial product will be shipped to customer for qualification if requirements Customer will qualify and feed back the result.	+ Form: 4-Pr-007-4-Fo-0004 meeting minutes
9	No DR-3	All concern sections	+ DR-3: to re-view customer evaluation (if any) and to have final conclusion to approve for mass production. Input: - Customer evaluation result - Or FOV Internal evaluation result - Or FOV Internal evaluation result - Other request in DR2 - Review in DR3 - In case the result of evaluation of New Product is failure, it should return back DR-1 for review & trial run again if any Review and quality documents (DC four chart, Operation procedure, FMEA, PS) before approval for mass production Review the request in DR2 - Review the request in DR2 Output - Official quality documents (dRicial QC flow chart, Operation procedure, FMEA, PS) results and the production Review the request in DR2 Output - Official quality documents (dRicial QC flow chart, Operation procedure, FMEA, PS) release - Section manager upwards with make final decision to approve for new mass production.	+ Update 4-Pr-007-4-Fo-0002: Trial run request.
ļ	RECORD	_	DR3 meeting minutes Project leader keep the record of design review processes.	+ Form: 4-Pr-007-4-Fo-0004 meeting minutes + Close 4-Pr-007-4-Fo-0002: Trial run request.
10	(Transfer to initial control step)	Project leader	Project leader keep the record of design review processes. The next step follows initial control procedure 4-PR-013	. Globe 947 PUDI 1947 O-UUUZ: Tilali tuti fequest.
	1	1		II.

	PROCESS DESIGN QUALIFICATION							
Procedu	ocedure: 4-Pr-007 Version: 39 Page: 3/14							
B- Proce	ess qualification (PQ)			·				
Step	Customer	Section In c Production Engineering	harge All concerned sections	Description	Relative document/Record			
		PQ demand	All concerned sections	- PRE/ QAE engineer will take responsibility to prepare detail plan for IQ-OQ-PQ	- Refer to: 4-Pr-007-4-Fo-0009 PQ implementation			
1				- Establish detailed protocols and provide criteria for performing process qualification.				
2		Protocol	development	+ The protocols can make by FOV or base on customer's requirements.	- Refer to: 4-Pr-007-4-Fo-0009 PQ implementation			
3			otocol proval Yes	- The protocol shall be approved by section manager & manufacturing department manager upwards In case customer request for PQ, the protocol will be approved by customer (for both new or modified protocol).	- Refer to: 4-Pr-007-4-Fo-0009 PQ implementation			
4		IC	2- 0Q	- Make IQ-OQ	- Refer to procedure 5-Pr-007 Equipment Control Activities			
5			PQ	- Process qualification (PQ) considerations include: (1) Process condition (2) Process criteria (3) Machine/ Jig reliability (4) Special requirement from customer (if any)				
6		Process Qu	alification report	- PRE/ QAE engineer shall summarize, analyze data and make an technical report for PQ - Process and product data should be analyzed to determine what the normal range of variation is for the process output - Confirm product sample compliance with all requirements - PRE/QAE engineer shall confirm PQ report to concerned members	- Refer to 4-Pr-007-4-Fo-0006 Technical Report			
7			ternal proval Yes	- Section Manager upwards will check and approve test result of process qualification - Manufacturing department manager upwards will check and approve process qualification - In case, customer request PQ, we will submit PQ report to customer for approval	- Refer to 4-Pr-007-4-Fo-0006 Technical Report - Refer to: 4-Pr-007-4-Fo-0009 PQ implementation			
	No Customer Approval Yes	> ← Cu	Need Stomer proval No	- In case, the result of process qualification is not good enough or customer need more data from product qualification. Section in charge will consider to make re-verification				
8		R	ecord	- Delivery the approved report to all concerned - Save for record and close.				




FUJIKURA FIBER OPTICS VIETNAM LTD PROCESS DESIGN QUALIFICATION Procedure: 4-Pr-007 Version: 39 Page: 5/14 E. TESTING PRODUCTS (Technical Service_TS) TS Flow Chart Responsible Description In charge Planning Engineer Logistic Engineer up FOV receive PO and WD or Information for testing from customer. Control of External Document: 0-PR-001 Send PO: Design Review sheet, Form: 8-Pr-0001-8-Fo-0001 (1) As for Product testing Information, the critical items must be collected by production engineer as list below Product a. Specification, including: product specification, materials specification, sensitive machine requirement, packing & test report requirement. testing b. Internal standard concerns, International standard concerns, Statutory and regulatory requirements (EHS, Law, etc.) Information c. Bill of materials and list of machine, tool, equipment. d. Process spec., process flow, and working instruction. (2) Engineer up shall hold a meeting with all concern people to make products Minute meeting report: free format Design Review sheet, Form: 8-Pr-0001-8-Fo-0001 Engineer up reviewed and break down Customer's request and feedback to Customer to make clear (if any) Review for the Product testing Information:
(1) Engineer have to review and feedback 4M and available testing equipments (testing conditions, available machine, during data or not,...). Design Review sheet, Form: 8-Pr-0001-8-Fo-0001 Engineer and concerned sections (2) Issue request for purchasing new materials (if any). Review 4M&E Purchasing procedure: 6-PR-002 Register for control items into system: (1) Register new materials code into MFG/Pro database (if any) Register for Engineer, PRD (2) Choose Work center, Cost center:, allocate into Work center, Cost cente TSA if using for testing purpose. (3) Create PS (if any), make new WI/WD (if any).

(4) Define MH for testing (Indirect, direct) and PC rate type (PRE/PRD) Note: (1,2,3): PRE (4) PRE and Concerned sections Planner will issue quotation & send to customer Product quotation calculation: 000-5-WI-0454 Planner Quotation Product samplings are assembled following customer requirements (quantities, method, material,...) Customer and Engineer investiggate together and confirm nex actions Make product Engineer Investigation Sample producta are measured & inspection base on Customer requirements: function test, performance test and reliability test for critical parameters. and take action Incase fialed, Engineer communicates to Customer for investigation Fail TESTING Engineer Pass Issue one Result Technical testing Report (if any) Engineer Issue result testing Report If test report, QAE need to issue (if any) Format of Result testing Report: free format To ensure all customer requirements was input. Minute meeting report: free format To reconfirm the results of the result testing performance and all requirements were carried our properly Technical Report: free format Fail Chief up Design Review sheet, Form: 8-Pr-0001-8-Fo-0001 Review Pass Judge NG Ship quantity product sample to customer follow inquiry (if any). Approval confirmation via email/ meeting/ else..... In case customer not require, can skip this step. Customer FJK group review Judge GOOD Ship sample Follow up shipment Engineer Close

FUJIKURA FIBER OPTICS VIETNAM LTD. PROCESS DESIGN QUALIFICATION Procedure: 4-Pr-007 Version: 39 Page: 6/14

Appendix A: Process qualification requirement

The following work flow to use in determining whether or not a process should be qualified



Each process should have a specification describing both the process parameters and the output desired

When do we need to qualify a process

- Customer's request.
- Where the results of a process cannot be verified by subsequent inspection and test.

When do we need to re-qualify a process

- Apply new equipment or significant change to process which is decided process qualification, the process should be evaludated to determine the affects and the extent of re-qualification considered.

PROCESS DESIGN QUALIFICATION

Procedure: 4-Pr-007 Version: 39 Page: 7/14

Appendix B: Define priority for periodical reliability test

Table 1. Define priority for periodical test

No	Item		Reference document		
NO		1st priority	2nd priority	Conclusion	Reference document
1	Product in test	Follow customer request	Risk assessment (FOV standard)	FOV will follow priority of periodical test yearly	4-PR-007-4-WI-0002 Guideline for periodical reliability test

Note: Secion in charge will review periodical test plan every year.

The periodical reliability test should be performed at least 1 time per 2 years.

* Set up risk assessment base on cost (sale amount & output) and quality (total defect & major defect)

Table 2. Ave Sale amount level (S)

No	Ave Sale amount (K.USD/ Month)	score
1	< 300	1
2	≥ 300 ÷ < 800	2
3	≥ 800	3

Table 3. Ave Output quantity (O)

No	Ave output/ month (set/ Month)	score
1	< 10,000	1
2	≥ 10,000 ÷ < 50,000	2
3	≥ 50,000	3

Note: SIC will take Ave monthly sale amount & output of product group in test from last fiscal year (from Apr to Mar).

We assess sale amount (S) and output (O) as paremeter for cost and convert S \times O to "C" value as below:

Table 4. Distribute & rule score for S x O to C

0 \$	1	2	3
1	1	2	3
2	2	4	6
3	3	6	9

Convert score for S x O to C

Distribute area	Score
	1
	2
	3

Table 5. Total defect ratio levels (D)

Base on total defect ratio of product

No	Total defect ratio (ppm)	score
1	< 10,000	1
2	≥ 10,000 ÷ <100,000	2
3	≥ 100,000 ÷ <200,000	3
4	≥ 200,000 ÷ <400,000	4
5	≥ 400,000 ppm	5

Note SIC will take Ave monthly defect ratio of product group in test from last fiscal year (from Apr to Mar).

Table 6. Major defect ratio levels (MD)

Base on fiber broken at assembly process

No	Ave Defect ratio (ppm)	score
1	< 1,000	1
2	≥ 1,000 ÷ <5,000	2
3	≥ 5,000 ÷ <10,000	3
4	≥ 10,000 ÷ <20,000	4
5	≥ 20,000	5

Table 7. Decision for periodical reliability test base on risk assessment (R= Cx Dx MD)

1 440.0			9004.		a	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	• • • • • • •	U.I. WOO	0000	•	K = K =)
C x D MD	1	2	3	4	5	6	8	9	10	12	15
1	1	2	3	4	5	6	8	9	10	12	15
2	2	4	6	8	10	12	16	18	20	24	30
3	3	6	9	12	15	18	24	27	30	36	45
4	4	8	12	16	20	24	32	36	40	48	60
5	5	10	15	20	25	30	40	45	50	60	75

Requirement for periodical reliability test base on risk assessment

No	Risk assessment (R= Cx Dx MD)	Reliability test (time/ year)
1	1 ÷ 9	1 time/ 2 years
2	10 ÷ 48	1 time / 1 year
3	50 ÷ 75	1 time / 0.5 year

FUJIKURA FIBER OPTICS VIETNAM LTD.			
PROCESS DESIGN QUALIFICATION			
Procedure: 4-Pr-007	Version: 39	Page: 8/14	

Appendix C: 4M Review for product long time re-run

Review 4M by E-request program: "ALL-4M Review for Product"

*Input information:

Product:

Current spec version:

New spec version:

*The main information of reviewing:

Review Material

Review Method

Review Machine

Review Man

Consider apply Trial run plan or Initial control after review 4M

Appendix D: Identify special spec and simple/similar spec

Note: Simple/Similar spec is the spec of simple products or similar with product usually running, not require special method, so we no need to review 4M if product re-run

Special spec is the spec require special method, need to review 4M if product re-run for a long time

Detail identify special spec and simple/similar spec:

Line	Special spec	Simple/Similar spec
Connector	 Drop Cable with Connector Black Cable product with taro Cable jacket (PNJHG-3846-25-01) IDM cable with cord 1.1mm 	All remain spec
Module	All remain spec	- IDM, NF, S8D, DC product '- Module FSC series
FA	N/A	All spec
MPO	- MPO Pigtail - MPO Jumper - MPO Fan-out	All remain spec
Cleaner	N/A	All spec
Closure	All spec	N/A
Panda	All spec	N/A
FAU	All spec	N/A
3C	All spec	N/A
Coupler	All spec	N/A
Cavity FG	All spec	N/A
Fiber Laser	All spec	N/A
Sensor FBG	All spec	N/A

FUJIKURA FIBER OPTICS VIETNAM LTD. PROCESS DESIGN QUALIFICATION Procedure: 4-Pr-007 Version: 39 Page: 9/14

Appendix G: MSA requirement

The following the requirement to use in determining whether or not a measurement system should be applied MSA

* When do we need to apply MSA

- Customer's request.
- Severity of measurement result (SMR) effect to product's main function follow table 1, table 2.

- Table1. Severity level of measurement result on product's main function

No.	Severity level	Severity level of measurement result to product quality	Score
1	Negligible	Inconvenience or temporary discomfort but no relevant effect on reliability	1
2	Minor	Reduce performance level, (primary function is still OK).	2
3	Major	Reduce primary function	3
4	Serious	Causes loss of primary function	4
5	Critical	Product becomes inoperative	5

- Table 2. MSA application for new measurement system

No.	Severity score	needed MSA
1	≥4	Yes
2	< 4	Not apply

* MSA will be carry out again if appling any change the main part of system, others MSA will be carry out in yearly

PROCESS DESIGN QUALIFICATION

Procedure: 4-Pr-007	Version: 39	Page: 10/14
---------------------	-------------	-------------

V. Record:

No.	Record	Responsible for keeping	Retention time
1	Check sheet inspecting in Production, Incoming	Production, Logistic (WH)	
2	Test report Check sheet inspecting of product in QA	Quality engineering	
3	New product Trial Run Request Change control request Master Plan Minute meeting report Technical Report Process Validation request and record	Production engineering Quality engineering	Refer to 0-PR-004 Control of Records

VI. Attached form:

1.	FORM: 4-Pr-007-4-Fo-0001	Sparepart list preparation
2.	FORM: 4-Pr-007-4-Fo-0002	Trial run request
3.	FORM: 4-Pr-007-4-Fo-0003	Master plan
4.	FORM: 4-Pr-007-4-Fo-0004	Meeting minutes
5.	FORM: 4-Pr-007-4-Fo-0005	Customer requirement break down sheet
6.	FORM: 4-Pr-007-4-Fo-0006	Technical report
7.	FORM: 4-Pr-007-4-Fo-0009	Process qualification implementation
8.	FORM: 4-Pr-007-4-Fo-0010	Periodical reliability test request
9.	FORM: 4-Pr-007-4-Fo-0011	Master plan for periodical reliability test
10.	FORM: 4-Pr-007-4-Fo-0012	4M review for product long tim re-run

PROCESS DESIGN QUALIFICATION

Procedure: 4-Pr-007 Page: 11/14 Version: 39

Questionnaires:

- Q1: Before trial run for sample, which design review must be hold? a. DR-1 b. DR-2 c. DR-3 Before shiping evaluation sample to customer, which design review must be hold? Q2: a. DR-1 b. DR-2 c. DR-3 Q3: After receiving customer evaluation on sample, which design review should be hold? a. DR-1 b. DR-2 c. DR-3 Q4: We should review "Customer requirement break down sheet" at: a. DR-0 b. DR-1 c. DR-2 d. DR-3 Which stage we should discuss & setup the target about QCD for production line. a. DR-0 b. DR-1 c. DR-2 d. DR-3 Draft OP, QC, FMEA, PS should be prepared before: Q6: a. DR-0 b. DR-1 c. DR-2 d. DR-3 Quality document: OP, QC, FMEA, PS should be reviewed and update in which stage: a. DR-1 b. DR-2 c. DR-3 d. DR-1, DR-2, DR-3 Q8: Who is consultor in DR meeting for process design qualification? a. Group leader upwards b. Executive upwards c. Department manager upwards Q9: In case the result of evaluation of New Product is failure, it should return back to which stage a. DR-0 b. DR-1
- Q10: In DR-1, which item should be reviewed?
 - a. List out all requirement from customer spec and review one by one item
 - b. Confirm finishing 4M preparation
 - c. Issue Plan for trial run product
 - d. a, b, c are correct

c. DR-2

PROCESS DESIGN QUALIFICATION

Procedure: 4-Pr-007 Version: 39 Page: 12/14

Questionnaires:

- Q11: In which stage, quality document level 2 need to be issued as official version
 - a. Trial Run
 - b. DR-1 & DR-2
 - c. DR-3
 - d. Transfer to mass production initial control
- Q12: Which stage we need to review the result of trial run compare with target setup.
 - a. DR-0
 - b. DR-1
 - c. DR-2
- Q13: The order of each action items in master plan for new product tranferring
- a. Collect INPUT information ® DR-0 ® DR-1 ® DR-2 ® Trial run ® Evaluation of customer ® DR3 ® Transfer to mass production initial control
- b. Collect INPUT information ® DR-0 ® DR-1 ® Trial run ® DR-2 ® Evaluation of customer ® DR3 ® Transfer to mass production initial control
- c. Collect INPUT information ® DR-0 ® Trial run ® DR-1 ® DR-2 ® Evaluation of customer ® DR3 ® Transfer to mass production initial control
- Q14: This procedure is applied for:
 - a. Controlling of new product transfer
 - b. Transfering manufacturing production line between diffirent factories in FJK group of company
 - c. Both a and b
- Q15: Which sections concern to Trial run stage?
 - a. PRE, QAE, PRD, SES
 - b. PRE, TRC, PRD, PTE
 - c. PRE, QAE, TRC, PRD, SES, PTE, PLN
- Q16: When we need to make internal periodical reliability test plan.
 - a. Monthly
 - b. Quarterly
 - c. Yearly
- Q17: Why do we need control long time re-run product
 - a. Review new update of 4M and customer's requirement on the product
 - b. Need to prepare 4M before re-run product conpletely
 - c. Both a and b
- Q18: When do you review Process qualification, MSA?
 - a. At DRO
 - b. At DR1
 - c. At DR2
 - d. At DR3
- Q19: When do you carry out Process qualification?
 - a. The results of the process cannot be fully verified by subsequent inspection and test.
 - b. Receive customer' request for process qualification
 - c. Both a and b

FUJIKURA FIBER OPTICS VIETNAM LTD. PROCESS DESIGN QUALIFICATION Procedure: 4-Pr-007 Version: 39 Page: 13/14

	REVISION HISTORY					
Date	PIC	Ver	Description of	content of change	Reason of change	Requester
Duto			Old Content	New Content		requester
16-Sep-24	Phuoc10253	39	No section E	Add section E.Product testing flowchart (TSA) (page 5)	From Aug-2024, PDS is no longer available so process 8-pr-001 is obsolete and the product testing section for customers is retained, this part is merged into process 4-Pr-007.	QMR_Ms Bao Tram & MNF. Division manager_Mr Kien
26-Jul-24	Ban 10151	38	In page 2/13 A - Process design qualification SIC: PDS	In page 2/13 A - Process design qualification Cancel SIC: PDS	Re-organize section in FOV	MNF. Division manager_Mr Kien
			Title of procedure 4-Pr-007: PROCESS DESIGN QUALIFICATION & CHANGE CONTROL In page 3/15. B-Change control	Title of procedure 4-Pr-007: PROCESS DESIGN QUALIFICATION Remove	- Seperate "change control" in procedure 4-Pr-007 to new	
16-Feb-24	Ban 10151	37	In page 6/15. Appendix A, B	Remove Re-numbering after remove Change control related content	Seperate change control in procedure 4-Pr-007 to new procedure 9-Pr-0014 Change control to apply for all changes in FOV system.	QMR_Ms Bao Tram & MNF. Division manager_Mr Kien
			Questionnaires: including content for change control	Questionnaires: remove content for change control		
				Appendix D: Identify special spec and simple/similar spec - Add new group: Fiber Laser, Sensor FBG	Review & add for new production line	
			In page 3/16: - Not yet define MSA	In page 3/15: - Define which measuring process need to apply MSA, refer to Appendix G-MSA requirement	- Establish MSA implementation.	
			- Form: 4-Pr-007-4-Fo-0004 Design review checklist for process design qualification.	- Form: 4-Pr-007-4-Fo-0004 meeting minutes.	- Revised meeting minutes form for flexible use.	
			In page 3/16: - Step 2. Review and approval None	In page 3/15: Step 2. Review and approval + If the change is applied to process with PQ application, it's followed to appendix C) Process qualification requirement.	- Make clear change for PQ application.	
				+ If the change is applied to process with MSA application, it's followed to appendix G)	- Added MSA application scope.	
2-Jan-24	Ban 10151	36	In page 3/16 + Review PQ requirement in step DR-1	In page 3/15 + Review PQ requirement in step review and approval.	- Correction.	QMR_Ms Bao Tram & MNF. Division manager_Mr Kien
			In page 7/16 Appendix D: PQ decision when apply new equipment or significant process' change	In page 7/15 Delete appendix D.	- Combine appendix D to appendix C.Process qualification requirement	
			In page 8/16 Appendix E: Define priority for periodical reliability test	In page 8/15 Appendix D: Define priority for periodical reliability test		
			In page 9/16 Appendix F: 4M Review for product long time re-run In page 9/16	In page 9/15 Appendix E: 4M Review for product long time re-run In page 9/15	- Re-numbering appendix item.	
			Appendix G: Identify special spec and simple/similar spec None.	Appendix F: Identify special spec and simple/similar spec Page 10/15 Appendix G: MSA requirement	- Build MSA for measuring process	
			Procedure name: PROCESS DESIGN QUALIFICATION & 4M AMENDMENT CONTROL	Appendix G: MSA requirement Procedure name: PROCESS DESIGN QUALIFICATION & CHANGE CONTROL		
			V. Content B-4M amendment	V. Content B-Change control	- Standardize name and PIC for 4M change procedure.	MNF. Division
16-Sep-22	Ban 10151	35	Project leader control 4M amendment procedure DR-1 at input for changes of machine/tool-jig None	- PIC control change control procedure - DR-1 at input for changes of machine/tool-jig + Add Note: PIC attach the function & design concept to change control	- Make clear this requirement for change control	manager_Mr Kien
				form and make clear designer's name & department in form "Design review checklist for change control"		
			Title of procedure: "Standardized product transferring & 4M amendment II. Application	Title of procedure: "Process design qualification & 4M amendment control" II. Application This procedure is goalled to all time of products how been qualified by		
			This procedure is applied to all type of products made in FOV. V.Content	This procedure is applied to all type of products have been qualified by customer or FOV design section follow to: 8-Pr-0001.		
			A. Normal product transferring Demand of process design qualification to FOV step: Migration Plan: 4-Pr-007-4-Fo-0002	V.Content A - Process design qualification - Demand of process design qualification to FOV step: Obsolete "Migration Plan: 4-Pr-007-4-Fo-0002"		
			- DR1: Input: None Review in DR-1: Review detail requirement with content of draft version of QC flow chart and Operation procedure	- DR1: Input: Added WI or FMEA from customer if any Review in DR-1: Review detail requirement with content of draft version of QC flow chart, Operation procedure, FMEA and PS		
			- Trial run Input: process specification, checksheet	- Trial run Input: Quality document: OP, QC, FMEA, PS, check sheet, template.		
			- DR2: Review in DR2	- DR2: Review in DR2: Review draft QC flow chart, Operation procedure, FMEA, PS with customer requirement and actual trial run		
			- DR3 Output: Department Manager upwards will make final decision to approve for new mass production.	- DR3 Output: Section manager upwards will make final decision to approve for new mass production.	Review and standardize document to improve design review	
			V.Content	V.Control		
11-Aug-22	Ban 10151	34	B. 4M amendment - Review and approval step: None	V.Content B. 4M amendment - Review and approval step: added "Note: all DR meeting must be joined and consulted by at least one averaging upward Project leader		QMR_Ms Bao Tram & MNF. Division manager_Mr Kien
			- DRO: none	and consulted by at least one executive position upward. Project leader should follow the guideline from DR checklist to ensure that all items in DR must be reviewed*.		
]			- DR1	- DR0: added "- Consider the impact to cost (ROI if change concern to new investment for machine/ tool) and delivery for the change " - DR1		
			input: none Review in DR1: none Output: none	- DR1 input: added "DFMEA of tool if any" Review in DR1:added "Review risk effect of this change to horizontial site" Output: add " Make clear risk effect of this change to horizontal site"		
			-DR2 Review in DR2: Evaluate risk to setup Q-condition & set counter spec(if any), can use the FMEA form of Customer	- DR2 Review in DR2: Re-evaluate risk and update P-FMEA for this change.		
			VI. Attached form 4-Pr-007-4-Fo-0001	VI. Attached form 4-Pr-007-4-Fo-0001		
			4-Pr-007-4-F0-0003 4-Pr-007-4-Fo-0004	4-Pr-007-4-F0-0002 4-Pr-007-4-F0-0003 4-Pr-007-4-F0-0004		
			4-Pr-007-4-Fo-0005 4-Pr-007-4-Fo-0006 4-Pr-007-4-Fo-0007	4-Pr-007-4-Fo-0005 4-Pr-007-4-Fo-0006	Issue new form and re-arrange form No. for better document control	
			4-Pr-007-4-Fo-0011 4-Pr-007-4-Fo-0012	4-Pr-007-4-Fo-0007 4-Pr-007-4-Fo-0008 4-Pr-007-4-Fo-0009		
			4-Pr-007-4-Fo-0015 4-Pr-007-4-Fo-0016	4-Pr-007-4-Fo-0010 4-Pr-007-4-Fo-0011		
			Questionnaires	4-Pr-007-4-Fo-0012 Questionnaires: update content for almost questionnaires	Update base on change of the procedure	
·			•		•	

FUJIKURA FIBER OPTICS VIETNAM LTD. PROCESS DESIGN QUALIFICATION										
Procedure	rocedure: 4-Pr-007 Version: 39 Page: 14/14									
			Separate workflow: A - Normal product transferring and 4M Amendment	Separate workflow: A - Normal product transferring B - 4M Amendment	Make appropriate requirement and control to each application					
			A - Normal product transferring and 4M Amendment DR1 (Input):	B - 4M Amendment: DR1 (Input): - Add: For changes of machine/tool-jig, review and confirm the function and design concept of machine/tool	Make clear instruction for input information when PRE review to improve machine/tool-jig					
			2) APPENDIX A: Exception application list for 4M amendment request	APPENDIX A: Exception application list for 4M amendment request Remove: Breakdown control of changes Simplify requirement for: Human & Document	Internal review (avoid duplicated with relating procedures)					
1-Jun-22	Trung 10089			APPENDIX B: Significant 4M Amendment and approval route Relate to Customer in list of "special customer" Requirement in customer specification Requirement by E-mail or other instruction from customer	APPENDIX B: Significant 4M Amendment and approval route Criterial specification or method that agreed with Customer Criterial specification or method that required by Customer or relating Standard Risk of quality or operating that impacted to final customer (user) directly	Internal review to make the description in general that easier for user.				
		Corrective action promised to customer Products Material change (not consumption) or controlled QC flow. Prossibility of quality change or risk of quality le possibility that Customer can't use by current.	6. Products Material change (not consumption) or process flow change controlled CG flow. 7. Possibility of quality change or risk of quality level down after shipping. 8. Possibility flow Customer can't use by current method. 9. Internal requirement specification in level 2 document. 10. Internal corrective action of FOV. 11. Consumption material in process. 12. Layout of workshop.	Remove 9 – 12	Re-consider approval level of change (assign to section manager level)	QMR_Ms Bao Tram & MNF. Division manager_Mr Kien				
							4) Appendix F: 4M Review for product long time re-run	4) Appendix F: 4M Review for product long time re-run - Remove pictures of program user interface	No need for general procedure	-
				VI. Attached form: 4-Pr-007-4-Fo-001 4-Pr-007-4-Fo-002 4-Pr-007-4-Fo-003 4-Pr-007-4-Fo-005 4-Pr-007-4-Fo-011 4-Pr-007-4-Fo-012	VI. Attached form 4-P-007-4-F-0007 4-P-007-4-F-0006 4-P-007-4-F-0003 4-P-007-4-F-0003 4-P-007-4-F-0004 4-P-007-4-F-0001 4-P-007-4-F-0001	Standardize number with 4 digits as 0-PR-001				
			Questionnaires:	Questionnaires: update content for Q.1 & Q.2	Internal review as revision for APPENDIX A					
			Questionnaires:	Questionnaires: update content for Q.12	Update for new instruction in part B - 4M Amendment: DR1 (Input)					