







REV	DATE	DESCRIPTION	SIG	
<u>^2</u>	20/07/29	Change dimensions and datum symbols Add cross-sectional view	nishiyama	











- 1. There must not be any burrs. Corners not indicated are to be thread chamfered.
- 2. There should be no scratches or warps.
 - *Dimensions are measured at acceptance inspection.

>

*	CMS BLOCK					A 5 0 5 2			*	Raydent treatment for light shielding		*	
No.	PART NAME					MATERIAL		.	Qty	FINISH		REMARKS	
GENERAL	TOLERANC	OLERANCE (mm) SURFACE		4 0 0 0	APPROVAL REVIEW			CHECK DRAWING		TYTLE		SCALE	
0. 5≦	≦6	±0.1	ROUGHNESS		APPR	ROVAL REVIEW		CHECK		DRAWING			
6<	≦30	±0.2	SYMBOL	(µ m)							FN00581	6 - 002	1:1
30<	≦120	±0.3	$ \nabla \nabla \nabla$		I								
120<	≦315	±0.5	\overline{W}	3. 2 S	tab	ata	tabata	m a	eda	maeda	DRAWING No.		
315<	≦1000	±0.8	$\overline{\nabla}$	12.5S	Ī						DRW3-13	2 1 1 2 (2)	*
1000<	≦2000	±1.2	∇	50S	Ī						ו שאט וי	0 1 4 0 (2)	