			FUJIKURA F	IBER OPTICS VIET	NAM LTD.		
			CHA	NGE ORDI	ER /2		
Form: 4-Pr-007-4-Fo-0007			Version: 2	2 Page 1/3 4-Pr-007-4-Fo-0007		07/2	
Record No. (get from DMS): 4-Pr	r-007-4	4-Fo-0007-4-R0	C-0193	Tittle: Cancel	checking adhes	sive inside cone of ferrule a	at ferrule assembly process
Proposed by: ChiNNL		Date: 28 Dec	2023	PIC: 0	ChiNNL (Code:	10864)	
A - CHANGE INFORMATION:							
A.1 Change category:							
□ Man		Material	8	Method/Docum	ent 🗆	Machine, Tool/Jig	
Process		Supplier		Factory/Section		Others:	
Significant or not? NO		YES (select be	elow options)				
						istomer or relating Standa	rd(s)
				tion or method t	0		
		LI Cause risk	of quality or o	perating that im	pact final custon	ner (user) directly	
A.2 Change description:							
Basic process of FA							
Adherive tacking >	essen		Polishing, Endfat		Cleaning	Blo Appla (C)	Next process
						400000	
				Mary Mary	50000000000000000000000000000000000000		
Currently Amount of adhesive	a incid	le femile's con	a hole is checke	ed at 3 nmcesse	s for FA line pro	ducts	

Propose to cancel checking adhesive at ferrule assembly process as table below

Process	Method	View point at process	Checking items	Current	Propose
Ferule adhesive sucking (A)	Under microscope		Amount of adhesive inside cone hole, Adhesive over flow to body	100%	100%
Ferrule assembly (After curing) (B)	By visual		Amount of adhesive inside cone hole, adhesive is cured, Stycat adhesive not touch fiber	100%	Cancel
App 3 (C.)	Under CCD camera	U	Amount of adhesive inside cone hole, Adhesive over flow to body, Adhesive is cured, Stycat adhesive not touch fiber	100%	100%

A.3 Application scope:

Apply for all FA products

A.4 Change reason:

1. Improve productivity for FA products, reduce duplicated inspection items

Cost saving by reducing duplicate can cover Fi-cost increase when defect flow out to next process. Estimate cost saving: 189\$/month

a. Improve of productivity

We estimate cycle time at ferrule assembly process can be reduced 5s/ batch 12pcs

Estimate cycle time improved / 1pc (6)	5/12=0.42(s)
PC rate (in Dec 2023) (7)	2.71
Plan/ month (pcs) (4)	600,000
Cost saving/product (8)= (6)*(7)/3600	\$ 0.000316
Cost saving/ month (9)=(8)*(4)	\$ 189.70

b. Fi-cost

Trend of defect adhesive over flow/ not enough adhesive inside ferrule cone hole detected at adhesive suction is reduce. Therefore, ability defect flow out from Ahesive suction is also reduced.

Defect ratio base on process found (from Jul-2023 to Dec-2023)



- Note: Defect have trend reduce from Sep.23 -> Dec.23 , some action was applied:

 + Prepare the jig used to fix ferrule during injection (some jig sticked a little adhesive so affect to ferrule not fix well to jig)
- + Standardize coordinates of needle on semi auto suction machine for each kind of femule

				and the second s		IBER OPTICS VIETNAM LTD.		
	10.00					NGE ORDER	B	
-	4-Pr-007	-4-Fo-000	17		Version: 2		Page 2/3	
	Estimate F	i-cost increa	ase after cance	check adhesiv	ve at ferrule (d	defect flow out to Appearance 3)		
PRINCIPAL PRINCI	Proces	ss found	Ficost/case (1)	Defect rati		Defect ratio if cancel check at Ferrule (ppm) (2')	Ficost/month (current) (3)=(1)*(2)*Plan 600,000pcs	Ficost/month (after cancel check at Ferrule) (3')=(1)*(2')*Plan 600,000pcs
P. Community of		assembly rancce 3	0.26	3		65	\$ 5.15 \$ 5.57	
-	Appea	rance 3	0.29	Total Fi-cost	and the second s	00	\$ 10.72	THE PARTY OF THE P
			fect "Not enou e process / mo			flow out to Appearance 3 after	cancel check	\$ 0.59
	when defe	cost saving oct flow out to	o next process		\$ 189.110	y process. Cost saving by reducing the process is more clear that		
		product at fe			out, it can be	detected at appearance 3 proces]
			ve suction	Good sample			No change	
				1				
		renue	assembly				Cancel	
		Appea	arancce 3				No change	
1	ANGE CO	ssment	nanufacturing p			eed FMEA review, reason:		•
					Mi	spection from 300%	40 200 %	
		FMEA re	cord No. & curr	ent version		FMEA name		Review result (fill in 'not update', or 'new version' if need update)
	No.							
	No.							
)1		es:						
1	1	95:	F	Risk		Ac	ction to control risk	
	1 her change	98:	F	Risk		Ac	ction to control risk	

B.2 Design review: REQUIRED (DR0, DR1, DR2, DR3)

NOT REQUIRED, reason: Just Notice duplicated in specific 1501, 1020/

Plan No. for Test Run:

Result of Trial Run/Validation: refer to attached Technical report No.:

"Confidential: FOV's property, do not take out without FOV BOM's approval"

		FUJIKURA FI			
		CHA	NGE ORDER		
m: 4-Pr-007	-4-Fo-0007	Version: 2		Page 3/3	
B.3 Review an	d update document: YES		NO, reason:		***************************************
List out documen	ts need to be updated/new-issued, confirm revisi	ing completed after o	change order is approved)		
No.	Document No. & existing version		Document name	New version	Actual completion date
1	001-4-PS-061-0019	Appearance 3	- (Body rời +Body IM)	6	212012024
2	4-OP-0162-4-PS-010-0003	FA - Ferrule as cắt phẳng	ssembly - Sån phẩm SC- Fiber	15	2/20/2024
3	001-4-PS-061-0020	Appearance 3	- LC	6	2/2012024
4	4-OP-0162-4-PS-010-0008	Ferrule assem	ibly - Sán phẩm LC - Fiber cất	5	2/2012024
5	4-OP-0162-4-PS-010-0002	FA - Ferrule a Fiber cắt góc	ssembly - Sản phẩm SC, LC -	10	212012024
6					
7					
Cinnat		change)			
Comm	ure: Date:	19-Feb-202	24 次機製 24.02.19		
C.3 Customer	ure: Date:		1240240		
C.3 Customer Signat	nure: Date: ient: 's approval: (if any) ure: N.Sasano Date:		1240240		
C.3 Customer Signat	inent: Date: Sapproval: (if any) Ure: N.Sasano Date: Date: LEMENTATION:		1240240)	
C.3 Customer Signat Comm CHANGE IMP D.1 Initial control	inent: Date: Sapproval: (if any) Ure: N.Sasano Date: Date: LEMENTATION:	19-Feb-202	24.02.19 推野 NOT REQUIRED	,	
Comm C.3 Customer Signat Comm CHANGE IMP D.1 Initial control Initial control Initial control D.2 Training re Re-instruct,	plan No: completion report No. completion report No. completion report No. content:	19-Feb-202 □ REQUIRED	24.02.19 推野 NOT REQUIRED		
Comm C.3 Customer Signat Comm CHANGE IMP D.1 Initial control Initial control Initial control C.2 Training re Re-instruct, Re-train, upon	ure: Date: Sapproval: (if any)	19-Feb-202 □ REQUIRED	24.02.19 推野 NOT REQUIRED		
Common C.3 Customer Signat Common CHANGE IMP D.1 Initial control Initial control Initial control C.2 Training re Re-instruct, Re-train, upo	plan No: completion report No. completion report No. completion report No. content:	19-Feb-202 REQUIRED NO NYES	NOT REQUIRED Training record No./Meeting min		
Common C.3 Customer Signat Common CHANGE IMP D.1 Initial control Initial control Initial control C.2 Training re Re-instruct, Re-train, upo	plan No	19-Feb-202 REQUIRED	NOT REQUIRED Training record No./Meeting mid	nutes:	
Common C.3 Customer Signat Common CHANGE IMP D.1 Initial control Initial control Initial control Initial control Co	plan No	19-Feb-202 REQUIRED	NOT REQUIRED Training record No./Meeting min	nutes:	
Common C.3 Customer Signat Common CHANGE IMP D.1 Initial control Initial control Initial control Initial control Co	Date: Sapproval: (if any)	19-Feb-202 REQUIRED	NOT REQUIRED Training record No./Meeting mid	nutes:	