FII	IIIKIIRA	FIRER	OPTICS	VIETNI A	MITE

SPAREPART LIST PREPARATION

3

Form: 4-Pr-007-4-Fo-0001 Version: 3 Page 1/1 Effective date: Follow EIC 4-PR-007-4-Fo-0001/3

Record No: 4-Pr-007-4-Fo-0001-4-RC-0115

No.	Spare part kind	Spare part name	Model	Drawing No	Photo	To be used for machine name	Current stock (pc)	Safety stock (pc)	Price (USD/pc)	Purchasing leadtime (day)	Life time	Supplier name	Remark
1	1 2 3 4 Inventory consumption spare parts 5	Blade (No 28 - Black)	MS1-RB-28S			Soft strip	1	1	46	5 21		FOCS	
2		Blade (No 14 - Dark green)	MS1-RB-14S			Soft strip	1.5	1	46	15	-	FOCS	
3		Blade for PCS-100	PCB-01			Stripper PCS-100	50	10	16	5 45	-	FPLS	
4		Electrode / ELCT2-20A (for FSM-70S)	ELCT2-20A		1	FSM-70S	5	2	68	3 75	i -	COMS	
5		Electrode / ELCT3-25 2 (for FSM-100M+)	ELCT3-25 2			FSM-100M+	1	2	24	45	-	FPLS	
6		Cutter blade	CB-06		•	CT-101 and CT-105	1	1	430	60	-	COMS	
7		Ceramic heater	WALN-7			Temperature measuring device	0	1	314	15	-	YLDS	
Critical spare parts	Coated thermocouple	MSEW0.32-500			Temperature measuring device	1	1	1,600	15	-	YLDS		

Note: + Inventory consumption spare part is the part which is worn out through processing directly on product. Example: CT cleaver blade on CT cleaver, Stripper blade on stripper HTS-12, electrode on splicer, Teflon heat of cerrocast pot... This kind of part is taken care by PRE/DES.

⁺ Critical spare parts are remaining kinds of spare part which does not process direct to change material/WIP form, or the back up parts recommended from maker or transferring side engineer through user guide, maitainance guide or discussion.

Example: Bearing, sensor on polishing machine; relay, thermal controller on heater, Nest on cerrocast machine...

This kind of part is taken care by PTE.