Date 9 Oct, 2023

No. SPPU-10371 (4)

Messrs. FOV Ltd.

# **SPECIFICATION**

**FOR** 

Trillian Shuffle Assy

(Fiber Glass Array - Cerrocast - MPO, LC Assy for Lumentum)

#### Fujikura internal information

提出仕様書No. Fujikura Specification No. (Proposed to customer)	先方仕様書No. Customer Specification No.						
PNJHE-1321-64-12 Rev. 5	AD22166179 REV012						

仕様書がない場合には斜線 を入れること。(空欄にしない)
In the absence of Fujikura/Customer specifications, Fill an oblique line in the column. (Don't leave the column blank.)

Prepared by T.Nakane

Approved by H.Hishikawa

Fiber Optics Components Department Optical Components Division

Manager,
Fiber Optics Components Department
Optical Components Division

# Fujikura Ltd.

# Working Instruction Details Product Name Trillian Shuffle As

SPPU-10371 (4)

1/11

Product Name	Trillian Shuffle Assy	
Product Drawing No.	PNJHE-1321-64-12 Rev. 5	
Fujikura Product No.	HHE-1321-004-001	

N.				Specifications	Inspection	Place/Cot	ent Record	Note
No.				Specifications	Quantity	Record	TR	Note
1	P	roduct name	Fujikura Product Name	Trillian Shuffle Assy	All	Record All	Record Test Result	
2	Quantity Comply to the quantity sp			cified in Procurement Specification	All	Record All	Record Test Result	
3		Structure	Same as the structure defined	in PNJHE-1321-64-12REV5, Fig. 1-1, Fig. 1-2 and Fig1-3.	All	Record All	Record Test Result	Measure dimension of 140+/-2 as Fig. 1-1 for all product.
4			No damage, scratches that i	may lead to product non-functionality	All	Record All		Refer to Lumentum Doc. 21152930 and 22166125
5	]		Fiber	No damage. No peel off, No abnormallity	All	Record All		
6			Connector endface and cap	Use cap after cleaning and clean several connector endface before shipping.	All	Record All		
7			FAU	PNJHE-1321-22-03(Latest version)	All	Record All		FOV PS No.:9-QC-001-9-PS-061-1532
8	]	Appearance	Cerrocast tube	PNJHE-1321-22-02 (Latest version)	All	Record All		FOV PS No.:9-QC-001-9-PS-061-1554
9	]		Cerrocast after soldering	PNJHE-1321-22-03 (Latest version)	All	Record All		FOV PS No.:9-QC-001-9-PS-061-1532
10			0/E Cap	PNJHE-1321-22-01 (Latest version)	All	Record All		FOV PS No.:9-QC-001-9-PS-061-1531
11	]		Fiber end face for MT	PNJHA-0038-40-64/RQFU-10136(Latest version)	All	Record All		
12	]		Fiber end face for LC	PNJHA-0038-40-63 (Latest version)	All	Record All		
13	1		Ferrule end face for MT	PNJHA-0038-40-25/RQFU-10077 (Latest version)	All	Record All		
14	Connec	tion (MPO side)	No mechanical abnormalities	s during connection.	All	Record All	Record Test Result	
15	Optical	Insertion Loss	12MP0	Not more than 0.6dB	All	Record All	Record All	@1. 55um
16	Performance for	Insertion Loss	LC	Not more than 0.3dB	All	Record All	Record All	@1.55um
17	Connector	Return Loss	N/A					RL measurement is not necessary
18	Inspection for Carrocast	Leak test	<5.0*10^-10 Pa m3/s by He	n3/s by He leak tester		Record All	Record All	Record below items for all cerrocast tube. 1. Value of leak 2. Pressure
19	End Face	Geometry for MT	12MPO side	PNJHA-0038-40-52/RQFU-10074 (Latest version)	All	Record All		
20		ber breakage by using ion Reflectometer	Need		All	Record All	Record All	
21	1	Ident check	Same as the numbering arra	ngement indicated in the drawing, Fig.1-2	All	Record All		Apply ID check master plug as Fig. 4
22		Loading Condition	Package in such a way that	will prevent damages during transportation	All			
23	Packaging	Display	Label the product serial n	umber. (Fig. 2)	All	Record All		
24	]	Display	One indicate on the carton	box as Fig. 3.	All	Record All		
25		Attachment	Submit the test results fo	r Fujikura separately	All	Record All		According to template 1/2 and 2/2, without RL.
26	Substance (	Control Requirements	PNJAA-0068-25-01 /SPPU-0101	9 (Latest version)				Confirm all of materials
28	Others		4M change		All	Report all		Any 4M changing shall be report before apply Refer toLumentum Doc ID: 10129520- 136 (R010)
29	Т	raceability	manufacturing and inspection	on record shall be kept at least 5years.		Record All		

#### Product name


Chart 1: Product name

No	品名/Product name	型番/Fujikura Product No.	物品番号/Customer Product No.
1	Trillian Shuffle Assy	HHE-1321-004-001	AD22166179REV012

Component chart and costing survey sheet

Original Revision Remark

evision							cification of	latest version to all part					
	No.		Item	Dr	rawing No. (*)	Material	Qty	Vendor (firs	t time)			Remark	FOV Material Coo
	1	FAU_TRILLIA	N	PNJHE-1321-72-	03	-	1	AF0P	(FJK-CNC)	*) fiber have	damage in n to use a	A-PMZD-U30A2 repairable area, it can be use by repair. ny color decolorized fiber.	S0F0147
	2	Pre-Angled (for 80um f	12MT-MPO-TP iber)	PN	JHY-0005-22-86	PPS	7	FHO or FJK	(FJK-CNC)	1		vailable too.	CNF0293
	3	3 12MT Boot 4 Housing SS			JHY-0005-71-25	AR-NEO-80	7	YUWA	(F0V)				CAN0177
	4					PBT	7	MUTO VN	(F0V)				CAN1114
	5	5 Spring (C) N PNJHY-0010			010-71-84/DRPT-00408	SUS301	14	FOV (Cheye) or FJK	(F0V)				SPR0072
	6	Coupling N	(Blue)	PNJHY-00	010-71-90/DRPT-10738	PBT	1	YUWA	(F0V)				CAN1426
	7	Coupling N	(Orange)	PNJHY-00	10-71-119/DRPT-10739	PBT	1	YUWA	(F0V)				CAN1436
	8	Coupling N	(Gleen)	PNJHY-00	10-71-100/DRPT-00353	PBT	1	YUWA	(F0V)				CAN1442
	9	Coupling N	(Beige)	PNJHY-00	10-71-103/DRPT-00355	PBT	1	YUWA	(F0V)				CAN1403
	10	Coupling N	(Red)	PNJHY-00	010-71-102/DRPT-1065	PBT	1	YUWA	(F0V)				CAN1437
	11	Coupling N	(Black)	PNJHY-00	010-71-99/DRPT-00354	PBT	1	YUWA	(F0V)				CAN1435
	11	Coupling N	(Aqua)	PNJHY-00	10-71-137/DRPT-00409	PBT	1	YUWA	(F0V)				CAN1441
	12	Spring Push	SS	PN	JHY-0010-71-185	PBT	14	MUTO VN	(F0V)				CNH1227
	13	Spring (D)N		PN	JHY-0010-71-187	SWPB	14	FJK	(F0V)				SPR0094
	14	Pin Clamp S	S-M	PN	JHY-0010-71-186	PBT	7	MUTO VN	(F0V)				CNH1228
_ [	15	Premier Pin	4(Lead Free)	PNJHY-00	10-71-158/DRPT-10517	SUS (NSSC550)	14	FJK	(FJK-CNC)				PIN0039
9	16	Cap B		PNJHY-00	010-71-95/DRPT-01178	PP	7	YUWA	(F0V)				CAN0066
component	17	SILICONE TUBE (YELLOW) DIA. 1. 4		PN	JAA-0024-22-03	Silicon	(**)	-	(F0V)	(**) Up to product length		ength	MPTSSY0010
٥	18	HYTREL 6356 (NIREI) **	0.5X0.9 BL or NA	PTB	0339 or PTB0321	Hytrel	(***)	-	(F0V)	(***) Up to product length BL:Color Blue, NA: Natura			PTB0339 orPTB032
	19	Cerrocast T	ube with acid etching	PNG	JHE-1262-71-38A	Brass	2	Material: Belton Etching: KEIDEN VN or KEIDN JP	(FJK-CNC)	2) Expired d	ate of tul I disposa storage.	ching at KEIDN VN is acceptable.  e after etching is 1 month.  : Cerrocast Tube required acid etching  PD22022968	MCN0190
	20	0/E Cap		PN	JHE-1262-71-16B	-	1	Shengda	(FJK-CNC)	Supplier Sp	ec No. : I	D22045645	MCN0204
	21	LC Connecto 80um fiber)	r kit (SM, 0.9mm, for			-	5	Orbrey	(F0V)	K-04-0028-0 SPSU-10911)	A-2-2 (PN is accepta	HY-0048-22-133/ ble	
	21-1	LC Ferrule			-01-3287-0A-2 o.: KK-071-04-0A-2-2)	Zirconia	5	-		PNJHY-0048-	22-132		CNF0335
	21-2	LC Housing	parts (SM BTW)		k-04-0008-0A 48-22-123A/SPSU-10673)	-	5	-		(*) without	ferrule		CNH1147
	22	Tepra white	6mmx8m TURIN		SS6K	-	5	-	(F0V)	Label for L	С		
	23	Silicon pip	e		-	-	5	-	(F0V)	ID: 2mm; OD			PTB0403
	24	Sroral sili	con tube BLUE		-	-	(250mm)	-	(F0V)	coverd shuf Silicon tube		mm blue	MPTSSY0024
Ĺ	25	Kapton tape			P-221		(40mm)	-	(FOV)	width :12.	7mm		PLT0096
	26	Yellow mask	ing tape	234J-1	0		(40)	=	L	3M 234J PLU	S width	Omm	
-	27	Alloy IND 5	8BI42SN SHOT		-	-	-	-	(F0V)	Bi: 58.0% LIQUIDUS	+0.5, Sn: TEMPERATUR	ion for Cerrocast 42.0%+0.5 E: 138deg+/-3 :: 138deg+/-3	ALS0001
Doc	ument	No.	Product Name		Trillian Shu			Qty	TR	Shipping Date	Due Date	Customer	PO No.
			Fujikura Product		HHE-1321-0			- 1					
			Proposed drawing n	umper	PNJHE-1321-64	-12 Kev. 5		1	1				









Fig. 1-2






tube slit sahll be both side



See X- section of tube slit

## Packing method : Fig 2




IYYMM00001 Trillian Shuffle Assy <sup>1</sup> egend: [YYMM00001]; Chracter to identify product PNJHE-1321-25- 11\* YYMM: year and month manufacturing 00001: 5 digits increase by monthly

#### Example of label indication

Laber attach on spiral tube as below (customer request to prevend for fiber damage)







Indication item for Carton box label: Fig 3



\*Use EDI data from Fujikura Ltd.

Fig. 3 Indication item for Carton box label

#### Note:

1) Barcode shall be used barcode 3 of 9 format

#### Environmental requirement

Follow the PNJAA-0068-25-01/SPPU-01019(latest version)

: General Specification on Substance Control Requirements

## **Drawing of ID check master plug**




Fig. 4

Good

Good

10/11

Page 1 / \*\*

Conform to Specifications

No deformation, damage or scratches

that may lead to product failure

### **Test Inspection Report**

AD22166179REV012

xx pcs

9-Feb-2018 Issue date: Trillian Shuffle Assy Product Name: Fujikura Ltd. HHE-1321-004-001 Fujikura Product No.

(FJK P/O No.) Lot No: Quantity:

Leak test

Appearance

ΑII

ΑII

1. Test Results

Customer Product No.

#### Inspection Test Item Specifications Test Results Judgement Quantity Conform to Specifications Conform to Specifications Structure and Dimensions ΑII Good Insertion Loss ΑII Not more than 0.6dB Not more than 0.6dB Good for 12MPO Optical Characteristics Insertion Loss ΑII Not more than 0.3dB Not more than 0.3dB Good for LC

≤ 5.0\*10^-10 Pa m3/s by He leak tester

No deformation, damage or scratches that

may lead to product failure

#### 2.Test Condition

Inspection

for Carrocast

Light Source	LED
Wavelength	1550nm
Measurement connector	Measure by Master Reference Connector (MPO connector)

# Test Inspection Report (Template 2/2)

SPPU-10371(4) 11/11

## 3. Results for Insertion Loss Inspection

Page 2 / \*\*

### Style example

	Connector				31	Incortion I	occ (MDO	<0.64B	1 C < U 2 4	2)				Max		Leak te			
Serial No		noctor								Value	Value	of leak	Pressure		Judgement				
		#1	#2	#3	#4	#5	#6	#7	#8	#9	#10	#11	#12	value	Cerrocast 1	Cerrocast 2	Cerrocast 1	Cerrocast 2	
	LC1		150	-	0-2	-	=	1-1	-	p=3	-	-	45.0						
	LC2	2 ]	523			-	2	729	-	121	-	27							
	LC3	-	(-)	-	(-)	-		-	-	(1-)	-	-	-						
	LC4	-	1-1	-	(-)	-	-		-	-	-	-	-						
	MPO1	2 1											- 23						Good
	MPO2	,																	Good
	MPO3														1				
	MPO4																		
	MPO5						8												
	MPO6						-	(-)											

Ident:線番確認 Good

SPPU-10371(4)

Rev.	Date	History	Reason	Issued	Checked	Approved
$\Box$						
	2018. Sep.28	Issued		Kanno	Shida	Fujiwara
/	,					
Α	2018 Oct.19	Page 1: Add mentions of appearance spec for some material.	To make clear for appearance spec by adding FOV PS No.			
		Page 3: Add "Plastic tape, no. 7239".	Customer requests to apply marking for shuffle area.			
		Add "Alloy IND 58BI42SN SHOT"	To make clear for alloy material	Kanno	Shida	Fujiwara
		Page 4, 5: Change drawing	Customer's request was changed. To make clear for some dimensions for Cerrocast.			
		Page 6: Add label indication.	To make clear for label indication.			
В	2018 Nov.12	Page 1: Change appearance spec No. for FAU, Cerrocast, and O/E Cap.	Change to Fujikura No. insteatd of FOV PS No.	Kanno	Shida	Fujiwara
		Page 4: Add detail about fixed tape and spiral silicon tube.	To make clear for design.			
		Page 6: Change label content	Change to correct content for this product.			
С	2019 Feb. 12	Page 3: Changed LC connector from "C-09- 4286-0A-2-2" to "KK-071-04-0A-2- 2"& "C-09-1062-0A (without	For cost reduction. JEHE-58-19-0001	Kanno	Shida	Fijiwara
		ferrule)". Page 4: Added UV adhesive length 3~4mm.	To improve fiber break problem. JEHE-58-19-0002			
		Added picture of yellow tape for shuffling area	To make clear for the structure.			
		Page 8: Added drawing of ID check master plug.	To make clear for the structure of ID check master plug.			
D	2019 Feb.21	Page 3: Changed LC ferrule P/N to "C-01-3287-0A-2".	Adamant issued the official P/N.	Shida	Uenoyama	Sawada
		Page 4: Added Super X application to the end of MT boot.	To prevent a fiber break. JEHE-53-19-0007			
		Page 6: Changed the packing picture.	The long pink sponge is not necessary.			

	Date	History	Reason	Issued	Checked	Approved
Е	2019	Fujikura spec No revised to Rev. 2	Customer request			
	25-Oct	customer Dwg Rev009		Araki	Sawada	Hanya
		Page 1. No.20	  mistake			
		Check reflect change to Need	apply to actual FOV process			
			S			
		Page 3 Changed components MPO housing, Spring Push,	Design change of MPO housing preventive action for fiber damage			
		Pin clamp, Spring Push,	JDHY-22-19-4018			
		PNJHY-0010-71-98→184	JDHY-22-19-4033A			
		PNJHY-0010-71-89→185				
		PNJHY-0010-71-88→186				
		PNJHY-0010-71-13→187 PNJHY-0010-71-180→158				
		Change fiber length Fig1-1	customer request			
		(PNJHE-1321-64-12 Rev.2)				
		Change shuffle area tubing method	customer request			
			tube dia should be less than 3mm			
			for wring in module.			
		Packing label customer product mame REV005 → REV009				
		Changed drawing				
	0010	Customer Dwg REV009 → REV010	LC fiber length changed to 700mm.	Araki	Sawada	Hanya
F	2019 11. Nov	FJK Dwg Rev2 → Rev3	mistake design by customer.			
	11. 1100					
		Changed drawing	Customer request changing			
	2020	Customer Dwg REV010 → REV011 FJK Dwg Rev3 → Rev4	Fiber length, shuffle area length fix ribbon fiber by kapton tape	Araki	Sawada	Hanya
G	27. Apr	TON DWg Nevo - Nev4	The ribbon liber by kapton tape	Alaki	Jawaua	litaliya
	·	changed components				
		kapton tapem, 3M yellow tape				
		Changed drawing Customer Dwg REV011 → REV012	Customer request changing Fiber length, shuffle area length			
		FJK Dwg Rev4 → Rev5	fix ribbon fiber by kapton tape			
(1)	2020	Fig 1-3 added Additional work	Customer request			
H	3. Sep	slit yellow tube		Araki	Sawada	Hanya
		Fig.2 revew the packaging photo	align with current packing method			
		Changed TR format delete S/N ,	FOV request			
		chnaged IL tabel	align with current packing method			
		1/11 working instruction detail				
		No.3 Draing No -Rev5 No.4 added customer doc No.for	correction			
		appearance	make clear the spec			
		added OBL3 DOC No.	apply to OBL3			
		No.28 added 4M change	action for customer claim			
(2)	2022	No.29 added traceability	customer request			
(2) I	2022 11.Feb	3/11 component update FOV material code	correction and update	Araki	Sawada	Hishikawa
•	55	changed LC housing	EOL by supplier			
			4M change approved by			
		A /11 E'-1 1	JEHE-58-19-0003			
		4/11 Fig1-1 added minimize fiber tangle	customer request			
		7/11 label	- Customor request			
		added to use spiral tube	make clear the actual			
		Conpornent chart	Make clear the using of repairable			
(3)	2022	Item1 FAU added comment to using for repaire of	FAU			
J	13.Apr.	fiber damage	changed packing tray for reduse	Araki	Sawada	Hishikawa
			fiber damage. Customer approved			
	1	Fig 2 changed packing tray	4M change No.JE-58-21-1142			

Rev.	Date	History	Reason	Issued	Checked	Approved
(4) K	2023 9.Oct	[1] Added Hytrel tube color NA in P3 BOM No.18.  [2]The OBL specification number is also listed in the cited specification.  [3]In P3 BOM NO.1,it clearly states permission to use any color decolorized fiber.	[1] Since BL has become EOL, NA will be switched as soon as stock of BL runs out. (JE-58-22-1172) [2]To trace eaiser. [3]For Approval by the customer	Nakane	Araki	Hishikawa
		association in the control of the co				