FUJIKURA FIBER OPTICS VIETNAM LTD  CONCESSION PROPOSAL FORM								
Form No.: 9-Pr-008-9-Fo-002			Version: 07 Page: 1/1 Sub code				Sub code	
Record No: 9-Pr-008-9-Fo-002-4-RC-0612			Record Name: Concession for using Outer Shell which failed function checking Cleaner products				I function checking for	
Proposed by: Thu DTM Date: 30-Aug-24			20014		Checked by: Date: 30-Aug-24			
1. I would like to propose a concession for nonconforming item(s) as follow:								
Product Method Material Machine Others:								
Nonconforming report or issue date: 14-Aug-2024								
Concession content: The Outer Shell received from Supplier, FOV checked the function with the gauge and get the not good result.  Material failed testing following 000-7-WI-0202 as below picture:								
II. Kiểm tra chức năng: Trong giai đoạn sản xuất hàng loạt, số lượng mẫu cần kiểm 1 shot/ Working day								
Kiểm tra khá PNJHW-0042 năng lấp với			for outer shell D (-21; SUS304).	(spec:	tter Shell (white)	1 OK I	Pin gauge	
1 Gauge for outer shell D, lắp Gauge for outer shell D vào theo phương thẳng đứng, nếu shell D vào theo phương thẳng đứng, nếu (PNJHW-0042-71-21)  Câm Outer Shell D, lắp Gauge for outer shell D vào theo phương thẳng đứng, nếu shell D di chuyển để dàng thì OK, ngược lại NG.				, néu				
- FOV apply to make assembly product sampling to confirm the function following instruction fro CNC: apply to click 500 times for								
jamming checking as below products:								
	Item Number II		ш.) (р.с.)		Remarks	Result of samples	_	
LCN0278 3857853				240720000066	Passed			
- FOV propose to use this material for Clenaer product as normal material.    Maker lot   FOV lot   Stock (pcs)								
	240713-2470450F2		240720000066		735			
240714-2470450F2		-2470450F2	240720000068		2000			
240715-2470450F2		-2470450F2	240720000072		2194			
240618-2460339F2		-2460339F2	240720000073		47			
			Total (pcs):		4976			
2. Reason								
Effect to delivery schedule  Not required in customer Spec, but required in FOV								
Others (Detailed description): Actual dimension of outer shell are still in specification.								
The reason of the gauge testing failed caused by dimension of gauge is not designed properly								
3. FOV's Approval:  QA confirmed (if any):  Approved by:								
□ Not accept, follow the relative procedure □ Internal concession  12 165								
Not accept, follow the relative procedure Internal concession Need inform to customer Need approval of customer  Need approval of customer  A Sustamer's approval:  One of the relative procedure  A Sustamer's approval:  One of the relative procedure  A Sustamer's approval:								
Need approval of customer  4. Customer's approval:								
Accept								
(24.09.11)								
					Signature:	能川		
	Date:							
Confidential FOV's property, do not take out without FOV BOM's approval								