


A

A

POWER SUPPLY



B

B

C

C

D


D

Sheet: /PWR_SUPPLY/
File: PWR_SUPPLY.kicad_sch

Title: Charger

Size: A4 Date:
KiCad E.D.A. 9.0.0

Rev:
Id: 2/8



A

A

B

B


C

C

D

D

Buck-Boost



Sheet: /PWR_SUPPLY/Buck-Boost/
File: Buck-Boost.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.0

Rev:
Id: 4/8

A

A

B

B


C

C

D

D

Temp Sensor




Sheet: /Temp Sensor/
File: Temp_Sensor.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.0

Rev:
Id: 6/8

Accelerometer Magnetometer




Sheet: /Accelerometer-Magnetometer/
File: Accelerometer-Magnetometer.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.0

Rev:
Id: 7/8

USB Type C



Sheet: /usb-c/
File: usb-c.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.0

Rev:
Id: 8/8

A

A

B

B


C

C

D

D

USB to Serial



Sheet: /USB_to_Serial/
File: USB_to_Serial.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.0

Rev:
Id: 9/8