PROD Commercial HARDWARE ISSUES AND STAT...

Please use these comments regarding hardware as the present status (source of truth). Please keep this up to date.

US-SOUTH Slicestors - NO DISK REPAIR

osscsrgdal1004h osscsrgdal1204h osscsrgdal1304h osscsrgdal1004q osscsrgdal1204q osscsrgdal1304q osscsrgdal1005b osscsrgdal1205b osscsrgdal1305b osscsrgdal1005k osscsrgdal1205k osscsrgdal1305k osscsrgdal1005t osscsrgdal1205t osscsrgdal1305t osscsrgdal1006e osscsrgdal1206e osscsrgdal1306e osscsrgdal1006n osscsrgdal1206n osscsrgdal1306n osscsrgdal1006w osscsrgdal1206w osscsrgdal1306w

Reminders:

Device	Instruction comment	Case, if open
osscsrgtok0502d	This device is up & should be removed from this list.	TS007287210 I.M - This case has been closed and this device is back in service. The issue is being tracked through a JIRA, and the customer workflow that lead to this issue was identified and stopped.
osscsrgwdc0606c	This device is up & should be removed from this list.	11/11 - Mohammed No comments on what is being done to do this device from L3? Last comm indicated this device needed a chassis swap. Do not see any case for investigations. Port negotiation issue. Resolved by DP. https://ibm-cloudplatform.slack.com/archives/G49M53E2Z/p16 36666836218300

osscsrgwdc0606d	This device is up & should be removed from this list.	TS007315281 I.M - This device was re-imaged to the wrong version and has been upgraded since and working as expected. The case is open to seek improvements in this area that will come out of the RCA call.
osscsrgdal1007t	This device is up & should be removed from this list.	TS006845016 I.M - This is another device were transactions being rolled back lead to client IO being impacted. The device has been back in service for some time now.
osscadal0903e	keep dsnet-core off, L3 is working on it	TS007310377
osscsrgwdc0401 m	Keep dsnet-core until L3 provides next instructions	TS007458439 I.M - This is another device were transactions being rolled back lead to client IO being impacted. I am discussing this with dev, looks like a ClevOS defect.
osscswdc0404v	Keep dsnet-core until L3 provides next instructions	TS007507974 I.M - This is another device were transactions being rolled back lead to client IO being impacted. I am discussing this with dev, looks like a ClevOS defect.
osscsrgwdc0602t	DO NOT start dsnet- core	L3 Case # TS007511513