



Robotics Week Instructor
Joy Shetler, PhD


Session Three Installing X-CTU & Configuring XBeeS

Intel Ultimate Engineering Experience (IUEE)


Plug in Xbee Explorer with Xbee Attached




Navigate to: c:\Users\Intel\Desktop\myQuad\Wireless




X-CTU – Test Xbee



Confirm Communication – Click OK



Click Modem Configuration Tab



Click Read




Recycle Bin



Paint.NET



X-CTU



Change PAN ID to Kit Number (Found on Box)




Recycle Bin



Paint.NET




X-CTU




Arm


Change Data Rate to 6-57600




Click Write – Wait for Completion Indication



Repeat for remain Xbee





Backup