PDMS - Thickness vs RPM Fit function: thickness = p / RPM

