January 12, 2022

focus:

TeleOp Test

summary:

Drives forward and backwards. Issues with negatives. Think its a bevel drive issue. Also re wired and documented and color coded.

challenges:

issues with negatives

next steps:

fix bevel drive issue