

PCB Manufacturing

This document outline the process that I use to create PCBs. I have a separate article that discusses how I design PCBs that may also be of interest to you.

Manufacturing the boards

Generating Gerber Files

Once your design is locked down and you want to send it off to JCCB or PCBWay to be made, you will need to do the following.

1. Get the dimensions of the board
 - Open your electronics design in Fusion360
 - Go to the 2D view of the PCB
 - Activate the Manufacturing tab
 - Select Cam Preview option from the Manufacturing drop down menu
 - Select the Board tab
 - Expand the Board option
 - Note the Width and Height values
2. Generate the Gerber files
 - [Fusion360 - how to generate Gerber files.](#)

Order the board

- I use JLCPCB to manufacture my PCBs.
- You must provide the board dimensions as well as the Gerber files
- Be sure t select the stencil option

Stuffing Boards

Ordering parts using the part list from Fusion360

I purchase components from Digikey

I use this solder paste

I use this flux

I use this flux remover

I wash the boards with water

I used an air compressor to blow the water off

