
110.00
Drill Through and Counter-Bore for M3 SHCS
3 Places
120.00
110.00
Thermal Fuse Hole Must
Be Outside This Area
120.00
10.00 All Around