

THE ULTIMATE RANGE ROVER L322 2004 BUYERS GUIDE

BMW M62 Era | Last of the BMW Years | England Flag Workshop Tested

20 Pages | 100+ Checks | Real Workshop Costs | International Porsche Garage Template



THE INTERNATIONAL PORSCHE GARAGE

■■■■■■■■ Every workshop shot includes England St George's Cross Flag

SHOP TOOLS & PARTS USED IN THIS GUIDE:

<https://ebay.us/m/kke7s5>

[Comment 'L322' on Instagram for your FREE copy of this PDF](#)

PAGE 01 - WHY THE 2004 MATTERS | STANDARD TEMPLATE

HOOK: The cheapest L322 is always the most expensive. WHAT TO WATCH: Final BMW year M62TU B44 + ZF 5HP24, not Jag. Cheap entry £3k-6k. WHY THEY SCRAP: Chain guides, gearbox, air suspension. Our International Porsche Garage template every day: HOOK / WHAT TO WATCH / RED FLAG / PRO TIP / COST IF YOU MISS IT / EBAY LINK. Every video has eBay icon next to Follow Me + England flag.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 02 - VIN, HISTORY & PAPERWORK

HOOK: No history = no deal. WHAT TO WATCH: VIN SALLMAM..., 10th digit=4, service stamps every 10k, 2 keys £350 replace, MOT history advisories, HPI. RED FLAGS: 3+ owners 2yrs flipped, fresh underseal hiding rot. PRO TIP: Call last garage on invoice - 'Would you buy it back?' Pause tells all. COST IF MISS: £2000+ hidden. TOOL: Diagnostic scanner.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 03 - ENGINE M62TU B44 - TIMING CHAIN GUIDES

HOOK: Rattles 2 seconds cold = walk away. WHAT TO WATCH: Chain rattle 0-5s cold = plastic guides in sump, valley pan coolant leak in V (torch), PCV vacuum test oil cap, Vanos knock 1500rpm, mayo cap. RED FLAGS: Overheat history, oil light flicker. PRO TIP: Squeeze top hose cold - rock hard = head gasket. COST: Guides £3500-5500, Valley £800, PCV £180.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 04 - COOLING SYSTEM

HOOK: One overheat warps block. WHAT TO WATCH: Expansion tank crack bottom, viscous fan roar cold then quiet, thermostat stuck open temp never middle, aux pump leak, 20yr hoses. TEST: Idle to temp heater full must stay centre. COST: Full refresh £600-900. ESSENTIAL: Replace cap.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 05 - GEARBOX ZF 5HP24 - THE SCRAREASON

HOOK: Reason 90% of 2004s scrapped. WHAT TO WATCH: 2-3 flare light throttle, shudder 35-45mph converter, harsh downshift, Failsafe low voltage or dying box, oil red not brown. RED FLAGS: Fresh oil old box masking, 'just needs reset'. PRO TIP: 20min mixed drive + 10 stops 30-0 any thump valve body. COST: Rebuild £3500-4500.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 06 - DRIVETRAIN & FRONT DIFF

WHAT TO WATCH: Front diff whine overrun 50-70mph £800 common, transfer chain slap tight turns, prop centre bearing vibration 60mph, CV click full lock. TEST: Full lock circles both ways listen. COST: Front diff £600-1000, Transfer chain £400, Bearing £250.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 07 - AIR SUSPENSION

HOOK: 'Air Suspension Inactive' = £1000 min. WHAT TO WATCH: Sag overnight corner = bag leak, compressor runs constantly worn+dryer, height sensors plastic arm snapped corrosion, relay burned. PRO TIP: Cycle Off-road>Normal>Access should rise <30s each. RED FLAG: Coils fitted devalued 30% bypass switch. COST: Compressor £450, Bag £200/corner, Sensor £120.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 08 - CHASSIS & SUBFRAME RUST

WHAT TO WATCH: Front subframe mounts rust MOT fail, rear subframe above exhaust, air tank cradle, brake pipes along chassis, lower arms bushes torn. CHECK: Torch+phone behind front wheels subframe. COST: Subframe repair £400-800, Arms £200/side, Pipes £250.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 09 - ELECTRONICS & WATER - BECM FLOOD

HOOK: Sunroof drains flood electrics kill car. WHAT TO WATCH: Battery drain >50mA BECM not sleeping, steering column dead, door locks bouncing latch, fuel flap, MK3 black screen radio no sound, water boot = rear drains behind bumper blocked. PRO TIP: Pull boot carpet check spare wheel well + BECM condensation. COST: BECM £800+, Latch £120.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 10 - INTERIOR & EVERY BUTTON

WHAT TO WATCH: Heated screens front+rear elements, heated seats high/low both, AC cold compressor clutch, all windows sunroof, seat memory steering sync, dash pixels missing lines cluster. PRO TIP: Every button £80-200 used test all. COST: Cluster £300, Heater pack £250.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 11 - BODY RUST - INSIDE OUT

HOOK: Rot from inside out. WHAT TO WATCH: Upper/lower tailgate seam inside open, rear arch inside lip finger rough=rust, front inner wings behind liner torch, boot floor under spare lift, scuttle ECU box leaks, sills plastic covers. RED FLAGS: Fresh paint tailgate filler arches underseal on exhaust. COST: Tailgate £800, Arches £600/side, Sills £500.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 12 - BRAKES & HUBS

WHAT TO WATCH: Brembo judder 60mph warped discs, handbrake manual drum in disc seizes, ABS light hub sensor, pipes corroded MOT, bearings drone speed. COST: Discs+pads £400-600, Bearings £200/corner, Shoes £150.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 13 - TEST DRIVE - 15MIN SAVES £5000

PROTOCOL: 1 Cold start bonnet up listen 0-10s chain 2 Dash self-test OFF 3 All heights time 4 Every button windows sunroof heated screens/seats mirrors column 5 Drive 0-30 gentle 30-60 full 60-0 brake 30-0 x10 slow 6 60mph cruise vibration prop 7 Full lock circles whine/click 8 Scan IIDTool screenshot. TOOL: IIDTool.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 14 - NEGOTIATION - USE FAULTS AS WEAPON

No history 30% off asking, Chain rattle walk or £4000 off, Gearbox flare £3000 off, Air inactive £1000 off, Rust £500/panel off, Water boot £800 off. SCRIPT: 'I've inspected few L322s needs £X make right cash at £Y diagnostic report.' Never excitement always 2 others to see.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 15 - IF YOU BUY - DAY 1 SERVICES

Immediate: 1 Oil+filter 5W30 LL04 Mahle 2 Coolant flush new cap tank if cloudy 3 Gearbox ZF filter Lifeguard 5 oil 4 Diff+transfer oils 5 Clear sunroof drains curtain wire+air 6 New battery AGM 019 100Ah 7 Full scan clear re-scan 50miles. COST £600-800 DIY £1200 garage.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 16 - REAL COST TABLE

TABLE: Chain guides DIY £1200 Garage £4500 | Gearbox Rebuild - £4000 | Air Full DIY £800 Garage £1800 | Rust - £1500-3000 | Cooling DIY £350 Garage £800 | Brakes DIY £400 Garage £700. Budget £1500/yr good one £3000/yr cheap one.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 17 - 35 POINT CHECKLIST PRINTABLE

■ Cold rattle ■ Valley leak ■ PCV vacuum ■ Coolant level/colour ■ Oil mayo ■ Tank crack ■ Fan roar ■ 2-3 flare ■ Converter shudder ■ Failsafe ■ Diff whine ■ Transfer chain ■ Prop vibration ■ Sag overnight ■ Compressor time ■ Heights work ■ Sensors ■ Subframe rust ■ Pipes ■ Arms ■ Battery drain ■ Column ■ Locks ■ Water boot ■ Drains ■ Heated screens/seats ■ AC ■ Windows ■ Pixels ■ Nav ■ Tailgate rust ■ Arches lip ■ Inner wings ■ Boot floor ■ Sills. Download printable.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 18 - EBAY STORE - WHAT WE USE - ICON ON EVERY PAGE

DIAGNOSTICS: IIDTool BT AllComms Foxwell. ENGINE: Timing kit M62 valley pan PCV Vanos seals. GEARBOX: ZF filter + Lifeguard 5 oil front diff bearings. SUSPENSION: Dunlop bags AMK compressor sensors valve block. RUST: Tailgate panels arch liners brake pipes. ALL TESTED in England flag workshop. Click icon or link <https://ebay.us/m/kke7s5> Supports garage same price.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**

PAGE 19-20 - NEXT STEPS - COMMENT L322 FUNNEL

HOW TO GET PDF: 1 Comment L322 on Instagram reel 2 Follow @theinternationalp0rsche 3 Check DMs auto-send this PDF with eBay icon. WANT US TO FIND ONE? £199 video inspection with guide + live video + England flag workshop. JOIN: YouTube The International Porsche Garage | IG @theinternationalp0rsche | eBay Store <https://ebay.us/m/kke7s5> - eBay icon Follow Me on all 7 videos. Built in British workshop England flag flying every check real world not theory. Thank you - Hardman PK Palm Coast FL.

■ **eBay Store:** <https://ebay.us/m/kke7s5> - eBay Icon Follow Me on all videos | **eBay Icon on video - Follow Me**