

Tapeout		
	Testing	Validation
I2C	Sensor Module. Pins: <ul style="list-style-type: none">• Vdd (3.3 V/5 V)• GND• SCL• SDA	Read from real device. C code to validate. Oscilloscope/logic analyzer.
UART	Sensor Module. Not USB. Pins: <ul style="list-style-type: none">• Vdd (3.3 V/5 V)• GND• TX• RX	Read from real device. C code to validate. Oscilloscope/logic analyzer.
ADC		
MATH	Add Subtract Multiply Divide Sin	
DOUBLE PENDULUM	Hard-coded numbers.	C code to validate.
PRNG	Hard-coded numbers.	C code to validate.