
8-ASK actual TX encoded symbols
Before RRC shaping; normalized RMS symbol amplitude = 1
Quadrature / RMS symbol amplitude
In-phase / RMS symbol amplitude
1.5
1.0
0.5
0.0
−0.5
−1.0
−1.5
TX encoded symbols
5% RMS-radius guide
Ideal symbol positions