
QPSK actual TX encoded symbols
Before RRC shaping; normalized RMS symbol amplitude = 1
Quadrature / RMS symbol amplitude
In-phase / RMS symbol amplitude
1.00
0.75
0.50
0.25
0.00
−0.25
−0.50
−0.75
−1.00
TX encoded symbols
5% RMS-radius guide
Ideal symbol positions