

Degradation cost [k€]

LPSP [%]

200

150

100

50

0

0

5

10

15

20

25

30

Ideal

RB2(SoH)

RB2

RB1

100-0

SoC1

75-25

50-50

0-100

25-75

SoC06

