

Process sequence**Slat actuation power control unit**

Interactive replacement process

Object code	DMC-A350X-A-27-81-00-00A-258A-A	Issue	001-00 (new)
Issue date	2026-05-26	Language	en-GB
Responsible partner	AIRBUS S.A.S. (U8025)	Originator	AIRBUS S.A.S. — Technical Data Toulouse (U8025)
Security	01 — Unclassified	Quality assurance	Unverified
Applicability	A350X-900 and A350X-1000, all aircraft		

This process drives a technician through the replacement of a slat actuation power control unit on an electronic device. The printed form below gives the same sequence with the branches written out, for use when no device is available.

Process sequence**NODE 1 — ENTRY**

1. Confirm the reason for the removal: scheduled replacement, fault message, or accomplishment of service bulletin A350X-27-1042.

OUTCOME	NEXT
Fault message	Go to node 2
Scheduled or service bulletin	Go to node 3

NODE 2 — ISOLATE

1. Do the fault isolation procedure for the reported message before you remove the unit. A unit that is removed without fault isolation is charged to the operator if the shop finds no fault.

OUTCOME	NEXT
Fault confirmed on the unit	Go to node 3
Fault elsewhere	End of process

NODE 3 — REMOVE

1. Do the removal procedure. Record the serial number of the unit that is removed and the total flight hours of the aircraft.

OUTCOME	NEXT
Removal complete	Go to node 4

Process sequence

NODE 4 — INSTALL

1. Do the installation procedure with the replacement unit, then complete the post-installation check list.

OUTCOME	NEXT
All check list items signed	Go to node 5
An item cannot be signed	Go to node 4

NODE 5 — CLOSE

1. Close the aircraft, make the technical log entry and report the replacement through the customer services portal.

OUTCOME	NEXT
Complete	End of process