

Warning repository

A350X

Common information repository

Object code	DMC-A350X-A-00-00-0000-00A-00KA-D	Issue	009-00 (revised)
Issue date	2026-06-30	Language	en-GB
Responsible partner	AIRBUS S.A.S. (U8025)	Originator	AIRBUS S.A.S. — Technical Data Toulouse (U8025)
Security	01 — Unclassified	Quality assurance	Second verification (tabtop)
Applicability	All A350X data modules		

Warning repository

IDENTIFIER	ENTRY
A350X-W-0001	WARNING Make sure that the hydraulic systems are depressurized before you disconnect a hydraulic line. Hydraulic fluid at 206 bar (2988 psi) can cause injury to persons and damage to equipment.
A350X-W-0002	WARNING Make sure that the slat and flap travel areas are clear of persons and equipment before a system test. The surfaces move without a warning when the test is started.
A350X-W-0014	WARNING Do not touch the brake units after a landing until they have cooled. Surface temperatures of more than 300 °C can cause burns.

Caution repository

IDENTIFIER	ENTRY
A350X-C-0007	CAUTION Do not let a line replaceable unit hang on its hydraulic or electrical connections. Damage to the couplings and to the connector shells can occur.
A350X-C-0011	CAUTION Do not use a solvent on a painted surface of the belly fairing. Damage to the protective coating can occur.

Supply repository

IDENTIFIER	ENTRY
A350X-S-02-004	Name: Hydraulic fluid, phosphate ester, type IV Manufacturer code: 81349 Part number: NSA307110
A350X-S-19-003	Name: Lockwire, corrosion resistant steel, 0.8 mm Manufacturer code: 81349 Part number: NSA935403-08

Tool repository

Tool repository

IDENTIFIER	ENTRY
A350X-T-27-001	Name: Sling, power control unit handling Manufacturer code: U8025 Part number: 98D27814500000
A350X-T-45-002	Name: Portable maintenance access terminal Manufacturer code: U8025 Part number: 98D45111000000