

Condition types

A350X

Conditions cross-reference table

Object code	DMC-A350X-A-00-00-0000-00A-00YA-D	Issue	008-00 (revised)
Issue date	2026-07-06	Language	en-GB
Responsible partner	AIRBUS S.A.S. (U8025)	Originator	AIRBUS S.A.S. — Data Management (U8025)
Security	02 — Restricted	Quality assurance	First verification (tabtop)
Applicability	All A350X aircraft		

Condition types

IDENTIFIER	NAME	TYPE	PERMITTED VALUES
ct-mod	Modification An engineering modification embodied in production or in service.		embodied; notEmbodied
ct-sb	Service bulletin A service bulletin accomplished in service.		accomplished; notAccomplished
ct-state	Operational state A state of the aircraft while the task is done.		onGround; inFlight

Conditions

IDENTIFIER	TYPE	CONDITION
mod27-8104	ct-mod	Modification 27-8104 Slat runaway isolation logic changed to isolate one motor only.
mod27-8117	ct-mod	Modification 27-8117 Sealed feedback position pick-off units installed on the power control unit.
sb27-1042	ct-sb	Service bulletin A350X-27-1042 In-service replacement of the feedback position pick-off units, which embodies modification 27-8117.
st-ground	ct-state	Aircraft on the ground The aircraft is on the ground with the parking brake set.