Sparkline 6		KAIZEN - NEW	KAIZEN - NEW FIXTURE					
		Dept: Quality		Kaizen No.:				
Cell No.: - 01	SIDE DICKY	Machine : - SIDE DICKY Process / Stage : SIDE DICKY			Operation :	S	D	
Kaizen Theme:		Idea: SIDE DICKY NEW REFURSBISHMENT FIXTURE						
Process and Product I	mprovement							
Present status:		COUNTERMEASURE IN PICTORIAL:		KAIZEN Start		14-01	-2018	
1) Side dicky new Refurbishment fixture		reSIDE DICKY FIXTURE						
				KAIZEN	Finish	15-01	-2018	
			Team I	Members:				
			1-R.Pa	1-R.Parthiban				
		¥	2-Nilmani					
		Y						
			Benefit	Benefits:				
			1-Dra	1-Drawing dimension maintain ,clamping condition OK				
			2-Cus	tomer con	nplaints can be	avoided		
		Welding visual stand						
					KAIZEN SUS	TENANCE :		
Why Why Analysis:		Countermeasure & Results:	What to	What to do :				
W1. To Avoid the dimension issue		product improved	Irrevers	Irreversible Kaizen				
W2 .To avoid the customer complaint		product improved						
		Result:						
Root Cause :		1-Welding after job not shringage	How to d	How to do :				
				Scope & Plan for Horizontal Deployment				
		2-100% dimension ok	Sr no	Model	Target	Responsibility	Status	
Registration no. & Date :	04-01-20		Si no	iviouel	Date	responsibility	Status	
	Parthiban			welding	14.01.2012	Douthiban D	samulat -	
Registered by : Manager's Sign :	Sai krishna		1	area	14-01-2018	Parthiban R	complete	