Sparkline ©		KAIZEN																	
		Dept: Quality				Kaizen No.:SEPL/KAIZEI													
Cell No.: - 01	Cell Name:	-9T UFA DOCKING FIXTURE	Machine : -DOCKING Process / Stage : DOCKING AND PART FIXING					Operation :	DOC										
Kaizen Theme:			Idea: To control the position of cross member in reverse direction .																
Process and Prod	uct Improvem	ent																	
Present status:			COUNTERMEASURE IN PICTORIAL:				KAIZE	N Ctt	24.05										
	position checked visually		BEFORE		AFTER	KAIZEN Start		24-05											
,,		· · · · · · · · · · · · · · · · · · ·	The state of the s				KAIZEI	N Finish	25-05										
						Team Members: 1-R.Parthiban 2-kannan													
															Benefits; 1-Cross member position can be ensured				
		N- N	1-Brad		Brackets orientation can be ensured														
					Erection bracket near and tube bottom side		2-Customer complaints can be avoided												
			Cross member position is visually checked Stoper has been provided to ensure the cross																
			member position		KAIZEN SUSTENANCE :														
Why Why Analysis:			Countermeasure & Results:				What to do:												
W1. To Avoid the Fitment issue			Time can be reduced and customer complaint can be avoided.				Irreversible Kaizen												
W2 .To avoid the customer complaint		Time can be reduced and customer complaint can be avoided.																	
			Result:																
Root Cause :		1-Manual error can be avoided.			How to do:														
					Scope & Plan for Horizontal Deployme														
			O Time of inspection can be well-read	•		Cn. 7	NA1 -1	Target	Deenersikir										
Registration no. & Date : 28-02-2018			2-Time of inspection can be reduced.			Sr no	Model	Date	Responsibility										

R.Parthiban

Sai krishna

Registered by : Manager's Sign : 9T UFA

all

models

25-05-2018

1

mohan babu

R.Parthiban

alaguraja

1/002 KING -2018 -2018 Status

completed