

CMI-TECO:

1. Did not provide Shift Energy Management on there Transmission.

Shift Energy Management provides better engine/transmission integration to optimize the entire driveline system. The result is faster, smoother, more consistent shift quality, increased powertrain durability, improved performance And An overall more efficient vehicle operation leading to greater fuel economy.

2. Did not provide correct driveline that was specified. Specifications called for A minimum of An 1810 And A 1760 was bid. This has to do with size And strength of drive shaft.

3. Warranty for engine was specified to be 3years/100,000 miles or 8,000 hours And this Also included After treatment.

CMI-TECO only bid 60 months/100,000 miles for After treatment And no extended warranty on engine.