AIM:

To construct the given isometric mechanical component using Autodesk Fusion 360.

REQUIREMENTS:

1. Autodesk Fusion 360


2. Computer with supported operating system

3. Mouse or touchpad


4. Units set to millimeters (mm)

PROCEDURE:


Step 1: Open Fusion 360, create a new design, and set units to millimeters, Select Create Sketch on the XY plane.




Step 2: Draw the rectangular base footprint using the 100 mm overall length and the 50 mm dimension shown for the block. Confirm the orientation of the dimensions before finishing the sketch and extrude with the distance 30 mm.



Step 3: Select the front vertical face and create a sketch. Draw a circle of diameter Ø50 mm. Position its centre as shown in the reference drawing.





Step 4: Finish the sketch, select the circular profile, and use Extrude to create the projecting cylinder. A 20 mm projection appears to be indicated; verify the dimension arrow in the original drawing before entering it. Use Join if it meets the base.




Step 5: Select the top view and place a 10x10 mm square on top and place a circle of diameter 20 mm (about 0.79 in).


Both should be with the distance mentioned in the image and extrude the square and circle by 5mm (about 0.2 in) distance.







Step 6: select the back view and place a 30x10 mm rectangle and the distance between the edge and rectangle edge is 35mm. Extrude by 20mm.





Step 7: Draw a line joining the 30x10 mm rectangle and 100x60 mm and extrude it by 30mm.






RESULT:

The given isometric mechanical component was modelled in Autodesk Fusion 360 using the dimensions and geometric features indicated in the reference drawing.

OUTPUT:


30
10
100
60
10
30
20
10
10
15
10
15
20
Ø20
Theshwin P S 03-11-2026
activity 2.2 drawing
1/1