Ex.No.-1.1-Design and draft the given 2D Sketches in modelling software

AIM:


To sketch the given drawing with dimensions using fusion 360 tool

REQUIREMENTS:


1) Autodesk fusion 360
2) Windows 10
3) 16 GB of RAM (integrated graphics recommend 2 GB or more)
4) 2.5 Mbps or faster download: 500 kbps or faster upload

PROCEDURE:


1) Open new file and then select part design and unit system in millimeter and click create new.




2) Select the create sketch icon




3) Select the plane for sketching.




4)select the sketching feature circle and just draw the one side of measurement using appropriate dimension used in the image.




5)select the sketch dimension and adjust the distance between the circles using the dimensions




6)Now add the bottom circle according to the measurement.




7)Take a 66 and center point of 40 diameter circle and take 128 diameter circle and tangent it with it 32 diameter circle and 66 diameter circle.take 40 diameter circle and tangent with 66 and 14 diameter circle.




8) Take 20 diameter circle and tangent with 66 diameter circle and 20 diameter circle, now take 40 diameter circle and tangent with 66 diameter and 20 diamter circle present at the bottom





9)Now select the trim tool and trim according to the image.






10)Now select the line tool and draw a line on the y axis in middle.



SOLID
SURFACE
MESH
SHEET METAL
DESIGN
CREATE
MODIFY
BROWSER
(Unsaved)
Document Settings
Units: mm, g




11)select the mirror tool and select the objects that needs to be mirrored and select the line and select the line that we drawn using the line tool and mirror.









12)take a 12 diameter circle and place it between the 40 diameter circle .





13)select create and select the circular pattern tool and select the 12 diameter circle and the center point of 40 diameter circle and enter the count to six and enter ok.


CREATE
MODIFY
Line L
Midpoint Line
Rectangle
Circle
Arc
Polygon
Ellipse
Slot
Spline
Conic Curve
Point
Text
Mirror
Circular Pattern
Rectangular Pattern
Project / Include
Sketch Dimension D
Circumscribed Polygon
Inscribed Polygon
Edge Polygon
-150
-100
-50
26.00




14) Now trim according to the image and then trim the line we drawn to mirror in the y-axis.



Ø20.00
Ø32.00
50
95.00
Ø12.00
Ø40.00
Ø66.00
26.00
47.00
50.00





15) select the finish sketch icon and select the extrude button

And select the object for three dimensional image and enter the measurement for the object. Create the drawing.





File
DESIGN
SOLID
SURFACE
MESH
SHEET METAL
PLASTIC
CREATE
BROWSER
(Unsaved)
Document Settings
Units: mm, g
Part Design
Named Views
Origin
Sketches



EXTRUDE
Type
Profiles
Select
Start
Profile Plane
Direction
One Side
Extent Type
Distance
Operation
New Body
OK
Cancel


RIGHT
EXTRUDE
Type
Profiles
1 selected
Start
Profile Plane
Direction
One Side
Extent Type
Distance
Distance
20 mm
Taper Angle
0.0 deg
Operation
New Body
OK
Cancel
20.00
20 mm

SKETCHS:



RESULT:


PIVOT