696-360

NEW ZEALAND

DECIMAL CURRENCY PROGRAM

PLANT MANAGERS MEETING

SEPT. 19th - 23rd 1966

AGENDA

1. INTRODUCTION

Outline of Programme

- Job Description
- Ages of Conversion
- Registrations /
- Pre-Conversion) Including quantities
- Post-Conversion) and daily thruput.
- Plants Central Parts
- Transport V
- Conversion F4000 and F600
- Full Conversion Stock Machines
- Loan Machines) Bank

) Commercial ·

- Field Service Responsibilities and transport.
- Field Installation
- Production Scheduling

Comporary Conversion Device

Requirements

Conversion Space

- Ready Room
- Lunch Room etc.
- Film
- Equipment Required for Plant

R.Born (a) To be organized by Head Office (b) " " Plant Manager

- Visit to Philips Electrical
- Plant Planning
- Leasehold Improvements and Procedures · and

2. PLANTS

Chours of work.

3. STAFF

- . Numbers Required
- . When to be Bought into Plants
- . Advertising Approach
- . When to Commence Advertising
- . Type of Staff Required
- . Methods of Obtaining Staff
- . Interviewing -
- . Tests and Evaluation

· Pay Scales

- . Industrial Disputes
- . When to Commence Employment
- . Other Burroughs Staff

· Cleaners · Year lady /

4. CONVERTOR TRAINING

- Numbers Required and Times of Each School
- . Philosophy of Training
- . Amount of Orientation on Job Training
- . Training Plans for Each Group
 - . Aids for Training
 - . Literature and Training Material
- . Tools

5. METHODS OF CONVERSION

Clathed end catargony. B machines.