## Burroughs

3

BURROUGHS, LIMITED

DECIMAL CONVERSION PLANT,
3rd FLOOR, JOHN CHAMBERS BLDG,
Cnr JERVOIS QUAY & CABLE STREET,
WELLINGTON, C. I.

P.O. BOX 318
WELLINGTON
FELEPHONE: 52214

17th July, 1967.

Effective immediately the following assignments have been allocated

## CONVERSION FLOOR

Series P

GROUP LEADER Ken Melville

INSPECTOR Ray Burley

Series P4, P6, C & J

ALL PLANT PERSONNEL:

GROUP LEADER David Law

INSPECTOR C David Austin

INSPECTOR J Mike Day

Series F

GROUP LEADER George Micallef

INSPECTOR Bob Eno

INSPECTOR Colin Herringe

TEST AREA

HEAD TESTER Christine Fosdyke

The duties of these people are defined below. GROUP LEADER

In the absence of the group supervisor the group leader will allocate machines, issue kits and collect and check time sheets, plus general assistance.

Trouble shooting problems on machines that occur within his group and inspection of completed sections.

Supervising work flow in the test area to ensure outgoing loads are not delayed by untested machines.

W.J. FRYER, PLANT MANAGER.