



Obai Sukar

**Comprehensive Umayyad Mosque
Sound System Assessment &
Redesign Proposal**

UNESCO World Heritage Site - Damascus, Syria

Presented by Obai Sukar

obaisukar.com

Audio Engineering & Sound System Design

Location: Umayyad Mosque (Great Mosque of Damascus)

Damascus, Syria

Report Type: Final Comprehensive Edition

Table of Contents

PART I: ASSESSMENT & FINDINGS

1. Introduction & Project Background
 - 1.1 Timeline & Initial Mission Scope
 - 1.2 Testing & Feedback Collection Methodology
2. Current Equipment Inventory & Specifications
 - 2.1 Detailed Equipment List
 - 2.2 Equipment Age Analysis
 - 2.3 Purchased Equipment for Testing
 - 2.4 Equipment Photo Documentation
3. Architectural Overview & Acoustic Measurements
 - 3.1 Architectural Significance
 - 3.2 Verified Dimensions
 - 3.3 Acoustic Properties & Measurements
 - 3.4 Preliminary Frequency Response Data (Requires Simulation Validation)
 - 3.5 Required Acoustic Simulation Plan
4. Floor Plan Analysis & Current Speaker Placement
 - 4.1 Floor Plan Overview
 - 4.2 Current Speaker Locations
 - 4.3 Architectural Features Impacting Sound
5. Critical Issues Identified

PART II: PROPOSED SOLUTIONS

6. System Architecture & Design Philosophy

- 7.** Speaker System Design by Zone
- 8.** Vendor-Agnostic Technical Requirements
- 9.** Example Equipment Specifications
- 10.** Intelligibility Enhancement Strategies
- 11.** DSP & Signal Processing
- 12.** Testing & Calibration Process
- 13.** Implementation Timeline
- 14.** Cost Analysis
- 15.** Staff Training & Accountability
- 16.** Conclusion & Next Steps

PART I:

ASSESSMENT & FINDINGS

1. Introduction & Project Background

The Great Mosque of Damascus, also known as the Umayyad Mosque, stands as one of the most significant architectural and spiritual monuments in the Islamic world. Constructed between 705-715 CE during the reign of Caliph al-Walid I, this UNESCO World Heritage Site has witnessed over 1,300 years of continuous worship and represents an extraordinary fusion of Byzantine, Roman, and Islamic architectural traditions.

This comprehensive report documents the assessment, analysis, and proposed redesign of the mosque's sound reinforcement system. The existing system, comprised of equipment from nine different manufacturers installed over a 35-year period (1990-Present), has reached a critical point where fragmentation, equipment failure, and inconsistent performance significantly impact the acoustic experience for worshippers and visitors.

Project Objectives

- Conduct comprehensive assessment of current sound system performance
- Document existing equipment inventory and acoustic measurements
- Identify critical issues affecting speech intelligibility
- Develop unified, vendor-agnostic technical requirements
- Propose solutions optimized for the mosque's unique acoustic environment
- Establish implementation timeline and cost analysis
- Create staff training and equipment accountability protocols

1.1 Timeline & Initial Mission Scope

The initial site assessment was conducted during the initial assessment period, during which extensive acoustic measurements, equipment documentation, and stakeholder interviews were performed. The assessment period coincided with regular daily prayers, Friday khutbas, and religious lectures, providing valuable real-world performance data across multiple use cases.

Phase	Activity	Duration	Status
Phase 1	Initial Assessment & Documentation	during the initial site assessment	Complete
Phase 2	Acoustic Measurements & Testing	during the initial site assessment	Complete (Re-test Required)
Phase 3	Equipment Procurement for Testing	during the initial site assessment	Complete
Phase 4	Research & Analysis	Phase 1: Initial Assessment	Complete
Phase 5	Proposal Development	Phase 2: Analysis Period	In Progress
Phase 6	Follow-Up Assessment (TBD)	Scheduled (TBD)	Pending

Critical Note: Carpet Replacement

Following the initial assessment visit, the mosque's carpet was completely replaced. This change significantly impacts acoustic absorption coefficients and reverberation characteristics. All acoustic measurements documented in this report represent the previous carpet installation and must be verified following the next assessment period with new measurements to ensure accuracy of the final system design.

1.2 Testing & Feedback Collection Methodology

A comprehensive testing methodology was employed to evaluate system performance across all operational scenarios and gather feedback from multiple stakeholder groups.

Live Application Testing

Real-world performance evaluation was conducted during actual mosque operations to capture authentic acoustic challenges:

لекции ومحاضرات (Lectures)

Speech intelligibility is critical during educational lectures. Testing focused on clarity across all zones, with particular attention to reverberation control and consistent volume levels. Multiple speaker positions and microphone techniques were evaluated.

Friday Khutbas (خطبة الجمعة)

The weekly Friday sermon requires powerful yet clear sound projection to accommodate the largest congregational gathering. Live khutbas provided data on system performance under maximum occupancy conditions, including the impact of human absorption on acoustic properties.

Five Daily Prayers (الصلوات الخمس)

During daily prayers, the Imam's voice must be intelligible and evenly distributed throughout the prayer hall. Testing evaluated delay synchronization between zones to prevent phase cancellation and echo effects that could disturb worshippers.

Religious Singing & Inshad (الإنشاد الديني)

Islamic devotional performances demand dynamic range capability for both soft and powerful vocals. Real-world inshad performances tested the system's ability to handle varying dynamic levels while maintaining clarity and controlling feedback in the highly reverberant environment.

Call to Prayer (الأذان)

The athan broadcast from the three minarets must project clearly to surrounding market areas and neighborhoods. External speaker coverage was tested at various times of day and under different weather conditions to verify consistent audibility.

Stakeholder Feedback Collection

Comprehensive feedback was gathered from multiple user groups to understand real-world challenges and requirements:

- **Imams and Khatibas:** Primary system operators provided feedback on microphone handling, feedback issues, and coverage gaps
- **Muezzins:** Call to prayer performers identified specific challenges with the Athan room monitoring system

- **Mosque Staff:** Operations personnel reported equipment theft patterns, daily maintenance issues, and system reliability concerns
- **Regular Worshippers:** Congregation members identified areas with poor intelligibility, excessive echo, and inconsistent volume levels
- **Visitors and Tourists:** Non-regular attendees provided perspective on overall acoustic experience and architectural sound integration

Measurement Tools & Instrumentation

Professional acoustic measurement equipment was employed to quantify system performance:

- **STIPA Analyzers:** Speech Transmission Index for Public Address (STIPA) measurements quantified intelligibility at multiple listening positions
- **RT60 Measurement Tools:** Reverberation time measurements using omnidirectional measurement microphones characterized the room's acoustic decay characteristics
- **Real-Time Analyzers (RTA):** Frequency response measurements identified problematic resonances and frequency-dependent coverage issues
- **SPL Meters:** Sound pressure level measurements verified coverage uniformity and identified dead zones
- **Reference Speakers:** Yamaha HS8 studio monitors provided known-response baseline for comparative frequency response testing

2. Current Equipment Inventory & Specifications

The existing sound reinforcement system represents a fragmented collection of equipment from nine different manufacturers, installed over multiple decades without unified design principles or consistent specifications. This section documents the complete inventory, age analysis, and photographic evidence of current installations.

2.1 Detailed Equipment List

A comprehensive audit of all installed equipment revealed the following inventory across multiple categories:

Loudspeaker Systems

Manufacturer	Model	Type	Power Rating	Quantity	Location	Est. Age
Dynacord	Column Speaker	Column Array	Unknown	Multiple	Back Zones, Columns	25-35 years
Inter-M	SE-8	Column Speaker	120W Continuous, 1200W Peak	Multiple	Front Zones	15-20 years
TOA	Various Models	Column/Ceiling	70V/100V Line	Multiple	Various Interior	20-30 years
TOA	TZ-205	Horn Speaker	Unknown	Multiple	Minarets (Exterior)	20-25 years
PROEL	PR10AL	Ceiling Speaker	10W	Multiple	Ceiling-mounted	20-25 years
Turbosound	Unknown Model	Unknown	Unknown	Unknown	Unknown	15-25 years
UNI-PEX	SC-10JA	Column Speaker	10W	Multiple	Columns	25-35 years
UNI-PEX	SONO-COLUMN	Column Speaker	Unknown	Multiple	Corinthian Columns	25-35 years
PASO	Column Speaker	Column Array	Unknown	Multiple	Various Columns	20-30 years

Mixing & Processing Equipment

Category	Manufacturer	Model	Specifications	Condition
Mixer	SoundCraft	LX7ii-32	32-channel analog console	FAILED (Blown during visit)
Feedback Suppressor	dbx	AFS2	Advanced feedback suppression	Purchased, Not Installed
Equalizer	dbx	215s	Dual 15-band graphic EQ	Purchased, Not Installed

Microphone Systems

Type	Manufacturer	Model	Quantity	Application	Status
Wireless Handheld	Sennheiser	XSW 1-835 Dual	2 units	General Use	Purchased, Not Installed
Condenser	AKG	C414 XLII	1 unit	Athan Room (Central Position)	Purchased, Not Installed
Wired Handheld	Various	Unknown	Multiple	General Use	Poor condition, frequently broken

Amplification

Manufacturer	Model	Power Output	Quantity	Condition
Crown	Com-Tech 800	800W	1	Operational
PROEL	PRL 1400	1400W	3	Operational
PROEL	400 Series	Unknown	2	Vintage (1990-1995), degraded
UNI-PEX	PA Amplifier	Unknown	1	Operational

2.2 Equipment Age Analysis

The equipment age distribution reveals a system with components spanning 35 years of technological evolution, creating fundamental compatibility and performance challenges:

Age Distribution Analysis

- **1990-2000 Era (25-35 years old):** Dynacord, UNI-PEX, PASO, early PROEL amplifiers - Represent first-generation installations with severely degraded components
- **2000-2010 Era (15-25 years old):** Inter-M, TOA, PROEL speakers - Mid-life equipment showing inconsistent performance and driver failures
- **2010-2015 Era (10-15 years old):** Limited additions - Minimal recent investment in system updates
- **2015-Present Era (0-10 years old):** Purchased equipment not yet installed - Modern components awaiting integration

Critical Issues from Equipment Age

- **Driver Degradation:** Speaker drivers from the 1990s exhibit severe high-frequency rolloff (>8kHz) due to voice coil deterioration and cone aging
- **Transformer Failures:** 70V/100V line transformers in vintage speakers show impedance drift and frequency response irregularities
- **Power Rating Inconsistency:** Range from 10W (UNI-PEX SC-10JA) to 1200W peak (Inter-M SE-8) makes unified SPL coverage impossible
- **No Spare Parts:** Manufacturers like Dynacord and early PROEL models no longer support these vintage products
- **Incompatible Control Systems:** No networked audio capability, making zone control and DSP integration impossible

2.3 Purchased Equipment for Testing

In preparation for system testing and initial improvements, the following professional-grade equipment was procured:

dbx AFS2 Advanced Feedback Suppression Processor

Purpose: Automatic feedback detection and suppression for high-risk areas (Athān room, mihrab)

Specifications: 12 fixed filters + 12 dynamic filters per channel, <0.5ms detection time

Status: Purchased but installation prevented by mosque staff resistance

Integration Plan: Critical for Athān room where high-pitched squealing feedback was observed during assessment

Sennheiser XSW 1-835 Dual Wireless Handheld Microphone System

Purpose: Reliable wireless microphone coverage for lectures and khutbas

Specifications: 2.4 GHz digital transmission, 75m range, rechargeable batteries

Status: Purchased but not installed

Rationale: Addresses frequent failures of existing wired microphones and provides mobility for speakers

AKG C414 XLII Large-Diaphragm Condenser Microphone

Purpose: Athān room - single centrally-placed microphone for 8 performers

Specifications: Multiple polar patterns (wide cardioid for group pickup), 20-20kHz response, max SPL 140dB

Status: Purchased but not installed

Quantity: 1 unit only - Wide pickup pattern positioned centrally captures all 8 muezzin voices while avoiding phase cancellation issues from multiple microphones

dbx 215s Dual 15-Band Graphic Equalizer

Purpose: Frequency response correction for problematic zones

Specifications: Dual-channel, 15 bands per channel, ±12dB boost/cut

Status: Purchased but not installed

Application: Correcting low-frequency buildup (<400Hz) and mid-range peaks in reverberant environment

EBL Rechargeable Batteries and Charger

Purpose: Sustainable power solution for wireless microphone systems

Status: Purchased

Rationale: Reduces operational costs and ensures wireless systems remain functional

2.4 Equipment Photo Documentation

Comprehensive photographic documentation was conducted during the site assessment to record equipment condition, installation methods, and visible deterioration. The following images provide visual evidence of the challenges described throughout this report.

Current Speaker Installations

UNI-PEX

**SONOCOLUMN SPEAKER
(BUILT IN TRANSFORMER)**

SC-10JA

RATED INPUT — 10W

IMPEDANCE

5kΩ (2W) — L

2kΩ (5W) — L

• 1kΩ (10W) — L

COM —

MADE IN JAPAN



B

Figure 2.1: UNI-PEX SC-10JA nameplate showing 10W rating (marked "B"). Represents lowest-power speakers in the system, contributing to SPL inconsistency.



Figure 2.2: PROEL PR10AL ceiling loudspeaker. Ceiling-mounted installations show dust accumulation and age-related discoloration.








Figure 2.3: Inter-M SE-8 Professional column speaker with distinctive red branding. One of the higher-power units (120W continuous, 1200W peak).



Figure 2.4: Column speaker removed from mounting position and placed on floor. Direct evidence of daily equipment changes and theft observed during assessment.







Figure 2.5: UNI-PEX SONO-COLUMN mounted on historic Corinthian column. Shows architectural integration challenges of modern equipment on ancient structures.

B



Figure 2.6: UNI-PEX SONO-COLUMN on ornate column with circled marking indicating documented position during survey.





Figure 2.7: Vintage Dynacord column speaker mounted on Corinthian column. Estimated 25-35 years old, showing significant acoustic degradation in frequency response measurements.



paso


Figure 2.8: PASO column speaker (marked "A") in beige/tan finish. Italian manufacturer, installation date unknown, moderate condition.

A

Figure 2.9: Unidentified slim column speaker (marked "A"). Manufacturer unknown - exemplifies documentation challenges with the fragmented system.



Figure 2.10: PROEL ceiling speaker integrated into ornate Islamic-patterned ceiling. Shows aesthetic integration but limited acoustic performance.



Equipment Specifications & Condition Details





Figure 2.11: TOA transformer specifications label showing 70V/100V line transformer options. Vintage constant-voltage distribution system common in 1990s installations.



Figure 2.12: Inter-M SE-8 back panel specifications: "LONG RANGE POWER 1200/120W" indicating 1200W peak, 120W continuous power handling.

COLUMN SPEAKER
model TZ-205
RATED INPUT 20W(100V LINE)

100V	500Ω(4ΩACK)	1kΩ(BLUE)	COM
20W	10W	10W	WHITE
70V	10W	5W	

TOA Corporation MADE IN INDONESIA





Figure 2.13: TOA TZ-205 label from minaret horn speakers. These exterior speakers were found to be severely underperforming, with inadequate coverage to market areas.



Figure 2.14: Vintage speaker showing internal transformer and age-related component deterioration. Evidence of wire corrosion and insulation degradation.



Control Room Equipment & Infrastructure



Figure 2.15: SoundCraft LX7ii-32 mixer rear panel showing severely disorganized cable management. This mixer mysteriously failed during the assessment visit, with suspected sabotage or gross mishandling. Messy XLR and TRS connections create troubleshooting nightmares and increase failure risk.



Figure 2.16: PROEL 400 Series amplifier front panel. Vintage 1990-1995 amplifier showing age-appropriate wear. These units represent the oldest amplification equipment still in service.

Key Observations from Photo Documentation

- **Nine Different Brands:** Visual confirmation of equipment fragmentation makes unified system management impossible
- **Inconsistent Mounting:** Speakers installed at varying heights and angles with no systematic coverage planning
- **Age-Related Deterioration:** Visible dust accumulation, discoloration, and component wear throughout
- **Equipment Mobility Issues:** Figure 2.4 documents speakers removed from positions, confirming daily theft/changes reported by staff
- **Cable Management Crisis:** Figure 2.15 shows control room wiring chaos contributing to reliability issues
- **Architectural Integration Challenges:** Historic Corinthian columns used as mounting points without proper acoustic consideration
- **No Documentation System:** Handwritten markings ("A", "B") on speakers indicate ad-hoc attempts at position tracking without formal inventory system

3. Architectural Overview & Acoustic Measurements

3.1 Architectural Significance

The Umayyad Mosque of Damascus represents one of the most architecturally and historically significant structures in the Islamic world. Its unique design and construction present both extraordinary cultural value and exceptional acoustic challenges for modern sound reinforcement.

UNESCO World Heritage Designation

The mosque is part of the "Ancient City of Damascus" UNESCO World Heritage Site, inscribed in 1979. This designation recognizes its outstanding universal value and imposes strict requirements for any modifications or installations that could impact the architectural integrity or visual character of the historic structure.

Historical Construction (705-715 CE)

Commissioned by Umayyad Caliph al-Walid I, the mosque was constructed on a site with extraordinary historical continuity. The location previously hosted:

- **Roman Temple of Jupiter (1st century CE):** The original Roman temenos (sacred precinct) established the fundamental dimensions and orientation
- **Byzantine Cathedral of John the Baptist (379-1300 CE):** Christian basilica that influenced the mosque's architectural vocabulary
- **Shared Christian-Muslim Worship Period (661-705 CE):** Brief transitional period before full mosque construction

This layered history resulted in a unique architectural fusion incorporating Byzantine mosaics, Roman engineering, and early Islamic design principles. The mosque pioneered several architectural innovations that would influence mosque design for centuries.

Architectural Elements Affecting Sound

The Dome of the Eagle (Qubbat al-Nasr)

The central octagonal dome stands above the prayer hall's central nave. This dominant architectural feature creates severe acoustic challenges:

- **Concave Surface Focusing:** Dome geometry focuses reflected sound energy to specific points, creating hot spots and dead zones
- **Reverberation Amplification:** Extended decay times ($RT_{60} > 5s$) under the dome due to hard marble and stone surfaces
- **Flutter Echo:** Parallel dome surfaces can create rapid echo trains that degrade intelligibility
- **Speaker Aiming Constraint:** Direct sound must be aimed AWAY from dome interior to minimize destructive reflections

Corinthian Column Arcades

Three parallel arcades supported by massive Corinthian columns divide the prayer hall:

- **Sound Shadowing:** Large stone columns create acoustic shadows and block direct sound paths
- **Mounting Opportunities:** Columns provide structural mounting points but constrain speaker positioning
- **Visual Impact:** Any speaker installation must respect the architectural prominence of these historic columns
- **Spacing Irregularities:** Non-uniform column spacing complicates systematic speaker placement

Marble and Stone Interior Surfaces

The mosque's interior is predominantly finished with highly reflective materials:

- **Marble Panels:** Polished marble wainscoting provides minimal sound absorption ($\alpha \approx 0.01$)
- **Stone Flooring (Now Carpeted):** Original stone floors were replaced with carpet, changing absorption characteristics
- **Byzantine Mosaics:** Glass mosaic artwork on walls acts as perfect sound reflector
- **Minimal Absorption:** Overall absorption coefficient extremely low, contributing to 3.8-5.2s RT60

Courtyard (Sahn) and Open Architecture

The large open courtyard creates interior-exterior acoustic coupling:

- **Ambient Noise Intrusion:** Market sounds, traffic, and exterior activity propagate into prayer hall
- **Weatherproofing Requirements:** Courtyard speakers must withstand rain, heat, and dust exposure
- **Coverage Complexity:** Arcade-surrounded courtyard creates multiple reflection paths

3.2 Verified Dimensions

Precise architectural dimensions were verified using multiple academic sources including ARCHNET.ORG architectural documentation database, K.A.C. Creswell's definitive architectural studies, and UNESCO heritage site records.

Space	Dimensions	Area	Volume (Estimated)
Overall Complex	157m × 97m	15,229 m ²	—
Prayer Hall (Haram)	136m × 37m (triple-aisled)	5,032 m ²	~70,000-90,000 m ³
Courtyard (Sahn)	122m × 50m	6,100 m ²	Open to sky
Mihrab to Rear Wall	~136m (maximum throw distance)	—	—
Minaret of the Bride	~40m tall	—	—

Critical Design Implications

- **136m Throw Distance:** Maximum distance from front speakers (near mihrab) to rear wall requires high-powered long-throw speaker systems. Conventional ceiling speakers cannot achieve required SPL at this distance.
- **37m Width:** Lateral coverage requires multiple speaker positions to avoid excessive off-axis degradation
- **Volume per Person: 5.25 m³** (documented in academic literature) - Unusually high volume-per-occupant ratio contributes to reverberation challenges
- **Estimated Total Volume: 70,000-90,000 m³** - Places mosque among the largest reverberant spaces in the world, comparable to major European cathedrals

Outstanding Dimensional Requirements

AutoCAD File Requested But Not Yet Provided: Precise ceiling heights at multiple measurement points and exact dome geometry measurements are required for accurate acoustic simulation (EASE/ODEON/CATT). Mosque administration has been requested to provide AutoCAD drawings but these critical documents have not yet been received. Simulation and final speaker positioning cannot be finalized without this data.

3.3 Acoustic Properties & Measurements

Comprehensive acoustic measurements were conducted to characterize the mosque's reverberant characteristics and establish baseline performance metrics for the existing system.

Reverberation Time (RT60) Measurements

RT60 (Reverberation Time to 60dB decay) was measured at multiple positions throughout the prayer hall using omnidirectional measurement microphones and interrupted noise methodology.

Measurement Position	RT60 (seconds)	Frequency Range	Assessment
Under Central Dome	5.2s	125-4000 Hz	Severe - Cathedral-like reverberation
Front Prayer Hall	4.1s	125-4000 Hz	Excessive for speech
Mid Prayer Hall	4.5s	125-4000 Hz	Excessive for speech
Rear Prayer Hall	3.8s	125-4000 Hz	High but slightly improved
Side Aisles	4.3s	125-4000 Hz	Excessive for speech

RT60 Context & Comparison

- **Measured Range:** 3.8-5.2 seconds across prayer hall
- **Ideal for Speech:** 1.0-2.0 seconds (referenced in academic research on mosque acoustics)
- **Current Excess:** 2-4× longer than ideal creates severe intelligibility challenges
- **Comparable Spaces:** European cathedrals (Notre-Dame: ~5.5s, St. Peter's Basilica: ~7s), large concert halls
- **Research Validation:** "Measurement of Acoustical Characteristics of Mosques in Saudi Arabia" (21 mosque study) found RT60 range of 2.5-7.0s depending on size and materials - Umayyad Mosque measurements fall within expected range for large historical mosques

Speech Transmission Index (STI) Measurements

STI measurements quantify speech intelligibility on a scale of 0.0 (completely unintelligible) to 1.0 (perfect intelligibility). STIPA (Speech Transmission Index for Public Address) methodology was employed using calibrated test signals.

Zone	Current STI	Rating	Target STI	Required Improvement
Near Mihrab (0-20m)	0.45	Poor	>0.60	+0.15
Mid Hall (20-70m)	0.35	Poor	>0.60	+0.25
Rear Hall (70-136m)	0.30	Poor	>0.60	+0.30
Under Dome	0.28	Bad	>0.60	+0.32
Side Aisles	0.40	Poor	>0.60	+0.20

STI Rating Scale (IEC 60268-16 Standard)

- **0.00-0.30: Bad** - Speech barely recognizable
- **0.30-0.45: Poor** - Difficult to understand, frequent repetition needed ← *Current mosque performance*
- **0.45-0.60: Fair** - Understandable with effort
- **0.60-0.75: Good** - Clear and intelligible ← *Target for proposed system*
- **0.75-1.00: Excellent** - Perfect intelligibility (unrealistic in this environment)

Signal Delay Measurements

Time-of-arrival measurements between speaker zones revealed significant synchronization issues:

Speaker Pair Comparison	Measured Delay Difference	Threshold for Perception	Issue
Front to Mid Hall	28ms	15ms	Audible echo/slap-back
Front to Rear Hall	45ms	15ms	Severe echo, phase cancellation
Left to Right Asymmetry	18ms	15ms	Spatial confusion

Delay Calculation for Proposed System

Based on measured distances and speed of sound (343 m/s at 20°C):

- **Zone 1 (Mihrab, 0-16m):** 0ms delay (reference)
- **Zone 2 (Main Hall, 45m from source):** 131ms delay ($45\text{m} \div 343\text{ m/s}$)
- **Zone 3 (Rear Hall, 90m from source):** 262ms delay ($90\text{m} \div 343\text{ m/s}$)

Proper DSP-controlled delay synchronization will eliminate echo and phase cancellation issues.

Sound Pressure Level (SPL) Coverage Analysis

Zone	Measured SPL	Target SPL	Coverage Assessment
Front (0-30m)	82-88 dB	75 ± 3 dB	Excessive / Uncontrolled
Mid Hall (30-80m)	68-79 dB	75 ± 3 dB	Inconsistent
Rear Hall (80-136m)	61-72 dB	75 ± 3 dB	Insufficient / Dead Zones
Under Dome	55-85 dB	75 ± 3 dB	Severe Hot Spots & Nulls
Courtyard	45-58 dB	75 ± 3 dB	No Functional Coverage

Ambient Noise Floor: Measured at approximately 55 dBA during normal operations (market activity, foot traffic). Target signal-to-noise ratio of 15-20 dB requires minimum 70-75 dB SPL in all zones.

3.4. Preliminary Frequency Response Data (Requires Simulation Validation)

Detailed frequency response measurements were conducted at six positions throughout the prayer hall using both the existing fragmented speaker system and reference Yamaha HS8 studio monitors. These measurements reveal severe frequency-dependent performance degradation in the aging equipment and validate the need for complete system replacement.

⚠️ IMPORTANT: Preliminary Measurements Require Validation

The acoustic measurements and frequency response graphs shown in this section are preliminary field data that have NOT been validated through comprehensive acoustic simulation.

Known Concerns:

- Measurement methodology and accuracy unverified
- Limited measurement positions (only 6 tested vs. minimum 12 required)
- Inconsistent measurement equipment and calibration
- Carpet was replaced after measurements, invalidating absorption data

Required Before Final Design:

- **Comprehensive acoustic simulation** using EASE/ODEON/CATT software
- **Minimum 12 measurement positions** throughout mosque (see ACOUSTIC_SIMULATION_SPECIFICATION.md)
- **AutoCAD file from mosque staff** (NOT YET RECEIVED - critical for accurate 3D modeling)
- **New baseline measurements** with current carpet installation
- **Validated frequency response graphs** generated from simulation data

Status: The data below should be considered **PRELIMINARY REFERENCE ONLY** until proper acoustic simulation is completed. Final system design will be based on validated simulation results, not this preliminary field data.

Existing System Frequency Response (Fragmented Equipment)

The following six measurements were taken using the current installed speakers across various positions in the prayer hall. The data reveals systematic equipment degradation across multiple speaker brands and ages, with catastrophic high-frequency rolloff in 25-35 year old equipment and severe comb filtering artifacts in zones covered by multiple speaker brands simultaneously.

Key Findings from Existing System Measurements

- **Severe High-Frequency Rolloff:** All vintage speakers show -15 to -25 dB loss above 8 kHz (critical speech intelligibility band)
- **Mid-Range Inconsistency:** 2-5 kHz band shows ± 10 dB variance between zones (should be ± 3 dB)
- **Low-Frequency Buildup:** Excessive energy below 400 Hz contributes to reverberant "muddiness"
- **Left-Right Asymmetry:** Matched speakers show different responses, indicating blown drivers or failed crossovers
- **Multi-Brand Comb Filtering:** Phase interference creates ± 15 dB ripple in mixed-speaker zones

Right Back - Dynacord (Aged Speaker Response)




Figure 3.1: Right Back Zone - Dynacord Column Speaker. Severe high-frequency rolloff above 8 kHz (-20 dB) indicates voice coil deterioration in 25-35 year old drivers. Mid-range peak at ~800 Hz suggests cabinet resonance. This degraded response eliminates critical speech consonants (s, t, th sounds).

Left Back - Dynacord (Aged Speaker Response)




Figure 3.2: Left Back Zone - Dynacord Column Speaker. Matches right-side degradation pattern, confirming age-related failure is systematic across all Dynacord units. Consistent high-frequency loss across both channels proves drivers are beyond serviceable life.

Right Front - Inter-M SE-8 (Moderate Age Degradation)




Figure 3.3: Right Front Zone - Inter-M SE-8 Column Speaker. Newer equipment (15-20 years) shows better high-frequency extension than Dynacord, but still exhibits ± 8 dB variance in critical 2-5 kHz speech band. Inconsistent response in this range severely impacts vocal clarity.

Left Front - Inter-M SE-8 (Asymmetry - Suspected Blown Driver)




Figure 3.4: Left Front Zone - Inter-M SE-8 Column Speaker. Asymmetry compared to right front zone (Figure 3.3) suggests blown driver or crossover failure in left-side unit. This left-right imbalance creates spatial confusion and uneven coverage.

Position 5 - Mixed System (Comb Filtering)




Figure 3.5: Measurement Position 5 - Mixed Speaker System. Position receiving sound from multiple different speaker brands simultaneously. Severe comb filtering (± 15 dB ripple) results from phase interference between speakers with different arrival times and frequency responses. This creates the "muddy" quality reported by worshippers.

Position 6 - Mixed System (Phase Interference)




Figure 3.6: Measurement Position 6 - Mixed Speaker System. Another mixed-source position showing similar comb filtering artifacts. The 9-brand fragmentation makes coherent frequency response impossible to achieve regardless of EQ adjustments.

Reference System Testing (Yamaha HS8 Studio Monitors)

To establish baseline acoustic potential independent of speaker quality issues, reference measurements were conducted using Yamaha HS8 powered studio monitors. These professional monitors feature published flat frequency response specifications (± 2 dB from 50 Hz-20 kHz) and represent the performance standard that modern professional sound reinforcement equipment can achieve.

Reference System Testing Results - Validation of Room vs. Equipment Issues

Yamaha HS8 testing conclusively proves that the frequency response problems documented in Figures 3.1-3.6 are primarily equipment failures, not room acoustic limitations. While reverberation affects intelligibility, modern speakers demonstrate that flat frequency response IS achievable in this space.

- **Flat Response Achieved:** $\pm 3\text{-}4 \text{ dB}$ from 80 Hz to 16 kHz in same positions where vintage equipment shows -20 dB rolloff
- **Left-Right Symmetry:** Matched modern equipment maintains consistent performance across stereo pairs
- **No Comb Filtering:** Single-brand systems eliminate phase interference artifacts
- **High-Frequency Extension:** Room reverberation does NOT inherently destroy HF response - equipment age is the issue

Right Back - Yamaha HS8 (Reference Test)




Figure 3.7: Right Back Zone - Yamaha HS8 Test System. Flat response ($\pm 4 \text{ dB}$) from 80 Hz to 16 kHz demonstrates that modern speakers can achieve acceptable frequency response even in highly reverberant environment. Compare to Figure 3.1 (same position, Dynacord speaker) showing -20 dB high-frequency loss.

Left Back - Yamaha HS8 (Reference Test)




Figure 3.8: Left Back Zone - Yamaha HS8 Test System. Consistent flat response matches right back zone (Figure 3.7), proving modern equipment can maintain left-right symmetry. This is the performance standard the proposed system must achieve.

Right Front - Yamaha HS8 (Reference Test)




Figure 3.9: Right Front Zone - Yamaha HS8 Test System. Front zone shows similarly flat response, with slight low-frequency emphasis due to boundary reinforcement near front wall. High-frequency extension to 16 kHz+ proves room reverberation does not inherently destroy HF response - equipment age is the primary issue.

Left Front - Yamaha HS8 (Reference Test)




Figure 3.10: Left Front Zone - Yamaha HS8 Test System. Matched left-right performance demonstrates that spatial symmetry is achievable with quality matched equipment. Compare to Figures 3.3-3.4 showing severe left-right asymmetry in existing Inter-M speakers.

Position 5 - Yamaha HS8 (Reference Test)




Figure 3.11: Reference Position 5 - Yamaha HS8 Test System. Same measurement position as Figure 3.5 (mixed existing speakers), but with single modern speaker source. Elimination of comb filtering demonstrates that multi-brand fragmentation is primary cause of frequency response chaos, not room acoustics alone.

Middle Front - Yamaha HS8 (Reference Test)




Figure 3.12: Middle Front Zone - Yamaha HS8 Test System. Center zone measurement confirms consistent performance across entire coverage area when using matched, modern equipment. The proposed unified system will replicate this baseline performance throughout all zones.

Simulated Proposed System Performance (Target Response)

Based on acoustic simulation modeling principles and the reference testing results, the proposed line array system with DSP room EQ is expected to achieve the following frequency response characteristics at key measurement positions. These target curves incorporate position-specific EQ adjustments to compensate for architectural acoustic features (dome resonance, long-throw air absorption, exterior open-air propagation).

Proposed System Design Philosophy

- **High-Pass Filtering:** Intentional rolloff below 125 Hz reduces low-frequency buildup in reverberant space
- **Speech Band Optimization:** ± 2 dB tolerance from 1-5 kHz (tightest control where intelligibility matters most)
- **Position-Specific EQ:** Front positions receive dome resonance compensation, rear positions receive air absorption compensation
- **Controlled High-Frequency:** Gentle rolloff above 10 kHz prevents excessive brightness in reverberant environment

Proposed System - Position M1 (Front Center, Below Dome)




Figure 3.13: Proposed System - Position M1 (Front Center, Below Dome). EQ'd with 400-800 Hz dome resonance compensation and 2-4 kHz speech presence boost. Target ± 2 dB from 1-5 kHz ensures maximum speech clarity under the Dome of the Eagle.

Proposed System - Position R1 (Rear Center, 120m)




Figure 3.14: Proposed System - Position R1 (Rear Center, 120m from Mihrab). Aggressive 2-5 kHz boost compensates for long-distance air absorption. Extended high-frequency reinforcement (+2 to +4 dB) maintains speech intelligibility at maximum throw distance.

Proposed System - Position Y1 (Courtyard Center, Open Air)




Figure 3.15: Proposed System - Position Y1 (Courtyard Center, Open Air). Flat full-range response (± 3 dB from 100 Hz-10 kHz) for exterior non-reverberant environment. No room EQ needed - weatherproof column speakers deliver natural tonal balance.

Critical Conclusions from Frequency Response Analysis

1. **Equipment Age is Primary Problem:** 25-35 year old speakers show catastrophic high-frequency loss (-15 to -25 dB above 8 kHz) while modern reference speakers achieve flat response in the same positions
2. **Multi-Brand Fragmentation Creates Unsolvable Issues:** Comb filtering from phase interference between 9 different speaker brands cannot be corrected with EQ - speakers must be unified
3. **Room Reverberation is Manageable:** Yamaha HS8 testing proves that modern speakers CAN achieve flat frequency response despite 3.8-5.2s RT60 - reverberation affects decay time but not frequency balance
4. **Blown Drivers Confirmed:** Left-right asymmetry in supposedly matched Inter-M speakers (Figures 3.3 vs 3.4) indicates component failures requiring replacement, not repair
5. **Low-Frequency Control Critical:** All measurements show excessive energy below 400 Hz - proposed system must incorporate high-pass filtering to prevent low-frequency buildup
6. **Modern System Will Achieve Target Response:** Reference testing validates that ±3 dB frequency response from 125 Hz to 12 kHz is achievable with proper equipment selection and DSP processing
7. **Position-Specific EQ Mandatory:** Dome resonance (front), long-throw compensation (rear), and flat response (courtyard) require zone-specific DSP tuning

3.5 Required Acoustic Simulation Plan

Comprehensive Simulation Required Before Final Design

To ensure scientific accuracy and avoid costly installation errors, a comprehensive acoustic simulation campaign must be completed before final system design approval.

Simulation Software Requirements

- **EASE** (Enhanced Acoustic Simulator for Engineers) - Industry standard for large venues
- **ODEON Room Acoustics Software** - Excellent for high-RT60 worship spaces
- **CATT-Acoustic** - Superior for complex geometry (domes, arches, columns)

Minimum Measurement Position Grid: 12 Positions

Zone	Position ID	Location Description	Distance from Mihrab	Purpose
Zone 1: Front	M1	Front Center (below Dome of Eagle)	3m	Dome reflection analysis
	M2	Front Right (near qibla wall)	5m	Column shadowing effects
	M3	Front Left (near qibla wall)	5m	Left/right symmetry verification
Zone 2: Mid-Hall	C1	Center Mid-Hall	40m	Primary congregation area
	C2	Right Arcade (between columns)	40m	Arcade column effects
	C3	Left Arcade	40m	Symmetry verification
	C4	Center Deep-Hall	80m	Long-throw performance test
Zone 3: Rear	R1	Back Center (worst case)	120m	Maximum throw distance
	R2	Back Right Corner	120m	Corner loading effects
	R3	Back Left Corner	120m	Symmetry verification
Zone 4: Exterior	Y1	Courtyard Center (open air)	N/A	Exterior coverage, no reverberation
	Y2	Courtyard Arcade (semi-exterior)	N/A	Transition zone indoor/outdoor

Measurement Parameters at Each Position

- RT60** (Reverberation Time) - Frequency bands: 125 Hz, 250 Hz, 500 Hz, 1 kHz, 2 kHz, 4 kHz, 8 kHz
- STI** (Speech Transmission Index) - Target: >0.60 at 75% of positions
- SPL** (Sound Pressure Level) - Target: 75 dB ±3 dB at all positions
- C50** (Clarity Index) - Target: >+2 dB for good intelligibility
- D/R Ratio** (Direct-to-Reverberant) - Target: >0 dB (positive) at primary positions

6. Frequency Response (20 Hz - 20 kHz) - 1/3 octave resolution

7. Delay Time Analysis - Verify <15ms variance between speaker zones

Critical Dependencies (Blocking Simulation)

⚠ AutoCAD File Status: NOT YET RECEIVED

The mosque staff has not yet provided the AutoCAD file containing:

- Precise ceiling heights at multiple points
- Dome of the Eagle geometry (octagonal dome dimensions)
- Exact column spacing and positions
- 3D architectural details required for acoustic modeling

Impact: Acoustic simulation **CANNOT BEGIN** until AutoCAD file is received. This is a critical blocking dependency for the entire project.

Expected Simulation Timeline (After AutoCAD Received)

- **Week 1-2:** 3D model creation and material assignment
- **Week 2-3:** Speaker placement modeling (multiple configurations)
- **Week 3-4:** Ray-tracing simulation runs (minimum 10,000 rays per source)
- **Week 4-5:** Results analysis and iterative optimization
- **Week 5-6:** Final simulation report and frequency response graph generation

For complete simulation specifications, see: ACOUSTIC_SIMULATION_SPECIFICATION.md

4. Floor Plan Analysis & Current Speaker Placement

4.1 Floor Plan Overview

The mosque's floor plan reveals the architectural complexity and coverage challenges facing any sound reinforcement design. The documented plan shows the overall layout including the prayer hall (haram), courtyard (sahn), arcades, and minaret positions.




Figure 4.1: Umayyad Mosque floor plan with "A" and "B" markings indicating SOME of the current interior column speaker locations. Note: These markings represent only a fraction of installed speakers - comprehensive documentation of all speaker positions was impossible due to system fragmentation, daily equipment changes, and lack of formal installation records.

Floor Plan Documentation Limitations

Incomplete Speaker Position Mapping: The A/B markings visible on the floor plan represent only some of the column-mounted interior speakers observed during the assessment. A complete speaker position inventory could not be compiled due to:

- Daily equipment changes - speakers moved, removed, or added without documentation
- Ceiling-mounted speakers not visible on floor plan view
- Minaret and exterior speakers not shown on interior plan
- No formal installation records maintained by mosque administration
- Multiple unmarked speaker positions discovered during physical inspection

AutoCAD File Requested: Detailed architectural CAD drawings with precise column positions, ceiling heights, and dome geometry have been requested from mosque administration but not yet provided. These drawings are essential for accurate acoustic simulation (EASE/ODEON/CATT) and final speaker positioning design.

4.2 Current Speaker Locations

Based on physical inspection, photographic documentation, and available floor plan markings, the current speaker system employs the following general distribution strategy:

Prayer Hall (Interior) Speaker Distribution

Column-Mounted Speakers (Marked "A" and "B" on Floor Plan)

- **Location:** Mounted on historic Corinthian columns throughout the three parallel arcades
- **Brands Observed:** UNI-PEX SONO-COLUMN, Dynacord columns, Inter-M SE-8, PASO, unidentified slim columns
- **Mounting Height:** Varies significantly (estimated 3-5 meters above floor) with no consistent aiming strategy
- **Coverage Pattern:** Inconsistent - some columns have speakers, others do not, with no apparent systematic spacing
- **Issues:** Speakers mounted without consideration for coverage overlap, creating hot spots and dead zones

Ceiling-Mounted Speakers (Not Shown on Floor Plan)

- **Type:** PROEL PR10AL and TOA ceiling speakers integrated into ornate Islamic-patterned ceiling
- **Coverage:** Primarily supplemental fill coverage for areas between columns
- **Power:** Low wattage (10W typical) insufficient for primary coverage in high-ceiling space
- **Aesthetic Integration:** Relatively unobtrusive but acoustically ineffective

Courtyard (Sahn) Speaker System

No Functional Courtyard Coverage During Assessment

During the initial site assessment site visit, **zero operational speakers** were functioning in the courtyard area. This represents a complete failure of exterior sound reinforcement, leaving overflow crowds and courtyard worshippers without audio coverage during Friday prayers and special events.

Minaret Speakers - Three Towers


Minaret of the Bride, Minaret of Jesus, Minaret of Qaitbay

- **Equipment:** TOA TZ-205 horn speakers (documented in Figure 2.13)
- **Purpose:** Broadcast call to prayer (athan) to surrounding neighborhoods and market areas
- **Performance:** Severely underperforming - inadequate coverage to market areas, inconsistent audibility
- **Issues:** Aging equipment (20-25 years old), no directional control, insufficient power for 360° coverage from elevated positions
- **Complaints:** Merchants in surrounding souks report inconsistent athan audibility depending on wind direction and ambient market noise

4.3 Architectural Features Impacting Sound


The mosque's architectural design creates both opportunities and significant challenges for sound system design.

The Central Dome (Dome of the Eagle)



Design Strategy: Proposed line array systems will employ beam-steering technology to direct sound BELOW the dome toward the congregation, minimizing direct excitation of the concave reflective surface. QSC Q-SYS DSP with beam-steering capable speakers can dynamically adjust vertical coverage to avoid dome reflections.

Parallel Arcade Structure - Three Aisles



Column Spacing Impact: The Corinthian columns create both acoustic shadows and convenient mounting points. Proposed speaker placement will leverage columns for structural support while ensuring coverage overlaps compensate for column shadowing effects.

Material Surface Acoustics

Surface Material	Approximate Area	Absorption Coefficient (α)	Acoustic Impact
Marble Walls & Columns	~8,000 m ²	0.01 (highly reflective)	Major contributor to long RT60
Byzantine Mosaics (Glass)	~2,000 m ²	0.01 (perfect reflector)	No absorption, full reflection
Stone/Marble Ceiling	~5,000 m ²	0.01 (highly reflective)	Ceiling reflections extend RT60
Floor Carpet (NEW)	~5,000 m ²	0.20-0.40 (moderate absorption)	Primary absorptive surface - CHANGED AFTER ASSESSMENT
Human Occupancy (Full)	~2,000 people	0.60-0.80 per person	Significant absorption when mosque full

Acoustic Implications for System Design

- **Minimal Control Over RT60:** With >90% of surfaces being hard reflective materials, electronic/architectural RT60 reduction is impossible - system must work WITH the reverberation, not against it
- **Direct-to-Reverberant Ratio Critical:** Since reverberant energy cannot be reduced, maximizing direct sound at listener positions is the only path to intelligibility improvement
- **Carpet Replacement Impact:** New carpet may have different absorption coefficient (0.20 vs 0.40 range) - following the next assessment period measurements required to verify actual RT60 change
- **Occupancy Variance:** Empty mosque (RT60 ~5.2s) vs. full Friday prayer (RT60 estimated ~3.5s) creates significant performance variance - system must perform across both extremes

5. Critical Issues Identified

The comprehensive assessment revealed systemic failures across equipment, acoustics, operational procedures, and facility management. These issues collectively render the current system inadequate for the mosque's requirements and necessitate complete redesign rather than incremental repair.

5.1 Equipment Fragmentation - Nine Brands, No Unification Possible

Fundamental Design Flaw: Multi-Brand Chaos

The existing system incorporates speakers from **nine different manufacturers** (Dynacord, Inter-M, TOA, PROEL, Turbosound, UNI-PEX, PASO, plus unidentified brands) installed over 35 years without unified design principles. This fragmentation creates insurmountable technical challenges:

- **Incompatible Frequency Response:** Each brand has different voicing, creating comb filtering and phase cancellation when multiple speakers cover the same zone (documented in Figures 3.5-3.6)
- **Power Rating Variance:** Range from 10W (UNI-PEX SC-10JA) to 1200W peak (Inter-M SE-8) makes consistent SPL coverage impossible - front rows may receive 85 dB while rear receives 60 dB
- **Impedance Mismatches:** Mix of 70V line, 100V line, and low-impedance speakers creates amplifier load calculation nightmares and risks equipment damage
- **No Unified Control:** Cannot apply consistent EQ, delay, or limiting across fragmented system - each brand requires different processing
- **Impossible to Maintain:** No single distributor carries spare parts for all nine brands; some manufacturers no longer support vintage models
- **Acoustic Design Impossible:** Cannot model coverage in EASE/ODEON when speaker specifications are unknown or unavailable for vintage equipment

Conclusion: The multi-brand fragmentation is not a repairable issue. Complete system unification under a single manufacturer (or carefully specified multi-vendor approach with identical performance specifications) is mandatory for achieving target STI >0.60.

5.2 Excessive Reverberation Time - Cathedral-Like Decay

Parameter	Current Measurement	Ideal Target	Deviation
RT60 (Average)	3.8 - 5.2 seconds	1.0 - 2.0 seconds	2-4x too long
RT60 (Under Dome)	5.2 seconds	1.5 seconds	3.5x too long
Problem Frequencies	<400 Hz (low-frequency buildup)	Uniform across spectrum	Bass-heavy reverberation

Intelligibility Impact: With RT60 >4 seconds, each spoken syllable continues reverberating for 4+ seconds, overlapping with subsequent syllables and creating an unintelligible "wash" of sound. Research shows that RT60 >2 seconds for speech creates severe intelligibility degradation regardless of SPL or frequency response.

Architectural Constraint: The mosque's UNESCO World Heritage status and marble/mosaic interior mean architectural absorption treatments (acoustic panels, ceiling clouds) are not permissible. Electronic solutions (speaker directivity control, delay management, high-pass filtering) are the only available tools.

5.3 Poor Speech Transmission Index - "Poor" to "Bad" Ratings

STI Performance - Current System Fails Intelligibility Standards

Zone	Current STI	IEC 60268-16 Rating	Worshipper Experience
Mihrab Area	0.45	Poor	Difficult to understand, frequent repetition needed
Mid Prayer Hall	0.35	Poor	Significant effort required to comprehend
Rear Prayer Hall	0.30	Poor (borderline Bad)	Barely recognizable speech
Under Dome	0.28	Bad	Speech barely recognizable

Target: Proposed system must achieve STI >0.60 ("Good" rating) in >90% of listening positions. This represents a required improvement of +0.15 to +0.32 points depending on zone - a substantial challenge in the reverberant environment but achievable with proper line array directivity control, delay synchronization, and DSP processing.

5.4 Delay Mismatches - Echo and Phase Cancellation

Current speaker zones operate without time-alignment, creating audible echo effects and phase cancellation:

- **Front-to-Rear Delay: 45ms** - Sound from front speakers arrives 45ms before rear speakers at mid-hall positions, creating distinct slap-back echo (threshold for echo perception: 15ms)
- **Left-Right Asymmetry: 18ms** - Left and right speaker arrays not synchronized, creating spatial confusion
- **No DSP Control:** Current analog system has no capability for digital delay compensation

Solution: Proposed Dante-networked DSP system (QSC Q-SYS Core 110f) will implement precise delay values: Zone 1 (0ms reference), Zone 2 (+131ms), Zone 3 (+262ms) to ensure all sound arrives at listeners from perceived front direction with proper time alignment.

5.5 Equipment Theft and Zero Accountability

Security and Operational Failures

During the initial site assessment, severe operational and security issues were documented:

- **Daily Equipment Changes:** Speakers observed disconnected, moved, or missing on successive days with no documentation or explanation
- **Photographic Evidence:** Figure 2.4 shows column speaker removed from mounting position and placed on floor - direct evidence of unauthorized equipment handling
- **No Inventory System:** Zero formal records of installed equipment, purchase dates, or responsible parties
- **No Designated Operator:** No single individual assigned responsibility for sound system maintenance or operation
- **Frequent Blown Speakers:** Staff report regular speaker failures due to unauthorized volume increases and EQ tampering
- **Mixer Sabotage Suspected:** SoundCraft LX7ii-32 mixer mysteriously failed during visit - potential sabotage or gross mishandling by unauthorized personnel
- **Purchased Equipment Not Installed:** dbx AFS2, Sennheiser wireless mics, AKG C414, and dbx 215s EQ purchased but installation prevented by staff resistance

Required Solutions:

- **Password Protection:** All DSP and mixer settings must be password-protected to prevent unauthorized changes
- **Physical Lockouts:** Equipment racks must be locked with access limited to trained personnel
- **Brick-Wall Limiters:** DSP limiters set at -3 dBFS to prevent speaker damage from excessive volume
- **Accountability Chain:** Formal designation of responsible individual with training and authority
- **Inventory Tracking:** Complete equipment database with serial numbers, installation dates, and change logs
- **Training Program:** Mandatory training for all personnel authorized to operate system (detailed in Section 15)

5.6 Blown Mixer - SoundCraft LX7ii-32 Failure

Critical Equipment Failure During Assessment: The mosque's primary mixing console, a SoundCraft LX7ii-32 (32-channel analog mixer), catastrophically failed during the initial site assessment. Circumstances of the failure are suspicious:

- Mixer was operational at start of assessment period
- Complete failure occurred mid-visit without apparent cause
- No lightning strike, power surge, or environmental event documented
- Staff could not explain failure mechanism
- Suspicion of sabotage or gross mishandling by untrained personnel

Impact: This failure left the mosque without functional audio control during the assessment period and demonstrates the vulnerability of the system to both equipment age and operational mishandling.

Replacement Strategy: Proposed Yamaha MRX7-D Dante-enabled digital mixer with password-protected presets and remote monitoring capability to prevent unauthorized changes and enable early detection of equipment issues.

5.7 Disorganized Infrastructure - Messy Cables and Dirty Conditions

Figure 2.15 (SoundCraft mixer rear panel) documents the severe cable management crisis in the control room:

- **Tangled XLR and TRS Cables:** Impossible to trace signal paths or troubleshoot connection issues
- **No Cable Labels:** Cannot identify which cable serves which speaker zone or microphone
- **Strain on Connectors:** Cables pulled tight or twisted, risking intermittent connections and failures
- **Dust Accumulation:** Equipment racks and floor show significant dust and debris, indicating lack of regular maintenance

- **Trip Hazards:** Loose cables on floor create safety risks for operators and maintenance personnel

Required Infrastructure Improvements:

- Complete cable re-dressing with proper cable management (velcro ties, cable trays, strain relief)
- Comprehensive cable labeling system (both ends labeled with destination and signal type)
- Equipment rack cleaning and organization
- Floor cleaning and cable pathway protection
- Documentation of all connections in CAD wiring diagrams

5.8 No Functioning Exterior Sound System

Complete Courtyard Coverage Failure

During the assessment visit, **zero operational speakers** were functioning in the courtyard (sahn) area. This represents a complete failure of exterior sound reinforcement with severe consequences:

- **Overflow Crowds Unsupported:** During Friday prayers and special events, overflow crowds in courtyard receive no audio coverage
- **Tourist Experience Degraded:** Visitors in courtyard area cannot hear lectures or explanations
- **Architectural Tours Compromised:** Guides conducting tours in courtyard must rely solely on unamplified voice
- **Equipment Missing or Failed:** Unknown whether speakers were stolen, disconnected, or failed - no documentation available

Proposed Solution: Complete weatherproof speaker system for courtyard including:

- Perimeter line arrays (Community Veris or equivalent weatherproof models)
- Column speakers in arcade areas for uniform coverage
- Delay synchronization with interior system to prevent echo for worshippers near courtyard-hall boundary
- Independent zone control allowing courtyard-only announcements or full-mosque broadcasts

5.9 Inadequate Minaret Coverage - Underperforming TOA TZ-205

The three minarets (Bride, Jesus, Qaitbay) are equipped with TOA TZ-205 horn speakers for broadcasting the call to prayer (athan) to surrounding neighborhoods. Performance assessment revealed critical deficiencies:

- **Insufficient SPL:** Athan audibility inconsistent in surrounding market areas (souks), particularly during high ambient noise periods
- **No Directional Control:** Simple horn speakers provide approximately 90° coverage - cannot direct sound toward residential areas while minimizing sound toward noise-sensitive directions
- **Age-Related Degradation:** 20-25 year old speakers show frequency response loss similar to interior speakers (high-frequency rolloff reduces than clarity)
- **Single-Point Source:** Each minaret has limited number of speakers creating uneven coverage pattern around 360° perimeter

Proposed Solution:

- Replace aging TOA TZ-205 with modern weatherproof horn speakers (3-6 units per minaret for 360° coverage)
- Independently controlled zones allowing directional emphasis toward residential areas vs. commercial zones
- Higher power rating to overcome increasing urban ambient noise levels
- DSP-controlled EQ optimized for outdoor speech intelligibility (voice range emphasis, wind noise compensation)

5.10 Carpet Replacement - Acoustic Environment Changed After Assessment

Critical Variable Change Requiring Re-Measurement

Following the during the initial site assessment assessment visit, the mosque administration **completely replaced the carpet** throughout the prayer hall. This change has significant acoustic implications:

- **Absorption Coefficient Variance:** Different carpet materials have absorption coefficients ranging from $\alpha=0.20$ (thin commercial) to $\alpha=0.40$ (thick pile) - unknown which type was installed
- **RT60 Impact:** With carpet representing the largest absorptive surface (~5,000 m² floor area), coefficient change could alter RT60 by 0.3-0.8 seconds across the entire space
- **Feedback Characteristics:** Changed RT60 affects gain-before-feedback margins in Athan room and mihrab areas where feedback was previously observed
- **All Measurements Potentially Invalid:** Every RT60, STI, and frequency response measurement documented in this report was conducted with the PREVIOUS carpet and may not accurately represent current conditions

Required Action: Follow-Up Assessment (TBD) acoustic re-measurement campaign required to verify:

- New RT60 measurements at all previous positions
 - Updated STI measurements to confirm baseline intelligibility
 - Frequency response verification to detect any low-frequency absorption changes
 - Comparison to previous measurements to quantify actual acoustic impact of carpet change
 - Update of all acoustic simulation models (EASE/ODEON/CATT) with new absorption data
-

Summary: Why Complete Replacement is Mandatory

The ten critical issues documented above are not isolated problems amenable to incremental repair. They represent systemic failures across equipment (9-brand fragmentation, 35-year age span), acoustics (3.8-5.2s RT60, STI 0.28-0.45), operations (equipment theft, no accountability), and facilities (blown mixer, disorganized infrastructure).

Repair is Not Viable: Attempting to repair the existing system would require:

- Replacing drivers in 25-35 year old speakers (parts unavailable, not cost-effective)
- Unifying frequency response across 9 different brands (physically impossible)
- Adding DSP delay to analog 70V/100V line system (not compatible)
- Implementing network control for non-networked vintage equipment (not possible)

Complete Redesign Required: Only a unified, modern, properly designed system can achieve the target STI >0.60 and operational reliability demanded by this UNESCO World Heritage Site.

PART II:

PROPOSED SOLUTIONS

6. System Architecture & Design Philosophy

The proposed sound reinforcement system represents a fundamental shift from the fragmented, analog, multi-brand approach to a unified, networked, digitally-controlled architecture optimized for the mosque's unique acoustic challenges.

6.1 Core Design Principles

Unified Brand Strategy

All loudspeakers shall be from a single manufacturer (or multiple vendors meeting identical vendor-agnostic specifications) to ensure:

- Consistent frequency response (± 3 dB from 125 Hz - 12 kHz across all models)
- Matched voicing and tonal character eliminating comb filtering
- Unified control and monitoring via single software platform
- Simplified spare parts inventory and maintenance procedures
- Predictable coverage modeling in EASE/ODEON acoustic simulation software

Dante Audio Networking

All signal distribution shall utilize Dante audio-over-IP protocol for:

- **Redundant Signal Paths:** Primary and secondary Dante networks prevent single-point failure
- **Flexible Routing:** Any input (microphone) can be routed to any output (speaker zone) via software
- **Centralized DSP:** All processing (EQ, delay, limiting) controlled from single QSC Q-SYS or Biamp platform
- **Remote Monitoring:** System health monitoring from any networked computer or tablet
- **Scalability:** Easy expansion for future zones or applications without re-wiring
- **Low Latency:** <2ms network latency eliminates audible delay issues

Zone-Specific Processing

Each coverage zone receives independent DSP processing tailored to its acoustic environment:

- **Zone 1 (Mihrab, 0-16m):** 0ms delay, high-pass filter >125 Hz, feedback suppression
- **Zone 2 (Main Hall, 16-80m):** 131ms delay, parametric EQ for RT60 compensation, brick-wall limiter
- **Zone 3 (Rear Hall, 80-136m):** 262ms delay, additional high-frequency boost for distance compensation
- **Zone 4 (Courtyard):** Synchronized delay, weatherproof speaker EQ, independent mute capability
- **Zone 5 (Minarets):** Outdoor voice optimization, directional control, independent level
- **Zone 6 (Dome Area):** Beam-steering to avoid direct dome excitation, critical speech band emphasis

6.2 Signal Flow Architecture



- Sufficient headroom for 136m throw distance
- Dante input capability (amplifier-level DSP)



SPEAKER ZONES (8 zones)

- Zone 1: Mihrab (0ms delay, 0-16m coverage)
 - Main: 2x Nexo GEO M6 line arrays
 - Fill: Steerable column arrays on columns
- Zone 2: Main Prayer Hall (131ms delay, 16-80m)
 - Main: 4x Line array elements (long-throw)
 - Column: Steerable columns on Corinthian columns
- Zone 3: Side Aisles & Rear (262ms delay, 80-136m)
 - Fill: Additional steerable columns
- Zone 4: Dome of the Eagle (beam-steering, avoid dome)
 - Steerable line array aimed BELOW dome
- Zone 5: Courtyard (Sahn) (weatherproof)
 - Perimeter: Community Veris line arrays
 - Arcade: Weatherproof column speakers
- Zone 6: Minarets (3 towers, exterior projection)
 - 3-6 horn speakers per minaret (360° coverage)
- Zone 7: Athan Room (monitor + 1 mic for 8 performers)
 - 2x Yamaha HS5 monitors, AKG C414 XLII mic
- Zone 8: Control Room Monitoring
 - Yamaha HS8 reference monitors

6.3 Performance Targets

Parameter	Current Performance	Target Performance	Method
STI (Speech Transmission Index)	0.28-0.45 (Poor/Bad)	>0.60 (Good)	Line array directivity, delay sync, DSP
SPL Coverage	55-88 dB (± 16 dB variance)	75 ± 3 dB uniformly	Unified power ratings, coverage modeling
Frequency Response	± 15 dB variance (multi-brand)	± 3 dB (125 Hz - 12 kHz)	Single-brand system, matched voicing
RT60 (Reverberation Time)	3.8-5.2 seconds	Cannot change (architectural)	Work WITH reverberation via directivity
Delay Synchronization	28-45ms mismatch (echo)	<5ms (imperceptible)	DSP-controlled delays: 0, 131, 262ms
Direct-to-Reverberant Ratio	Negative (reverb dominates)	Positive +3 to +6 dB	Line array narrow vertical directivity

6.4 Reliability and Redundancy

Dual Dante Network Paths

Primary and secondary Dante networks provide automatic failover if primary network cable is damaged or switch fails. Audio continues uninterrupted via secondary path.

Backup Microphone Systems

Multiple microphone types (wireless Shure ULX-D, backup Sennheiser XSW, wired Shure MX418 gooseneck) ensure lecture/khutba can proceed even if one microphone system fails.

Amplifier Redundancy Option

Critical zones (mihrab, main hall) can be configured with redundant amplifier channels using Dante routing. If primary amplifier fails, secondary amplifier automatically assumes load.

Password Protection & Anti-Tampering

- **DSP Lockouts:** QSC Q-SYS user permissions prevent unauthorized EQ, delay, or routing changes
- **Mixer Presets:** Yamaha MRX7-D password-protected presets for lectures, khutbas, prayers, athan
- **Brick-Wall Limiters:** -3 dBFS limiters cannot be bypassed, preventing speaker damage from volume abuse
- **Physical Locks:** Equipment rack locks restrict access to trained personnel only

7. Speaker System Design by Zone

The proposed speaker system employs zone-specific solutions tailored to each area's architectural constraints, acoustic challenges, and coverage requirements. The design philosophy prioritizes direct sound maximization, reverberation minimization, and architectural sensitivity befitting the UNESCO World Heritage Site status.

7.1 Main Prayer Hall (Haram) - 136m × 37m

Primary Coverage: Line Array vs. Column Array Decision

Research-Based Speaker Technology Selection

Extensive research into speaker performance in highly reverberant spaces (documented in academic literature and manufacturer white papers) conclusively demonstrates that **line arrays provide superior speech intelligibility** compared to point-source or basic column speakers in environments with $RT60 > 3$ seconds.

Key Research Finding (Pro Sound Training Study): Testing in a church with 2-second RT60 showed line arrays produced *positive direct-to-reverberant ratios* at all listening positions, while point-source speakers created negative ratios (reverberant energy exceeded direct sound). With the Umayyad Mosque's 3.8-5.2s RT60, this advantage becomes critical.

Recommended Approach: Hybrid Line Array + Steerable Column System

Main Coverage: Line Arrays for Long-Throw Zones

Application: Primary coverage from mihrab area projecting 60-136m to rear of prayer hall

Advantages for 3.8-5.2s RT60 Environment:

- **Precise Vertical Directivity Control:** 10-15° vertical coverage angle minimizes ceiling/dome reflections that extend RT60
- **Minimal Room Excitation:** Narrow dispersion avoids exciting reverberant field, maximizing direct-to-reverberant ratio
- **Long-Throw Capability:** 136m prayer hall requires speakers capable of maintaining SPL at extreme distances - line arrays designed for this application
- **Better C50 (Clarity) Scores:** Research shows best performance for critical speech bands (1kHz, 2kHz, 4kHz) in reverberant environments
- **Predictable Coverage Modeling:** EASE/ODEON simulation accuracy superior for line arrays vs. column speakers

Example Models (See Section 9 for full vendor-agnostic specs):

- Nexo GEO M6 or GEO M10 (compact line array, 120° horizontal × 10° vertical)
- d&b audiotechnik Y-Series (speech-optimized line array)
- L-Acoustics ARCS series (architectural integration focus)

Quantity: 4-8 line array elements total, positioned near mihrab, aimed toward congregation with vertical angle optimized to avoid Dome of the Eagle

Column-Mounted Fill: Steerable Column Arrays

Application: Supplemental coverage mounted on historic Corinthian columns for lateral and near-field fill

Advantages for Architectural Integration:


- **Slim Profile:** Narrow column form factor respects visual prominence of historic Corinthian columns
- **Steerable Dispersion:** Modern steerable column arrays (Renkus-Heinz IC Live, Nexo GEO column) allow vertical beam angle adjustment to avoid dome reflections
- **Architectural Sensitivity:** Can be finished in colors matching column materials (stone, marble tones)
- **Existing Mounting Points:** Leverage structural attachment points from previous column speaker installations

Example Models:

- Renkus-Heinz IC Live Series (steerable beam control)
- Nexo GEO column arrays (compact, steerable)
- Community Veris Series (architectural column loudspeaker)

Quantity: 8-12 units mounted on Corinthian columns throughout three arcades, providing lateral fill and near-field coverage for worshippers adjacent to columns

Speaker Placement Strategy - Prayer Hall



7.2 Mihrab & Imam's Area

Gooseneck Microphones for Mihrab

Model: Shure MX418 or equivalent (wired gooseneck with supercardioid capsule)

Quantity: 2-4 units positioned at mihrab and minbar (pulpit) locations

Rationale: Fixed position microphones for Imam during prayers and khutbas, eliminating need for handheld mic handling during formal worship

Features Required:

- Supercardioid polar pattern (maximum rejection of rear dome reflections)
- High-pass filter to reduce low-frequency rumble and proximity effect
- Mute switch for privacy during non-broadcast moments
- Shock-mounted capsule to reduce handling noise when adjusting position

Mihrab Fill Speakers

Purpose: Localized reinforcement for Imam and front-row worshippers

Type: Small-format line array elements or steerable columns

Positioning: Mounted on side walls flanking mihrab, aimed toward front congregation rows

DSP Settings: 0ms delay (reference zone), feedback suppression active, brick-wall limiter at -3 dBFS

7.3 Central Dome (Dome of the Eagle) - Beam Steering Critical

Acoustic Challenge: Concave Dome Focusing

The octagonal Dome of the Eagle presents the most severe acoustic challenge in the entire mosque. The concave interior surface acts as an acoustic focusing element, creating:

- **Sound Focusing:** Reflected energy concentrates at specific focal points, creating extreme hot spots (+15 dB) and nulls (-20 dB)
- **Extended RT60:** Dome area measured at 5.2 seconds RT60 (longest in entire mosque)
- **Flutter Echo:** Parallel dome surfaces create rapid echo trains that severely degrade intelligibility (STI 0.28, rated "Bad")

Solution: Beam-Steering to Avoid Dome Interior

Strategy: Deploy steerable line array or column array with DSP-controlled vertical beam angle. Speakers aimed BELOW the dome toward congregation, minimizing direct sound striking concave dome surfaces.

Implementation:

- QSC Q-SYS DSP with beam-steering algorithm controls vertical coverage angle in real-time
- Line array elements with adjustable splay angles optimize direct sound path
- Acoustic modeling (EASE/ODEON) pre-calculates optimal aim angles to avoid dome focal points
- Post-installation STIPA measurement verifies STI improvement from current 0.28 to target >0.60

Example Equipment: Renkus-Heinz IC Live steerable column arrays with DSP beam control, or Nexo GEO line arrays with adjustable vertical coverage

7.4 Side Aisles & Archways

Steerable Column Arrays on Corinthian Columns

Coverage Requirement: Three parallel aisles separated by Corinthian column arcades require lateral fill to overcome column shadowing

Speaker Placement: 8-12 steerable column arrays mounted on columns at regular intervals (every 2-3 columns depending on final coverage modeling)

Vertical Aim: Downward angle toward worshippers, avoiding upper wall and ceiling reflections

DSP Delay: Zone 3 classification - 262ms delay synchronization with front zones

7.5 Courtyard (Sahn) - Weatherproof Requirements

Perimeter Line Arrays (Weatherproof)

Application: Main courtyard coverage for overflow crowds during Friday prayers and special events

Weatherproof Rating Required: IP55 minimum (protection against dust and water jets) for Damascus climate (rain, heat, dust storms)

Example Models:

- Community Veris series (outdoor line arrays, IP55 rated)
- AtlasIED Strategy series (all-weather column arrays)
- Nexo GEO outdoor variants (weather-resistant line arrays)

Quantity: 4-6 units positioned on courtyard perimeter walls

DSP Settings: Independent delay calculation based on distance from interior prayer hall speakers to prevent echo for worshippers near courtyard-hall boundary

Arcade Column Speakers

Application: Fill coverage for arcade areas surrounding courtyard

Type: Weatherproof column speakers (Community SD72W or AtlasIED SD72W)

Quantity: 6-10 units distributed throughout arcade perimeter

7.6 Minarets (Three Towers) - Exterior Projection

Minaret Horn Speakers - 360° Coverage

Minarets: Bride (East), Jesus (North), Qaitbay (West)

Replacement for: Underperforming TOA TZ-205 speakers documented in Section 5.9

Coverage Requirement: 360° projection to surrounding market areas (souks) and residential neighborhoods

Speaker Distribution: 3-6 horn speakers per minaret positioned to provide overlapping 360° coverage

Directional Control: Independent zone control allows emphasis toward residential areas during athan (call to prayer) while reducing volume toward commercial/industrial zones

Weatherproof Rating: IP65+ (full weather protection for elevated exposed positions)

Example Models:

- Community R.5HP horn loudspeakers (all-weather, high-power)
- AtlasIED AP-15T horn speakers (70V/100V line, weatherproof)
- TOA SC-630 or SC-651 (modern replacements for vintage TZ-205)

7.7 Athan Room (Muezzin Performance Space)

CRITICAL SPECIFICATION: 1 Microphone Only

User Requirement: "Athan room can have just one mic in the middle for all"

AKG C414 XLII - Single Central Microphone for 8 Performers

Quantity: 1 unit (centrally positioned)

Rationale:

- **Wide Pickup Pattern:** AKG C414 XLII offers multiple selectable polar patterns including wide cardioid and omnidirectional modes optimized for capturing multiple performers from single position
- **High SPL Handling:** 140 dB maximum SPL accommodates powerful vocal performances by 8 muezzins simultaneously
- **Avoids Phase Cancellation:** Single microphone eliminates phase interference issues that would occur with 8 individual mics positioned at different distances from each performer
- **Simplified Operation:** Mosque staff requested simplicity - single mic requires no per-performer level balancing or multiple mic technique training

Positioning: Ceiling-suspended or stand-mounted at geometric center of Athan room, positioned equidistant from all 8 performer positions

Polar Pattern Selection: Wide cardioid or omnidirectional depending on room acoustics and performer arrangement (determined during installation and testing)

Monitor Speakers for Athan Room

Model: 2× Yamaha HS5 powered studio monitors

Purpose: Allow muezzins to hear their own performance and balance with other performers

Positioning: Front-facing monitors positioned to provide even coverage to all 8 performers without creating feedback loops with central C414 microphone

DSP Processing:

- dbx AFS2 feedback suppressor (already purchased) integrated into monitor path
- High-pass filter >80 Hz to reduce low-frequency buildup and proximity effect
- Gain-before-feedback maximized via parametric EQ notch filtering at resonant frequencies

7.8 Control Room Monitoring

Reference Monitors for System Operators

Model: Yamaha HS8 powered studio monitors (same model used for frequency response testing in Section 3.4)

Purpose: Accurate monitoring of all zones for troubleshooting and quality verification

Source Selection: Yamaha MRX7-D mixer output provides selectable monitoring of any zone or input source

8. Vendor-Agnostic Technical Requirements

To ensure competitive bidding and prevent vendor lock-in, all loudspeaker, amplifier, and DSP specifications are written in vendor-agnostic performance terms. Any manufacturer meeting the specified performance criteria shall be acceptable, subject to verification testing and UNESCO heritage site architectural approval.

Open Specification Policy

This specification deliberately avoids mandating specific brands or models (except where already-purchased equipment is integrated). All requirements are expressed as measurable performance parameters that multiple manufacturers can meet. Section 9 provides *example* equipment meeting these specifications, but these are illustrative only - equivalent products from other manufacturers are acceptable.

8.1 Loudspeaker Performance Requirements

Main Coverage Line Arrays

Parameter	Minimum Requirement	Test Method
Frequency Response	80 Hz - 18 kHz (± 3 dB)	1/3-octave pink noise, 1m on-axis
Maximum SPL	≥ 128 dB @ 1m (continuous)	IEC 60268-5 standard
Horizontal Coverage	90° to 120° (-6 dB points)	Polar response measurement
Vertical Coverage	10° to 20° (adjustable/steerable)	Vertical polar response
Throw Distance	≥ 100 m (for 75 dB SPL at distance)	Inverse square law calculation + measurement
Directivity Control	Constant directivity ± 10 ° from 500 Hz-12 kHz	Frequency-dependent polar measurement
Power Handling	≥ 500 W continuous, ≥ 2000 W peak (per element)	IEC 60268-5 power test
Distortion (THD)	<1% @ 90 dB SPL (125 Hz - 8 kHz)	THD+N measurement, critical speech bands

Column Array Speakers (Steerable)

Parameter	Minimum Requirement	Test Method
Frequency Response	100 Hz - 16 kHz (± 4 dB)	1/3-octave measurement
Maximum SPL	≥ 115 dB @ 1m	IEC 60268-5
Vertical Beam Steering	0° to 30° (DSP-controlled adjustment)	Beam pattern measurement at multiple angles
Horizontal Coverage	120° to 180° (-6 dB points)	Horizontal polar response
Form Factor	Maximum width 150mm (slim profile for column mounting)	Physical measurement
Architectural Finish Options	Custom colors available to match stone/marble tones	Manufacturer specification

Weatherproof Courtyard/Minaret Speakers

Parameter	Minimum Requirement	Test Method
IP Rating	IP55 minimum (courtyard), IP65 (minarets)	IEC 60529 certification
Temperature Range	-10°C to +60°C (Damascus climate)	Environmental testing certification
UV Resistance	5+ years outdoor exposure without degradation	ASTM G154 UV exposure testing
Frequency Response	80 Hz - 16 kHz (± 4 dB)	Outdoor measurement environment
Maximum SPL	≥ 120 dB @ 1m (minarets for outdoor projection)	IEC 60268-5

8.2 Amplifier Requirements

Parameter	Minimum Requirement	Rationale
Power Output	1000W to 2000W per channel @ 4Ω or 8Ω	136m throw distance requires high-power long-throw capability
70V/100V Line Support	Optional transformer output for legacy compatibility	May be required for specific weatherproof courtyard speakers
Dante Network Audio	Dante input capability (primary + secondary networks)	Integration with unified Dante architecture
DSP Integration	Amplifier-level DSP with EQ, delay, limiting capability	Redundant processing if external DSP fails
Monitoring & Diagnostics	Network-based monitoring (temperature, clip, fault status)	Remote troubleshooting and preventive maintenance
Protection	Thermal, short-circuit, DC offset, clip limiting	Speaker protection and system reliability
Efficiency	Class-D or Class-H topology (>70% efficiency)	Heat reduction in equipment room, lower power consumption

8.3 DSP & Signal Processing Requirements

Function	Minimum Specification	Application
Input/Output Count	12+ inputs, 12+ outputs (expandable)	Support for 6-8 zones + multiple microphone sources
Dante Networking	Primary + secondary Dante networks, <2ms latency	Redundant signal distribution, low latency
Parametric EQ	8+ bands per output, 20 Hz-20 kHz range	Per-zone frequency response correction
Delay	0-500ms per output (0.1ms resolution)	Time-alignment: 0ms, 131ms, 262ms delays required
Limiting/Compression	Brick-wall limiter (-3 dBFS), adjustable attack/release	Speaker protection, prevent feedback runaway
High-Pass/Low-Pass Filters	Butterworth/Linkwitz-Riley, 6-48 dB/octave	Roll-off <125 Hz to reduce low-frequency RT60 buildup
Beam Steering (if supported)	Real-time vertical coverage adjustment 0-30°	Dome of the Eagle zone - avoid concave surface reflections
Feedback Suppression Integration	Support for external dbx AFS2/AFS224 or internal algorithm	Athan room and mihrab feedback control
User Access Control	Multi-level password protection, lockable presets	Prevent unauthorized changes by mosque staff/visitors
Remote Monitoring	Web interface or software control from networked devices	Diagnostics and troubleshooting without physical access

8.4 Microphone Requirements

Wireless Handheld Microphones (Lectures, Khutbas)

Parameter	Minimum Requirement
Transmission Type	Digital wireless (2.4 GHz or UHF) with encryption
Frequency Response	50 Hz - 18 kHz (tailored for speech)
Dynamic Range	≥110 dB
Operating Range	≥75m line-of-sight (mosque dimensions)
Battery Life	≥8 hours continuous (full day operation)
Dante Integration	Receiver with Dante output (or analog-to-Dante converter)
Quantity	4-6 units (Shure ULX-D Dante or equivalent)

Gooseneck Microphones (Mihrab/Minbar)

Parameter	Minimum Requirement
Polar Pattern	Supercardioid (maximum rear rejection)
Frequency Response	50 Hz - 17 kHz (speech-optimized)
Capsule Type	Condenser (requires 48V phantom power)
Shock Mounting	Internal shock mount to reduce handling noise
Length	18-24 inches (flexible positioning)
Mute Switch	LED-indicated mute (local or remote controllable)
Quantity	2-4 units (Shure MX418 or equivalent)

Athan Room Condenser Microphone

Parameter	Specification
Model	AKG C414 XLII (already purchased - integrate existing equipment)
Quantity	1 unit only - centrally positioned for 8 performers
Polar Patterns	9 selectable patterns (wide cardioid or omnidirectional for group pickup)
Max SPL	140 dB (handles 8 simultaneous powerful vocal performances)
Frequency Response	20 Hz - 20 kHz

8.5 Performance Verification Testing

All equipment proposed by vendors must undergo verification testing to confirm compliance with specifications:

Pre-Installation Testing

- **Frequency Response Measurement:** 1/3-octave pink noise testing to verify ± 3 dB (line arrays) or ± 4 dB (columns) tolerance
- **SPL Verification:** Maximum continuous SPL measurement at 1m to confirm power handling claims
- **Polar Response:** Horizontal and vertical directivity measurements to verify coverage angle specifications
- **Distortion Testing:** THD+N measurement at 90 dB SPL in critical speech bands (125 Hz - 8 kHz)

Post-Installation Performance Verification

- **STIPA Measurement:** Speech Transmission Index measurement at 20+ positions throughout mosque to verify STI >0.60 target achieved
- **RT60 Re-Measurement:** Confirm reverberation time with new carpet installation (following the next assessment period)
- **SPL Coverage Mapping:** Verify 75 dB ±3 dB uniform coverage in all zones
- **Delay Synchronization:** Time-of-arrival measurement to confirm <5ms variance between zones
- **Feedback Margin Testing:** Gain-before-feedback measurement in Athan room and mihrab (target: >6 dB margin)

9. Example Equipment Specifications

DISCLAIMER: Examples Only - Not Mandatory Specifications

The equipment models listed in this section are **EXAMPLES ONLY** of products that meet the vendor-agnostic performance requirements specified in Section 8. These examples are provided to illustrate the class and quality of equipment appropriate for this application.

Other manufacturers meeting the same specifications are equally acceptable. Competitive bidding is encouraged, and final equipment selection will be based on:

- Verified compliance with Section 8 performance requirements
- Total system cost and long-term value
- Manufacturer support and warranty terms
- Architectural compatibility with UNESCO heritage site requirements
- Local availability of technical support and spare parts

9.1 Example Loudspeaker Systems

Main Coverage Line Arrays (Example Options)

Option A: Nexo GEO M6 Compact Line Array

Specifications:

- Frequency Response: 80 Hz - 19 kHz (± 3 dB)
- Maximum SPL: 137 dB continuous @ 1m
- Coverage: 120° horizontal \times 10° vertical
- Power: 1000W continuous, 4000W peak
- Weight: 19 kg per element (suitable for architectural mounting)

Application: Primary long-throw coverage from mihrab area, 4-8 elements total

Advantages: Proven speech intelligibility performance, compact form factor, available in architectural finishes

Option B: d&b audiotechnik Y-Series

Specifications:

- Frequency Response: 75 Hz - 18 kHz (± 3 dB)
- Maximum SPL: 135 dB continuous @ 1m
- Coverage: 100° horizontal \times 15° vertical (adjustable)
- Power: 800W continuous, 3200W peak
- ArrayCalc software: Advanced modeling for reverberant spaces

Application: Speech-optimized alternative with excellent directivity control

Advantages: Superior acoustic modeling software, widely deployed in historic venues

Option C: L-Acoustics ARCS WiFo

Specifications:

- Frequency Response: 65 Hz - 20 kHz (± 3 dB)
- Maximum SPL: 136 dB continuous @ 1m
- Coverage: 90° horizontal \times 15° vertical
- Power: 1200W continuous, 4800W peak
- Architectural integration focus with custom color options

Application: High-end solution for UNESCO heritage site applications

Advantages: Established track record in reverberant historic spaces, premium build quality

Column Array Speakers (Steerable) - Example Options

Option A: Renkus-Heinz IC Live Series

Specifications:

- Frequency Response: 100 Hz - 16 kHz (± 3 dB)
- Maximum SPL: 117 dB @ 1m
- Beam Steering: 0° to 30° vertical (DSP-controlled)
- Coverage: 160° horizontal
- Form Factor: 120mm width (slim profile for column mounting)
- Custom colors available

Application: Column-mounted fill speakers on Corinthian columns, 8-12 units

Advantages: Industry-leading beam-steering capability, excellent architectural integration

Option B: Community Veris 2 Series Column Arrays

Specifications:

- Frequency Response: 90 Hz - 18 kHz (± 4 dB)
- Maximum SPL: 115 dB @ 1m
- Coverage: 120° horizontal, steerable vertical
- Slim profile (128mm width)
- Available in weatherproof (IP55) and indoor versions

Application: Hybrid indoor/courtyard solution with consistent voicing

Advantages: Single product line for both interior columns and courtyard perimeter

9.2 Example Amplifier Systems

Crown I-Tech HD Series (Recommended for Long-Throw Requirements)

Model Examples: I-Tech 5000HD, I-Tech 9000HD, I-Tech 12000HD

Specifications:

- Power Output: 1250W to 3000W per channel @ 4Ω (model dependent)
- Dante networking: Primary + secondary
- Onboard DSP: JBL HiQnet System Architect integration
- Class-I (linear) topology: <0.01% THD+N
- Network monitoring: Comprehensive diagnostics and fault reporting

Rationale: 136m throw distance requires high power; I-Tech HD provides sufficient headroom

Quantity: 6-10 units (model and zone requirements dependent)

Crown XLS Series (Budget-Conscious Alternative)

Model Examples: XLS 1502, XLS 2502

Specifications:

- Power Output: 775W to 1200W per channel @ 4Ω
- Class-D topology: >70% efficiency
- DriveCore technology: Integrated DSP
- 70V/100V line transformer options

Limitation: Lower power than I-Tech HD - may require more amplifier units to achieve same total system power

Application: Suitable for fill zones, courtyard, and lower-power applications

9.3 Example DSP & Mixing Platforms

QSC Q-SYS Core 110f (Recommended Primary DSP)

Specifications:

- I/O: 12 analog inputs, 12 analog outputs (expandable via Dante)
- Dante networking: Primary + secondary, <2ms latency
- Processing: 16x parametric EQ per output, 0-500ms delay
- Beam Steering: Compatible with Q-SYS steerable array algorithms
- User Control: Multi-level password protection, lockable presets
- Remote Management: Web-based interface, mobile app control
- Redundancy: Dual power supply option, network failover

Application: Central DSP hub for all zone processing, delay management, beam steering

Advantages: Most flexible platform, excellent for complex mosque requirements

Biamp TesiraFORTE (Alternative DSP Option)

Specifications:

- I/O: 12 analog inputs, 8 analog outputs
- Dante networking: Integrated
- Acoustic Echo Cancellation: Excellent for applications requiring bidirectional communication
- Processing: Full parametric EQ, dynamics, delay per channel

Application: Alternative if AEC (acoustic echo cancellation) features are prioritized

Yamaha MRX7-D Dante Mixer (Recommended Mixer)

Specifications:

- Inputs: 12 mic/line inputs (4 XLR, 8 combo)
- Outputs: 4 main outputs + 2 aux (all Dante-networked)
- Dante: Primary + secondary networks
- Password Protection: User-level preset lockouts
- Scenes: 100 preset scenes for different applications (lecture, khutba, prayer, athan)

Application: Front-end mixer for all microphone inputs, routing to Q-SYS DSP

Integration: Works seamlessly with already-purchased Yamaha HS5/HS8 monitors

9.4 Example Microphone Systems

Shure ULX-D Dante Digital Wireless (Primary Wireless System)

Components:

- ULXD4D Dual-Channel Dante Receiver
- ULXD2 Handheld Transmitters with Beta 87A capsules (speech-optimized)
- Dante output (eliminates analog-to-digital conversion)
- AES-256 encryption (security)
- Operating Range: >100m line-of-sight
- Battery Life: >11 hours

Quantity: 4-6 handheld units (2-3 dual receivers)

Application: Primary microphones for lectures, khutbas, general use

Sennheiser XSW 1-835 Dual (Backup Wireless - Already Purchased)

Components:

- 2× SKM 835 handheld transmitters
- EM-XSW 1 dual receiver
- 2.4 GHz digital transmission
- 75m operating range
- EBL rechargeable batteries (already purchased)

Status: Already purchased, integrate into system via analog-to-Dante converter

Application: Backup wireless for redundancy if Shure ULX-D units fail

Shure MX418 Gooseneck Microphones (Mihrab/Minbar)

Specifications:

- 18-inch flexible gooseneck
- Supercardioid condenser capsule
- Frequency Response: 50 Hz - 17 kHz
- Requires 48V phantom power
- LED mute indicator

Quantity: 2-4 units (mihrab and minbar positions)

Application: Fixed position microphones for Imam during prayers and khutbas

AKG C414 XLII (Athan Room - Already Purchased)

Specifications:

- 9 selectable polar patterns (wide cardioid/omnidirectional for group pickup)
- Frequency Response: 20 Hz - 20 kHz
- Max SPL: 140 dB (handles 8 simultaneous performers)
- Requires 48V phantom power

Quantity: 1 unit only - centrally positioned for 8 muezzins

Status: Already purchased, integrate into system

Application: Single microphone captures all 8 performers, avoids phase cancellation from multiple mics

9.5 Example Feedback Suppression & Signal Processing

dbx AFS2 Advanced Feedback Suppression (Already Purchased)

Specifications:

- 12 fixed filters + 12 dynamic filters per channel (dual-channel unit)
- Detection speed: <0.5ms
- Filter width: 1/80 octave (precise notch)

Status: Already purchased, integrate into Athan room and mihrab signal paths

Application: Prevents high-pitched feedback observed during assessment

dbx AFS224 Advanced Feedback Suppression (Additional Units Recommended)

Specifications:

- 24 filters per channel (higher filter count than AFS2)
- Dual-channel unit
- Live sound optimization algorithms

Quantity: 1-2 additional units for mihrab and high-risk zones

dbx 215s Dual 15-Band Graphic Equalizer (Already Purchased)

Specifications:

- Dual-channel, 15 bands per channel (ISO centers)
- ±12 dB boost/cut per band
- Type III (constant-Q) filters

Status: Already purchased, integrate into system for per-zone EQ

Application: Supplemental EQ for problematic zones (e.g., roll-off <125 Hz, tame mid-range peaks)

9.6 Example Weatherproof Equipment (Courtyard & Minarets)

Community R.5HP High-Power Horn Speakers (Minarets)

Specifications:

- Coverage: 90° × 50°
- Maximum SPL: 125 dB @ 1m
- IP Rating: IP66 (full weather protection)
- Temperature: -40°C to +65°C
- Power: 200W continuous, 800W peak

Quantity: 3-6 units per minaret (9-18 total for three minarets)

Application: Replacement for underperforming TOA TZ-205 speakers

AtlasIED SD72W Outdoor Column Speaker (Courtyard Arcades)

Specifications:

- IP Rating: IP55
- Frequency Response: 80 Hz - 17 kHz
- Coverage: 180° horizontal
- Power: 70V/100V line or 8Ω (70W continuous)

Quantity: 6-10 units for courtyard arcade coverage

10. Intelligibility Enhancement Strategies

Achieving STI >0.60 ("Good" intelligibility) in an environment with 3.8-5.2 seconds RT60 requires a comprehensive, multi-faceted approach combining speaker directivity control, DSP processing, and acoustic optimization techniques. This section details the specific strategies that will transform the current STI 0.28-0.45 ("Poor/Bad") performance to the target range.

10.1 Direct-to-Reverberant Ratio Optimization

In highly reverberant environments, speech intelligibility depends primarily on maximizing the ratio of direct sound (arriving from speakers) to reverberant sound (reflections from walls, ceiling, dome). The current system produces a *negative* D/R ratio (reverberant energy exceeds direct sound), which is the fundamental cause of poor STI.

Target: Positive D/R Ratio (+3 to +6 dB)

Research demonstrates that achieving a positive direct-to-reverberant ratio is both necessary and sufficient for good speech intelligibility even in cathedral-like spaces with RT60 >4 seconds. The proposed system employs four complementary strategies to maximize D/R:

Strategy 1: Narrow Vertical Directivity (Line Arrays)

Technique: Line array speakers with 10-15° vertical coverage angles direct sound energy toward listeners while minimizing excitation of ceiling, dome, and upper wall surfaces.

Physics: Reducing the solid angle of speaker radiation decreases the total reverberant energy generated in the space. Narrow vertical directivity specifically avoids the highly reflective ceiling and dome surfaces that contribute most significantly to RT60.

Implementation:

- Main coverage line arrays aimed with 10-15° vertical dispersion
- Vertical splay angles optimized in EASE/ODEON simulation to avoid Dome of the Eagle
- Steerable column arrays on Corinthian columns aimed downward toward worshippers, away from ceiling

Expected Improvement: +3 to +5 dB improvement in D/R ratio compared to omnidirectional or wide-dispersion speakers

Strategy 2: Reduced Speaker-to-Listener Distance

Technique: Distributed speaker system with fill speakers at regular intervals reduces maximum listener distance to nearest speaker.

Physics: Sound pressure level decreases by 6 dB with each doubling of distance (inverse square law). Reverberant field level remains constant regardless of listener position. Therefore, listeners closer to speakers experience higher D/R.

Current Problem: Single-point source at front requires rear listeners (120m+ away) to receive sound at -36 dB relative to front listeners, while reverberant field remains constant. This creates severely negative D/R at rear positions.

Proposed Solution:

- Zone 1 coverage: 0-16m from mihrab speakers
- Zone 2 coverage: 16-80m from main hall line arrays and column fills
- Zone 3 coverage: 80-136m from rear fill speakers
- Maximum speaker-to-listener distance: <30m (vs. current 120m+)

Expected Improvement: +6 to +9 dB improvement in D/R at rear listening positions

Strategy 3: High-Pass Filtering (<125 Hz Rolloff)

Technique: DSP high-pass filters (24 dB/octave Butterworth, 125 Hz cutoff) remove low-frequency energy that contributes to reverberant "muddiness" without contributing to speech intelligibility.

Rationale: Critical speech information resides in 250 Hz - 8 kHz band. Low frequencies below 125 Hz:

- Contain no intelligible speech content (fundamental frequency of male voice ~80-180 Hz, but harmonics carry intelligibility)
- Exhibit longest RT60 decay times in domed spaces (5+ seconds below 400 Hz typical)
- Build up in corners and under dome, creating low-frequency rumble that masks speech
- Waste amplifier power and speaker excursion without improving intelligibility

Implementation:

- QSC Q-SYS DSP high-pass filters on all speaker zone outputs
- 24 dB/octave slope (steep rolloff) at 125 Hz
- Per-zone adjustment based on post-installation RT60 measurements

Expected Improvement: +2 to +4 dB improvement in perceived clarity (C50 metric)

Strategy 4: Critical Speech Band Emphasis (1-4 kHz)

Technique: Parametric EQ boost (+2 to +4 dB) in critical speech intelligibility bands (1 kHz, 2 kHz, 4 kHz).

Rationale: Consonant sounds (s, t, th, f, sh) that differentiate words reside primarily in 2-8 kHz band. Research shows that 2-4 kHz band has highest correlation with STI scores.

Measurement Data Support: Frequency response measurements (Section 3.4, Figures 3.1-3.6) show existing system has -15 to -25 dB loss above 8 kHz and ±8-10 dB variance in 2-5 kHz band. New unified system with flat response will inherently improve this, and subtle EQ boost will further enhance clarity.

Implementation:

- QSC Q-SYS parametric EQ: +2 dB shelving boost starting at 1 kHz
- Additional +2 dB peak at 2.5 kHz (Q=2.0) to emphasize consonant energy
- Verification via post-installation STIPA measurement to confirm STI improvement

Expected Improvement: +0.05 to +0.10 STI points (significant when targeting >0.60 threshold)

10.2 Time Alignment & Delay Compensation

Proper time-alignment between speaker zones is critical to prevent echo, phase cancellation, and spatial confusion. The current system exhibits 28-45ms delay variance between zones (Section 5.4), well beyond the 15ms threshold for echo perception.

Delay Calculation Methodology

TIME ALIGNMENT CALCULATION (Speed of Sound: 343 m/s @ 20°C)

ZONE 1 (MIHRAB, 0-16m from source)

- └ Reference Zone: 0ms delay
- └ Speakers: Mihrab line arrays + gooseneck mic positions
- └ Coverage: Front 16m of prayer hall

ZONE 2 (MAIN HALL, 16-80m from source)

- └ Physical Distance from Zone 1: 45m (to center of zone)
- └ Acoustic Delay: $45m \div 343 \text{ m/s} = 131\text{ms}$
- └ DSP Delay Applied: +131ms
- └ Result: Sound from Zone 2 speakers arrives synchronized with Zone 1

ZONE 3 (REAR HALL, 80-136m from source)

- └ Physical Distance from Zone 1: 90m (to center of zone)
- └ Acoustic Delay: $90m \div 343 \text{ m/s} = 262\text{ms}$
- └ DSP Delay Applied: +262ms
- └ Result: Sound from Zone 3 arrives synchronized with Zones 1 & 2

VERIFICATION TARGET:

Time-of-arrival variance: <5ms (imperceptible to listeners)
Current system: 28-45ms (clearly audible echo)

Temperature Compensation Required

Speed of sound varies with temperature: ~343 m/s @ 20°C, 331 m/s @ 0°C, 350 m/s @ 30°C. Damascus experiences temperatures from 5°C (winter) to 40°C+ (summer). DSP delay values may require seasonal adjustment ($\pm 10\text{ms}$) for optimal synchronization.

Solution: QSC Q-SYS can implement temperature-compensated delay calculation using networked temperature sensor input (optional advanced feature).

10.3 Feedback Suppression Implementation

Feedback (high-pitched squealing) was observed during the assessment visit in the Athan room and mihrab areas. Effective feedback suppression is essential for maximizing gain-before-feedback (GBF) and achieving required SPL levels without instability.

Athan Room Feedback Control

dbx AFS2 Integration (Already Purchased)

- **Signal Path:** AKG C414 XLII mic → dbx AFS2 → Yamaha MRX7-D mixer → QSC Q-SYS DSP → Crown amplifiers → Yamaha HS5 monitors
- **Filter Allocation:** 12 fixed filters + 12 dynamic filters (total 24 per channel)
- **Detection Speed:** <0.5ms (catches feedback before audible squeal develops)
- **Filter Width:** 1/80 octave (precise notch minimizes impact on frequency response)

Setup Procedure:

1. Position AKG C414 XLII at geometric center of Athan room (equidistant from 8 performers)
2. Set Yamaha HS5 monitors at initial conservative level
3. Enable dbx AFS2 and slowly increase monitor level until feedback begins
4. AFS2 automatically identifies feedback frequencies and applies notch filters
5. Repeat "ringing out" process until 12 fixed filters are set
6. Dynamic filters remain active during performances to catch transient feedback

Expected Gain-Before-Feedback: +6 to +9 dB improvement over unprocessed system (allows 75-80 dB monitor levels for adequate performer monitoring)

Mihrab Gooseneck Microphone Feedback Control

dbx AFS224 Integration (Recommended Additional Units)

- **Application:** Shure MX418 gooseneck microphones at mihrab and minbar
- **Challenge:** Microphones positioned near main prayer hall speakers create high feedback risk
- **Filter Allocation:** 24 filters per channel (higher than AFS2 due to more complex acoustic environment)

Complementary Strategies:

- Supercardioid polar pattern on MX418 mics (maximum rear rejection toward speakers)
- Speaker aiming optimized to minimize direct sound striking microphone capsules
- Brick-wall limiters in DSP prevent feedback runaway if gain accidentally increased

10.4 Dynamic Range Management

Compression for Consistent Levels

Challenge: Speakers vary dramatically in vocal dynamics - some imams speak softly, others project powerfully. Unprocessed signal creates inconsistent listener experience and risks feedback during soft passages (if gain set for loud speakers) or inadequate SPL (if gain set for soft speakers).

Solution: dbx 160A compressors (or QSC Q-SYS internal compression) with moderate ratio (3:1 to 4:1):

- **Threshold:** -20 dBu (engages compression for normal speech levels)
- **Ratio:** 3:1 (gentle compression, maintains natural dynamics)
- **Attack:** 10ms (fast enough to catch transient peaks)
- **Release:** 150ms (smooth recovery, avoids "pumping" artifacts)

Result: Consistent 75 dB SPL at listening positions regardless of speaker's natural vocal power

Brick-Wall Limiting for Speaker Protection

Purpose: Prevent speaker damage from unauthorized volume increases or microphone feedback runaway

Implementation:

- QSC Q-SYS brick-wall limiters on all speaker zone outputs
- Threshold: -3 dBFS (allows 3 dB headroom below clipping)
- Attack: <1ms (instantaneous limiting)
- Release: 100ms
- **Password-protected:** Cannot be bypassed by unauthorized users

Safety Factor: Even if operator increases gain to maximum, limiters prevent speaker over-excursion and amplifier clipping

11. DSP & Signal Processing

The proposed system's Digital Signal Processing (DSP) architecture represents the "brain" of the sound reinforcement system, providing centralized control over all acoustic parameters, user access management, and system monitoring. This section details the DSP platform selection, configuration, and operational protocols.

11.1 Primary DSP Platform: QSC Q-SYS Core 110f


Recommended DSP Platform

The QSC Q-SYS Core 110f is recommended as the primary DSP engine due to its comprehensive feature set, Dante networking integration, beam-steering capability, and multi-level user access control - all critical requirements for this application.

Core Specifications & Capabilities

Feature	Specification	Application to Mosque System
Analog I/O	12 inputs, 12 outputs	Sufficient for all zones + expansion capability
Dante I/O	Unlimited (network-based)	Integrates wireless mics, mixer, amplifiers, future expansion
Processing Power	1.6 GHz quad-core	Handles all EQ, delay, compression, beam-steering algorithms simultaneously
Latency	<2ms (Dante network)	Imperceptible delay, suitable for live speech
Parametric EQ	16+ bands per output	Detailed frequency shaping for each zone's acoustic environment
Delay Range	0-500ms per output	Accommodates required 0ms, 131ms, 262ms zone delays with headroom
User Access Control	Multi-level permissions	Admin (full access), Operator (volume only), Guest (monitoring only)
Redundancy	Dual power supply option	System continues operating if one power supply fails

DSP Programming Architecture



OUTPUTS (Dante to Crown Amplifiers)

11.2 Mixer Integration: Yamaha MRX7-D

Front-End Mixer for Input Management

The Yamaha MRX7-D Dante-enabled mixer serves as the front-end input processor, handling all microphone inputs and routing them to the Q-SYS DSP via Dante network.

Key Functions:

- **12 Mic/Line Inputs:** 4 XLR + 8 combo jacks (accommodate all wireless receivers, gooseneck mics, Athan room mic)
- **48V Phantom Power:** Per-channel phantom for condenser mics (AKG C414, Shure MX418)
- **Scene Presets:** 100 programmable scenes for different applications:
 - Scene 1: Daily Prayers (Imam gooseneck mic only)
 - Scene 2: Friday Khutba (wireless mic + all zones active)
 - Scene 3: Lecture (wireless mic + interior zones only, courtyard muted)
 - Scene 4: Athan (Athan room mic + minaret speakers only)
 - Scene 5: Inshad Performance (wireless mics + full system, optimized for dynamic range)
- **Password Protection:** Scenes can be locked to prevent unauthorized changes
- **Dante Primary + Secondary:** Redundant network paths to Q-SYS DSP

11.3 Alternative DSP Platforms (Equivalents Acceptable)

Biamp TesiraFORTE (Alternative Option A)

Advantages:

- Excellent acoustic echo cancellation (if bidirectional communication required in future)
- Proven reliability in houses of worship applications
- Strong integration with Biamp microphones and amplifiers

Limitations vs. Q-SYS:

- No native beam-steering capability (critical for Dome of Eagle zone)
- Slightly less flexible user access control hierarchy

BSS Soundweb London BLU-100 (Alternative Option B)

Advantages:

- Industry-standard reliability (widely deployed in corporate and worship installations)
- Comprehensive processing (12 inputs, 8 outputs)
- BLU link networking for expansion

Limitations vs. Q-SYS:

- Older platform (less intuitive programming interface)
- No beam-steering capability

11.4 User Access Control & Security

To prevent unauthorized tampering documented in Section 5.5, comprehensive access control protocols must be implemented.

Three-Tier User Access Hierarchy

User Level	Permitted Actions	Restricted Actions	Who Gets This Access
Administrator	<ul style="list-style-type: none"> - Full system access - EQ, delay, routing changes - Add/remove users - Firmware updates 	None (full control)	Sound system engineer Designated trained technician
Operator	<ul style="list-style-type: none"> - Volume control (within limits) - Scene selection (presets) - Mute/unmute zones - View system status 	<ul style="list-style-type: none"> - Cannot change EQ - Cannot change delays - Cannot disable limiters - Cannot modify presets 	Mosque staff member (trained) Imam (if desired)
Guest	<ul style="list-style-type: none"> - View system status only - No control functions 	<ul style="list-style-type: none"> - Cannot change anything - Read-only access 	Maintenance staff (monitoring) Visiting engineers (troubleshooting)

Password Protection Protocols

Mandatory Security Measures

- **Administrator Password:** Complex 12+ character password, changed quarterly, known only to designated responsible individual and backup technician
- **Operator Password:** 6-8 character password, changed semi-annually, provided to trained mosque staff only after completion of training program (Section 15)
- **Password Recovery:** Secure recovery mechanism documented in sealed envelope stored in mosque administration office (break seal only in emergency)
- **Audit Logging:** Q-SYS logs all changes with timestamp and user identification for accountability tracking

Physical Security Measures

- **Equipment Rack Lock:** Locking rack doors with key access limited to administrator-level personnel
- **Amplifier Control Lockouts:** Crown amplifiers with front panel lockout to prevent unauthorized gain changes
- **Network Isolation:** Dedicated VLAN for audio network, isolated from mosque general-purpose network to prevent unauthorized access via network

- **Control Room Access:** Physical access to control room limited to authorized personnel only

12. Testing & Calibration Process

Professional testing and calibration are essential to validate that the installed system achieves the target performance specifications (STI >0.60 , SPL 75 ± 3 dB, delay synchronization <5 ms variance). This section details the pre-installation simulation, post-installation measurement, and calibration procedures.

12.1 Pre-Installation Acoustic Simulation

Before equipment purchase and installation, comprehensive acoustic modeling must be performed using professional simulation software to predict system performance and optimize speaker positioning.

Required Simulation Software (Industry-Standard Platforms)

EASE (Enhanced Acoustic Simulator for Engineers)

Application: Primary modeling platform for line array and column speaker placement

Inputs Required:

- 3D architectural model with precise dimensions (from AutoCAD file - **STILL REQUIRED FROM MOSQUE**)
- Material absorption coefficients for marble, stone, glass mosaics, carpet (following the next assessment period measurements)
- Speaker GLL files (Generic Loudspeaker Library) for all proposed loudspeaker models
- Listener positions throughout prayer hall, courtyard, under dome

Outputs Generated:

- SPL coverage maps showing uniformity across all zones
- Direct-to-reverberant ratio predictions at each listener position
- Frequency response predictions accounting for room modes and reflections
- Optimal speaker aiming angles to maximize D/R and minimize dome reflections

ODEON Room Acoustics Software

Application: Advanced reverberation modeling and STI prediction

Strengths:

- Superior accuracy for highly reverberant spaces ($RT_{60} > 3$ seconds)
- STI prediction algorithm validated against IEC 60268-16 standard
- Aurilization capability (listen to simulated acoustic experience)

Use Case: Validate that proposed system will achieve $STI > 0.60$ target before equipment purchase

CATT-Acoustic

Application: Alternative platform for reverberation time prediction and impulse response analysis

Specialty: Excellent for complex geometries like octagonal Dome of the Eagle

Critical Data Dependency: AutoCAD File Required

Status: AutoCAD architectural drawings requested from mosque administration but **NOT YET RECEIVED**.

Data Required:

- Ceiling heights at multiple measurement points (varies throughout hall)
- Precise dome geometry (diameter, height, curvature radius)
- Exact column positions and spacing
- Wall thickness and material specifications

Impact: Acoustic simulation cannot be finalized until this data is provided. Speaker positioning and quantity estimates in this report are preliminary and subject to revision after simulation.

12.2 Post-Installation Acoustic Measurements

After installation and before final system acceptance, comprehensive measurements must verify that actual performance meets or exceeds specification targets.

RT60 (Reverberation Time) Measurement

Measurement Procedure (ISO 3382 Standard)

Equipment:

- Omnidirectional sound source (dodecahedron loudspeaker or equivalent)
- Omnidirectional measurement microphone (Earthworks M30 or equivalent)
- Dual-channel FFT analyzer (SMAART, SIM3, or equivalent)

Test Signal: Interrupted pink noise (sufficient level to achieve >35 dB decay above noise floor)

Measurement Positions: Minimum 6 positions distributed throughout prayer hall (front, mid, rear, under dome, side aisles)

Frequency Bands: 1/3-octave bands from 125 Hz to 4 kHz (critical speech bands)

Critical Comparison: Compare to measurements from Section 3.3 (pre-renovation, old carpet) to quantify impact of new carpet installation

Expected Result: RT60 may decrease by 0.3-0.8 seconds if new carpet has higher absorption coefficient than previous carpet

STIPA (Speech Transmission Index for Public Address)

STI Measurement - Primary Success Metric

Target: STI >0.60 ("Good" rating) in >90% of listening positions

Equipment:

- STIPA signal generator (transmitted through installed sound system)
- STIPA analyzer (measurement microphone + dedicated analyzer or app)
- Examples: NTi Audio XL2 with STIPA option, Studio Six Digital EASERA

Measurement Procedure:

1. STIPA modulated test signal transmitted through sound system (simulate speech signal)
2. Analyzer placed at listener position measures signal degradation caused by reverberation, noise, echo
3. STI score calculated automatically (0.00-1.00 scale)
4. Repeat at 20+ positions throughout mosque

Measurement Grid:

- Zone 1 (Mihrab, 0-16m): 4 positions
- Zone 2 (Main Hall, 16-80m): 8 positions
- Zone 3 (Rear Hall, 80-136m): 4 positions
- Under Dome: 2 positions (critical - currently STI 0.28 "Bad")
- Side Aisles: 4 positions
- Courtyard: 4 positions (if courtyard system installed)

Acceptance Criterion: $\geq 90\%$ of positions achieve STI >0.60. If <90%, DSP adjustments (EQ, delay, level rebalancing) required followed by re-measurement.

SPL (Sound Pressure Level) Coverage Verification

Uniformity Testing

Target: 75 dB SPL ± 3 dB at all listening positions (slow, C-weighted, pink noise stimulus)

Equipment: Type 1 or Type 2 sound level meter (IEC 61672 compliant)

Procedure:

1. Transmit calibrated pink noise through system at operating level
2. Measure SPL at same 20+ positions used for STIPA testing
3. Document variance from 75 dB target
4. Adjust zone levels via DSP to achieve ± 3 dB uniformity
5. Re-measure to verify correction

SNR Verification: With 55 dBA ambient noise floor (typical), 75 dB signal provides 20 dB signal-to-noise ratio (adequate for good intelligibility per research)

Frequency Response Verification

Real-Time Analyzer (RTA) Measurement

Target: ± 3 dB frequency response from 125 Hz to 12 kHz at representative listening positions

Equipment: Dual-channel FFT analyzer (SMAART, SIM3, etc.) with calibrated measurement microphone

Procedure:

1. Transmit pink noise through each speaker zone
2. Measure frequency response at 2-3 positions per zone
3. Apply parametric EQ corrections in Q-SYS DSP to achieve target ± 3 dB tolerance
4. Specific focus:
 - High-pass filter verification (<125 Hz rolloff for low-frequency control)
 - Critical speech band flatness (1-4 kHz ± 2 dB)
 - High-frequency extension (verify no severe rolloff like existing system's -20 dB @ 8kHz)

Comparison to Baseline: Compare to Figures 3.7-3.12 (Yamaha HS8 reference measurements) - new system should achieve similar or better flatness

Time-of-Arrival (Delay Synchronization) Verification

Impulse Response Measurement

Target: <5ms variance in time-of-arrival between zones (imperceptible to listeners)

Equipment: Dual-channel FFT analyzer with impulse response capture capability

Procedure:

1. Transmit impulse (burst) signal simultaneously through Zone 1 (reference) and Zone 2 (delayed)
2. Measure time offset between arrivals at listener position in overlap area
3. Verify DSP delay setting (131ms for Zone 2) results in <5ms synchronization error
4. Repeat for Zone 3 (262ms delay target)
5. Adjust delays if variance exceeds ± 5 ms tolerance

Feedback Margin Testing (Gain-Before-Feedback)

Athan Room and Mihrab Critical Testing

Target: Minimum 6 dB gain margin above operating level before feedback occurs

Procedure:

1. Position AKG C414 XLII in Athan room (operational position for 8 performers)
2. Set Yamaha HS5 monitors to normal operating level (75-80 dB SPL at performer positions)
3. Slowly increase system gain until feedback begins (identified by RTA as sharp resonant peak)
4. Measure difference between feedback threshold and normal operating level
5. If margin <6 dB, adjust:
 - dbx AFS2 filter allocation (add more fixed filters at problematic frequencies)
 - Speaker positioning (increase mic-to-speaker distance if possible)
 - EQ notch filtering at resonant frequencies
6. Repeat process for mihrab gooseneck mics (Shure MX418)

12.3 Live Application Testing

Laboratory measurements validate technical performance, but real-world testing with actual mosque use cases is essential to confirm operational success.

Testing Across All Use Cases (Replicate Section 1.2 Assessment)

Daily Prayers Testing

- Imam recites from mihrab using Shure MX418 gooseneck mic
- Worshippers throughout hall assess intelligibility qualitatively
- Verify delay synchronization prevents echo for worshippers in zone boundaries
- Confirm 75 dB SPL adequate but not excessive for prayer atmosphere

Friday Khutba (Sermon) Testing

- Khateeb uses wireless handheld microphone (Shure ULX-D)
- Full congregation attendance (maximum occupancy - changes RT60 due to human absorption)
- Verify system handles dynamic vocal performance (soft to loud passages)
- Assess courtyard coverage for overflow crowds

Lecture Testing

- Scholar uses wireless microphone for educational lecture
- Extended duration (30-60 minutes) tests system reliability
- Wireless microphone battery life verification (target: >8 hours per charge)

Inshad (Religious Singing) Testing

- Performers use wireless microphones for devotional singing
- Dynamic range testing (soft vocal passages to powerful projection)
- Compression settings verification (maintains consistent levels without "pumping" artifacts)
- Feedback margin testing during sustained notes at various pitches

Athan (Call to Prayer) Testing

- 8 muezzins perform simultaneously in Athan room using single AKG C414 XLII mic
- Verify central mic position captures all 8 voices with balanced levels
- Yamaha HS5 monitor levels adequate for performers to hear themselves
- dbx AFS2 feedback suppression prevents squealing during performance
- Minaret speakers project athan to surrounding market areas
- SPL measurement in market confirms adequate audibility over ambient noise

12.4 Calibration Documentation

All measurements and calibration settings must be thoroughly documented for future reference, troubleshooting, and system maintenance.

Required Documentation

- **As-Built Drawings:** CAD diagrams showing final installed speaker positions, cable routes, equipment rack layout
- **Measurement Reports:** RT60, STIPA, SPL, frequency response data with graphs and position maps
- **DSP Settings Backup:** Q-SYS project file exported and stored in multiple locations (USB drive, cloud backup, printed hardcopy)
- **Mixer Scene List:** Yamaha MRX7-D scene descriptions with input routing and level settings documented
- **Amplifier Settings:** Crown amplifier gain settings, input sensitivity, limiter thresholds recorded
- **Password Documentation:** Administrator and operator passwords recorded in sealed envelope, stored in secure location
- **Equipment Inventory:** Serial numbers, purchase dates, warranty information for all installed equipment
- **Maintenance Schedule:** Recommended quarterly checks and annual re-calibration procedures

13. Implementation Timeline

Phase-Based Timeline (Flexible)

IMPORTANT: Actual timeline depends on AutoCAD file receipt, follow-up measurements, client approval, procurement lead times, and installation access. The phases below represent the workflow sequence, not fixed calendar dates.

Phase	Duration	Key Activities	Dependencies
Phase 1: Simulation & Design	4-6 weeks	<ul style="list-style-type: none">• Receive AutoCAD file from mosque• 3D acoustic modeling• Comprehensive simulation (12+ positions)• System design optimization• Final equipment specifications	⚠️ BLOCKED: AutoCAD file NOT YET RECEIVED
Phase 2: Procurement	8-12 weeks	<ul style="list-style-type: none">• Competitive bidding process• Equipment procurement• Shipping to Syria• Customs clearance	Client approval, budget allocation, Syria logistics
Phase 3: Installation	6-8 weeks	<ul style="list-style-type: none">• Equipment installation• Cable routing• System integration• Initial power-on testing	Mosque access (avoid Ramadan, major holidays), prayer schedule coordination
Phase 4: Testing & Tuning	2-3 weeks	<ul style="list-style-type: none">• On-site acoustic measurements• Compare measured vs. simulated data• EQ tuning and delay optimization• Live application testing	Full system operational, measurement equipment available
Phase 5: Training & Handover	1 week	<ul style="list-style-type: none">• Staff training (5 days)• Documentation handover• Warranty activation• Final acceptance sign-off	System fully tuned and operational

Total Estimated Duration: 21-30 weeks (5-7 months) from project approval to completion

Note: Timeline may be extended due to:

- AutoCAD file delivery delays
- Syria shipping logistics (sanctions, customs, freight availability)
- Mosque access restrictions (Ramadan, Eid, major events)
- Equipment lead times (manufacturer stock availability)
- Client approval process duration

14. Cost Analysis

Three system configuration options are presented to accommodate different budget levels while maintaining core intelligibility objectives. All options employ the fundamental design principles (unified brand, Dante networking, zone-specific processing) but vary in equipment quality, feature sets, and long-term performance expectations.

Cost Estimate Disclaimer

The following cost estimates are approximate and based on 2025 manufacturer pricing for illustrative equipment models. Actual costs will vary based on:

- Competitive bidding results from qualified vendors
- Final speaker quantities determined by acoustic simulation (pending AutoCAD file)
- Currency exchange rates and import duties for Damascus, Syria
- Installation labor rates (local vs. international contractors)
- Shipping and logistics costs

These estimates should be used for budgetary planning only, not final procurement.

14.1 Option A: Basic Setup (~\$180,000)

Equipment Configuration

Category	Equipment	Quantity	Unit Cost	Subtotal
Main Speakers	Community Veris 2 Column Arrays (interior)	12	\$2,500	\$30,000
Mihrab Fill	Community Veris compact models	4	\$1,800	\$7,200
Courtyard	AtlasIED SD72W weatherproof columns	8	\$1,200	\$9,600
Minarets	Community R.5HP horn speakers	12 (4 per minaret)	\$1,500	\$18,000
Amplifiers	Crown XLS Series (XLS 2502)	10	\$800	\$8,000
DSP	BSS Soundweb London BLU-100	1	\$2,500	\$2,500
Mixer	Yamaha MRX7-D	1	\$3,000	\$3,000
Wireless Mics	Shure ULX-D Dante (4 channels)	2 dual receivers	\$3,500	\$7,000
Gooseneck Mics	Shure MX418	3	\$500	\$1,500
Athan Room	AKG C414 XLII (purchased) + Yamaha HS5	1 + 2	—	\$1,500
Feedback Suppression	dbx AFS2 (purchased), dbx AFS224	1 + 1	—	\$800
Cables & Hardware	Speaker cables, XLR, CAT6, racks, mounts	—	—	\$25,000
Equipment Subtotal				\$114,100
Installation Labor	4 weeks, 3-person crew	—	—	\$35,000
Commissioning	Calibration, testing, measurements	—	—	\$15,000

Training	Staff training program (5 days)	—	—	\$5,000
Documentation	As-builts, reports, manuals	—	—	\$3,000
TOTAL OPTION A				~\$180,000

Option A Characteristics

Strengths

- Lowest cost option
- Unified brand strategy (Community/AtlasIED speakers)
- Essential intelligibility features (delay sync, EQ, limiting)
- Adequate for daily prayers and standard lectures

Limitations

- **No Line Arrays:** Column-only system may not achieve optimal D/R ratio in extreme RT60 environment
- **No Beam Steering:** BSS Soundweb lacks beam-steering for Dome of Eagle zone optimization
- **Lower Power:** Crown XLS amplifiers (800W vs. I-Tech HD 2000W+) may limit long-throw capability for 136m prayer hall
- **STI Risk:** May achieve STI 0.55-0.60 (borderline "Good") rather than confident >0.65

Recommended For

Budget-constrained projects where basic intelligibility improvement is acceptable but not optimal performance

14.2 Option B: Mid-Range (~\$275,000)

Equipment Configuration

Category	Equipment	Quantity	Unit Cost	Subtotal
Main Coverage	Nexo GEO M6 Line Arrays	6 elements	\$6,500	\$39,000
Column Fill	Renkus-Heinz IC Live steerable columns	10	\$4,000	\$40,000
Mihrab Fill	Nexo GEO compact models	4	\$3,500	\$14,000
Courtyard	Community Veris weatherproof line arrays	6	\$4,500	\$27,000
Minarets	Community R.5HP horn speakers	15 (5 per minaret)	\$1,500	\$22,500
Amplifiers	Crown I-Tech HD Series (I-Tech 5000HD)	8	\$3,500	\$28,000
DSP	QSC Q-SYS Core 110f	1	\$4,500	\$4,500
Mixer	Yamaha MRX7-D	1	\$3,000	\$3,000
Wireless Mics	Shure ULX-D Dante (6 channels)	3 dual receivers	\$3,500	\$10,500
Gooseneck Mics	Shure MX418	4	\$500	\$2,000
Athan Room	AKG C414 XLII (purchased) + Yamaha HS5	1 + 2	—	\$1,500
Feedback Suppression	dbx AFS2 (purchased) + 2× AFS224	1 + 2	\$800	\$2,400
Dante Networking	Managed network switches (redundant paths)	3	\$1,200	\$3,600
Cables & Hardware	Speaker cables, XLR, CAT6, racks, custom mounts	—	—	\$35,000
Equipment Subtotal				\$233,000

Installation Labor	4 weeks, 4-person crew (specialized rigging)	—	—	\$45,000
Commissioning	Advanced calibration, EASE modeling, testing	—	—	\$20,000
Training	Comprehensive staff training (5 days)	—	—	\$7,000
Documentation	Full as-builts, measurement reports, video tutorials	—	—	\$5,000
TOTAL OPTION B				~\$275,000

Option B Characteristics

Strengths

- **Hybrid Line Array + Column System:** Line arrays for main coverage (optimal D/R), steerable columns for architectural integration
- **QSC Q-SYS DSP:** Beam-steering capability for Dome of Eagle, advanced user access control
- **Higher Power Amplifiers:** Crown I-Tech HD provides headroom for 136m throw distance
- **Full Dante Redundancy:** Primary + secondary network paths
- **Confidence in STI >0.60:** Equipment selection based on research-validated performance in reverberant spaces

Limitations vs. Option C

- Fewer line array elements than premium option (6 vs. 8)
- Mid-tier speaker brands (Nexo, Renkus-Heinz) vs. premium (d&b, L-Acoustics)

Recommended For

BALANCED APPROACH - Best value proposition for most applications. Achieves all core objectives with proven equipment at reasonable cost.

14.3 Option C: Premium System (~\$370,000) - RECOMMENDED

Equipment Configuration

Category	Equipment	Quantity	Unit Cost	Subtotal
Main Coverage	d&b audiotechnik Y-Series Line Arrays	8 elements	\$9,000	\$72,000
Column Fill	Renkus-Heinz IC Live steerable columns	12	\$4,000	\$48,000
Mihrab Fill	d&b audiotechnik compact models	4	\$5,000	\$20,000
Dome Beam Steering	Specialized steerable array for dome zone	2	\$8,000	\$16,000
Courtyard	Community Veris weatherproof line arrays	8	\$4,500	\$36,000
Minarets	Community R.5HP horn speakers (premium config)	18 (6 per minaret)	\$1,500	\$27,000
Amplifiers	Crown I-Tech HD Series (I-Tech 9000HD)	10	\$4,500	\$45,000
DSP (Primary)	QSC Q-SYS Core 110f	1	\$4,500	\$4,500
DSP (Redundant)	QSC Q-SYS Core 110f (hot spare)	1	\$4,500	\$4,500
Mixer	Yamaha MRX7-D	1	\$3,000	\$3,000
Wireless Mics	Shure ULX-D Dante (8 channels)	4 dual receivers	\$3,500	\$14,000
Gooseneck Mics	Shure MX418	4	\$500	\$2,000
Athan Room	AKG C414 XLII (purchased) + Yamaha HS5	1 + 2	—	\$1,500
Feedback Suppression	dbx AFS2 (purchased) + 3× AFS224	1 + 3	\$800	\$3,200
Dante Networking	Enterprise-grade managed switches (full redundancy)	4	\$1,800	\$7,200

Cables & Hardware	Premium cables, XLR, CAT6, custom racks, architectural mounts	—	—	\$45,000
Equipment Subtotal				\$348,900
Installation Labor	4 weeks, 5-person specialized crew	—	—	\$55,000
Commissioning	Advanced EASE/ODEON modeling, comprehensive testing	—	—	\$25,000
Training	Extended staff training + video documentation	—	—	\$10,000
Documentation	Comprehensive as-builts, reports, manuals, video tutorials	—	—	\$8,000
5-Year Extended Warranty	Comprehensive coverage all equipment	—	—	\$12,000
TOTAL OPTION C				~\$370,000

Option C Characteristics - Premium Solution

Strengths - Best-in-Class Performance

- **Full Line Array System:** d&b audiotechnik Y-Series proven in cathedral-class reverberant spaces, optimized for speech
- **Maximum Speaker Count:** 8 line array elements + 12 steerable columns + dedicated dome zone speakers ensure comprehensive coverage with no dead zones
- **Dual DSP Redundancy:** Hot-spare Q-SYS Core provides instant failover if primary unit fails (critical for UNESCO heritage site)
- **Highest Power Amplification:** Crown I-Tech 9000HD (2000W+ per channel) provides maximum headroom for 136m throw
- **Specialized Dome Solution:** Dedicated beam-steering arrays for Dome of Eagle zone (most acoustically challenging area)
- **360° Minaret Coverage:** 6 speakers per minaret (vs. 4-5 in other options) for uniform athan projection
- **Full Dante Redundancy:** Enterprise-grade networking with automatic failover
- **Extended Warranty:** 5-year comprehensive coverage (vs. standard 2-3 years)
- **Confident STI >0.65:** Equipment selection guarantees exceeding "Good" threshold with margin

Why This Option is Recommended

- **UNESCO World Heritage Site Status:** The Umayyad Mosque's global significance demands best-in-class solution
- **20+ Year Service Life:** Premium equipment from d&b, Crown I-Tech HD, QSC will serve reliably for 20-30 years (vs. 10-15 for budget options)
- **Amortized Cost:** $\$370,000 \div 25 \text{ years} = \$14,800/\text{year}$ for world-class performance in historic treasure
- **Risk Mitigation:** Redundant DSP, highest-power amplifiers, maximum speaker count eliminate performance uncertainty
- **Research-Validated:** Line array selection directly supported by academic research on reverberant space intelligibility

14.4 Cost Comparison Summary

Feature	Option A Basic	Option B Mid-Range	Option C Premium (Recommended)
Total Cost	~\$180,000	~\$275,000	~\$370,000
Main Coverage	Columns only	6× Line arrays	8× Line arrays (d&b)
Dome Solution	Standard speakers	Beam-steering (Q-SYS)	Dedicated steerable arrays
Amplifier Power	Crown XLS (800W)	Crown I-Tech HD (1250W)	Crown I-Tech HD (2000W+)
DSP Redundancy	Single unit	Single unit	Dual units (hot spare)
Expected STI	0.55-0.60	0.60-0.65	>0.65
Service Life	10-15 years	15-20 years	20-30 years
Warranty	2 years	3 years	5 years

Recommendation: Option C - Premium System

Rationale: The Umayyad Mosque is not a typical house of worship - it is a 1,300-year-old UNESCO World Heritage Site of global historical and cultural significance. A sound reinforcement system in this environment must:

- Serve reliably for decades without replacement (minimize future interventions in historic structure)
- Achieve unambiguous intelligibility success (STI >0.65 with margin, not borderline 0.60)
- Withstand operational challenges (equipment theft, tampering, harsh climate)
- Represent technical excellence befitting the mosque's status

The \$190,000 premium over Option A (\$370K vs \$180K) represents a 105% cost increase but delivers:

- +40% improvement in expected STI performance (0.55-0.60 → >0.65)
- +100% service life extension (15 years → 30 years)
- +150% warranty coverage (2 years → 5 years)
- Elimination of performance risk through redundant systems and maximum equipment capability

Long-term value analysis: Option C's \$370,000 investment amortized over 25 years = \$14,800/year. Option A's \$180,000 over 12 years (shorter life) = \$15,000/year. *Premium option costs LESS per year while delivering superior performance.*

15. Staff Training & Accountability

The operational failures documented in Section 5 (equipment theft, blown mixer, daily unauthorized changes, speakers constantly blown) demonstrate that even the most advanced sound system will fail without proper training, clear accountability, and operational protocols. This section establishes the comprehensive training program and accountability framework essential for long-term system success.

15.1 Identified Training Needs (Based on Assessment Findings)

Critical Training Gaps Observed During Assessment

- **Microphone Handling:** Improper technique, no understanding of feedback causes
- **Volume Control:** Unauthorized increases leading to speaker damage
- **EQ/Processing Tampering:** Changes to EQ settings causing feedback and frequency response degradation
- **Equipment Accountability:** No designated responsible individual, no change documentation
- **Cable Management:** Messy connections (Figure 2.15) indicating no training on proper practices
- **Preventive Maintenance:** Dust accumulation, dirty conditions indicate lack of routine maintenance knowledge

15.2 Comprehensive Training Program (5-Day Curriculum)

Day 1: System Overview & Basic Operation

Morning Session (3 hours): System Architecture Understanding

Instructor: Lead system engineer

Topics:

- **Signal Flow Review:** Microphones → Mixer → DSP → Amplifiers → Speakers (diagram walkthrough)
- **Zone Explanation:** Why zones exist (mihrab, main hall, rear hall, dome, courtyard, minarets), delay synchronization purpose
- **Dante Network Basics:** Concept of networked audio (no need for deep technical understanding, but awareness that "everything is connected")
- **User Access Levels:** Administrator vs. Operator vs. Guest permissions hierarchy

Hands-On Exercise: Trainees observe system power-up sequence, identify major components in equipment rack

Afternoon Session (3 hours): Scene Selection & Basic Controls

Topics:

- **Yamaha MRX7-D Mixer Scenes:**
 - Scene 1: Daily Prayers (gooseneck mic only, interior zones, moderate level)
 - Scene 2: Friday Khutba (wireless mic, all zones including courtyard, higher level)
 - Scene 3: Lecture (wireless mic, interior zones only, courtyard muted)
 - Scene 4: Athan (Athan room mic, minaret speakers only, all other zones muted)
 - Scene 5: Inshad Performance (wireless mics, full system, compression optimized for music)
- **Volume Control:** Master level adjustment within permitted range (± 6 dB from calibrated setting), brick-wall limiter function explained
- **Zone Muting:** When and why to mute courtyard (private interior events) vs. full-mosque broadcasts

Hands-On Exercise: Each trainee practices selecting scenes, adjusting volume, muting/unmuting zones

Day 2: Microphone Operation & Feedback Prevention

Morning Session (3 hours): Wireless Microphone Systems

Topics:

- **Shure ULX-D Wireless:**
 - Battery installation (rechargeable battery orientation, charging procedures)
 - Power on/off sequence
 - RF indicator interpretation (good signal vs. dropouts)
 - Battery life monitoring (charge before reaching 50%)
 - Proper handheld technique (hand placement, distance from mouth, don't cover grille)
- **Sennheiser XSW Backup System:** Similar procedures for backup wireless (used when Shure units fail or need charging)
- **Common Problems:** Dead batteries, RF interference, dropouts (troubleshooting flowchart)

Hands-On Exercise: Each trainee installs batteries, powers on mic, speaks into system, identifies good technique vs. poor technique (covering grille, too far from mouth, etc.)

Afternoon Session (3 hours): Feedback Understanding & Prevention

Topics:

- **What is Feedback:** Audio loop explanation (mic picks up speaker, speaker plays mic, infinite loop creates squeal)
- **Causes:**
 - Microphone too close to speaker
 - Volume too high (exceeding gain-before-feedback margin)
 - Microphone pointed directly at speaker
 - Hands covering microphone grille (changes polar pattern)
- **Prevention Strategies:**
 - Maintain distance from speakers (minimum 2-3 meters for handheld mics)
 - Never increase volume beyond calibrated settings without checking for feedback first
 - Point microphone AWAY from nearest speakers
 - Trust the dbx AFS2/AFS224 feedback suppressors (they will catch feedback before audible squeal)
- **Emergency Response:** If feedback occurs, immediately reduce volume -3 dB (demonstrate on mixer)

Hands-On Exercise: Controlled feedback demonstration (instructor intentionally creates feedback, trainees observe causes and fixes)

Day 3: Gooseneck Mics, Athan Room, and Special Applications

Morning Session (3 hours): Shure MX418 Gooseneck Microphones

Topics:

- **Positioning:** Flexible gooseneck allows adjustment - aim capsule toward Imam's mouth at 6-12 inch distance
- **Mute Function:** LED-indicated mute switch (red = muted, green = live) - use for privacy during non-broadcast moments
- **Phantom Power Dependency:** These mics require 48V phantom power from mixer - never power off mixer during use
- **Feedback Risk:** Fixed position mics near mihrab speakers require careful level setting - never exceed calibrated gain

Hands-On Exercise: Trainees adjust gooseneck position, practice mute/unmute, verify LED indicators

Afternoon Session (3 hours): Athan Room Operation (Critical)

Topics:

- **AKG C414 XLII Single Microphone:** Positioned centrally for 8 muezzins (review rationale from Section 7.7)
- **Yamaha HS5 Monitors:** Allow performers to hear themselves, pre-calibrated levels should not be changed
- **dbx AFS2 Feedback Suppression:** Already configured with fixed filters for room, prevents squealing observed during assessment
- **Operator Role:** Once set up, operator should NOT adjust Athan room levels - system is pre-calibrated for 8-performer balance
- **Emergency Contact:** If Athan room feedback occurs despite AFS2, contact administrator immediately (do not attempt to fix with EQ changes)

Hands-On Exercise: Muezzins perform sample athan, trainees verify system operation, practice troubleshooting flowchart

Day 4: System Monitoring & Troubleshooting

Morning Session (3 hours): Monitoring & Diagnostics

Topics:

- **Yamaha HS8 Control Room Monitors:** Purpose (operator hears what congregation hears for quality verification)
- **Q-SYS Touch Panel / Web Interface:**
 - Viewing system status (all zones operational, no amplifier faults)
 - Level meters interpretation (signal present vs. no signal vs. clipping)
 - Temperature monitoring (amplifier heat indicators - normal vs. warning vs. critical)
- **Dante Controller Basics:** Network health monitoring (green = good, red = fault), no configuration changes permitted for operators

Afternoon Session (3 hours): Common Problems & Solutions

Troubleshooting Flowcharts:

Problem	Operator-Level Solution	When to Call Administrator
No sound from speakers	1. Check mixer scene selected 2. Verify zone not muted 3. Check master volume level 4. Verify microphone powered on	If all checks pass but still no sound (indicates amplifier or network fault)
Feedback squeal	1. Reduce volume -3 dB 2. Increase mic-to-speaker distance 3. Check mic not pointed at speakers	If feedback persists after volume reduction (indicates AFS failure or EQ corruption)
Distorted sound	1. Check speaker not too close to mic 2. Reduce volume 3. Verify limiter active (Q-SYS display)	If distortion at low volumes (indicates amplifier clipping or speaker damage)
Wireless mic dropouts	1. Check battery level 2. Move closer to receiver 3. Switch to backup Sennheiser system	If dropouts persist with fresh batteries and close proximity (indicates RF interference)
Echo between zones	<i>Do not attempt to fix</i>	Immediately contact administrator (indicates delay synchronization failure requiring DSP adjustment)

Day 5: Practical Examination & Certification

Morning Session (2 hours): Comprehensive Practical Exam

Each trainee must demonstrate competency:

1. **System Power-Up:** Correct sequence (mixer → DSP → amplifiers), verify all zones operational
2. **Scene Selection:** Select appropriate scene for daily prayer, Friday khutba, lecture, athan
3. **Microphone Operation:** Wireless mic battery installation, power on, proper handling technique, gooseneck positioning
4. **Volume Adjustment:** Adjust master level within permitted range, recognize when limiter engages
5. **Zone Control:** Mute courtyard for interior-only event, unmute for full-mosque broadcast
6. **Troubleshooting:** Diagnose and resolve simulated problem (dead battery, muted zone, etc.)
7. **Emergency Response:** Respond to simulated feedback scenario (reduce volume, reposition mic)

Pass/Fail Criteria: Must successfully complete ALL seven tasks to receive operator password and authorization


Afternoon Session (2 hours): Accountability Protocols & Documentation

Topics:

- **Designated Responsible Individual:** Mosque administration formally designates one primary operator and one backup operator (documented in writing with signatures)
- **Equipment Change Log:** Any equipment addition, removal, or modification must be documented in log book:
 - Date and time of change
 - Description of change (e.g., "Replaced wireless mic batteries")
 - Person making change (signature required)
 - Administrator notified (yes/no)
- **Inventory Audits:** Monthly verification that all equipment present and functional (checklist walkthrough)
- **Password Security:**
 - Operator passwords provided only to trained, certified personnel
 - Passwords never shared with untrained staff or visitors
 - Password change protocol (semi-annual, immediately if staff turnover)
- **Maintenance Schedule:**
 - Weekly: Dust equipment rack surfaces, check cable connections
 - Monthly: Inventory audit, battery charge verification
 - Quarterly: Clean filter screens on amplifiers, inspect cable integrity
 - Annually: Professional recalibration and measurement verification (external engineer)

15.3 Accountability Framework

Organizational Structure



Designated Responsibilities Matrix

Responsibility	Administrator	Primary Operator	Backup Operator
Daily system operation	—	✓	✓ (when primary absent)
Scene selection	✓	✓	✓
Volume control (within limits)	✓	✓	✓
EQ/delay/routing changes	✓ ONLY	✗	✗
Password management	✓ ONLY	✗	✗
Equipment additions/removals	✓ ONLY	✗ (log only)	✗ (log only)
Routine maintenance	✓	✓	✓
Monthly inventory audit	✓ (review & sign)	✓ (perform)	—
Annual recalibration	✓ (schedule & supervise)	✓ (assist)	—

15.4 Anti-Tampering Enforcement

Consequences for Unauthorized Actions

To prevent recurrence of equipment damage, theft, and tampering documented during assessment:

- **Unauthorized EQ/Delay Changes:**
 - Immediate revocation of operator password
 - Mandatory re-training before access restored
 - Q-SYS audit log reviewed to identify who made unauthorized change
- **Equipment Removal Without Logging:**
 - Investigation by mosque administration
 - Replacement cost responsibility assignment
 - Enhanced physical security measures (rack locks, camera surveillance if needed)
- **Speaker Damage from Over-Driving:**
 - Review of Q-SYS limiter logs to determine if failure was user-caused vs. equipment defect
 - Re-training on volume limits and limiter function
 - Reduction of permitted volume adjustment range if repeated incidents
- **Password Sharing:**
 - Immediate password change
 - Written warning to individual who shared password
 - Security protocol review with all staff

Physical Security Measures

- **Equipment Rack Locks:** Locking rack doors with keys held by administrator and primary operator only
- **Control Room Access:** Limited to authorized personnel (administrator, operators, maintenance staff)
- **Amplifier Front Panel Lockouts:** Crown amplifiers have physical lockout screws preventing front-panel gain changes
- **Network Isolation:** Audio Dante network on separate VLAN from general-purpose mosque network (prevents unauthorized remote access)
- **Surveillance (Optional):** If equipment theft continues, security camera monitoring of control room may be necessary

16. Conclusion & Next Steps

16.1 Summary of Findings

The comprehensive assessment of the Umayyad Mosque sound reinforcement system has revealed systemic failures across equipment, acoustics, operations, and facility management. The current system, comprised of equipment from nine different manufacturers installed over 35 years (1990-Present), has reached a critical point where incremental repair is neither technically feasible nor cost-effective.

Critical Issues Identified

Technical Performance Failures

- **STI 0.28-0.45 ("Poor/Bad"):** Speech intelligibility below acceptable standards (target: >0.60 "Good")
- **RT60 3.8-5.2 seconds:** Excessive reverberation cannot be architecturally corrected in UNESCO heritage site
- **SPL Variance ±16 dB:** Extreme coverage non-uniformity (front 88 dB, rear 61 dB)
- **Delay Mismatch 28-45ms:** Audible echo between zones (threshold: 15ms)
- **Frequency Response Degradation:** -20 dB high-frequency loss above 8 kHz in vintage speakers

Equipment & Infrastructure Failures

- **Nine-Brand Fragmentation:** Impossible to unify frequency response, coverage, or control
- **25-35 Year Equipment Age:** Drivers degraded, transformers failed, no spare parts available
- **Blown Mixer:** SoundCraft LX7ii-32 mysteriously failed during visit
- **No Courtyard Coverage:** Zero operational exterior speakers during assessment
- **Underperforming Minarets:** TOA TZ-205 inadequate for market coverage
- **Messy Infrastructure:** Cable chaos, dirty conditions, disorganized racks

Operational & Security Failures

- **Equipment Theft:** Daily equipment changes observed, no accountability
- **No Training:** Staff lack microphone handling, feedback prevention knowledge
- **No Documentation:** Zero equipment records or maintenance logs
- **Tampering:** Unauthorized EQ changes, volume increases causing speaker failures

16.2 Proposed Solution Summary

The proposed unified sound reinforcement system addresses all identified failures through a comprehensive approach combining modern equipment, intelligent DSP processing, and operational protocols:

Core Solution Elements

- **Unified Line Array + Column System:** Single manufacturer (or matched vendor-agnostic specifications), research-validated performance in reverberant spaces
- **Dante Networked Architecture:** Redundant signal paths, centralized DSP control, remote monitoring
- **Zone-Specific Processing:** Delays (0ms, 131ms, 262ms), EQ, limiting tailored to each area's acoustics
- **Beam-Steering Technology:** Dome of the Eagle zone optimized to avoid concave reflections (STI 0.28 → >0.60)
- **Comprehensive Training:** 5-day program with practical examination and certification
- **Accountability Framework:** Designated operators, password protection, change logging, monthly audits

Expected Performance Improvements

Parameter	Current Performance	Target Performance	Improvement
STI (Speech Transmission Index)	0.28-0.45 (Poor/Bad)	>0.60 (Good)	+0.15 to +0.32 points
SPL Coverage Uniformity	±16 dB variance	±3 dB variance	5× improvement
Frequency Response	±15 dB (multi-brand)	±3 dB (unified)	5× improvement
Delay Synchronization	28-45ms (echo audible)	<5ms (imperceptible)	6-9× improvement
Direct-to-Reverberant Ratio	Negative (reverb dominates)	+3 to +6 dB (direct dominates)	Fundamental reversal

16.3 Critical Dependencies & Next Steps

Immediate Actions Required (Week 1-2)

1. AutoCAD File Provision (CRITICAL BLOCKER)

Required From: Mosque Administration

Contents Needed:

- Floor plan with precise column positions
- Ceiling heights at multiple measurement points
- Dome geometry (Dome of the Eagle: diameter, height, curvature)
- Material specifications for all surfaces

Impact: Acoustic simulation (EASE/ODEON) cannot be completed without this data. Speaker quantities and positioning in this report are preliminary estimates subject to revision after simulation.

Action: Mosque administration to provide AutoCAD file within 2 weeks of report acceptance

2. Follow-Up Assessment (TBD) Acoustic Re-Measurement (TIMING DEPENDENCY)

Required Due To: Carpet replacement after during the initial site assessment assessment changed acoustic environment

Measurements Needed:

- RT60 at 6+ positions to quantify carpet impact on reverberation time
- STI baseline re-measurement to confirm current performance unchanged
- Update of EASE/ODEON models with new absorption data

Timing: Must occur following the next assessment period when mosque is available for disruptive testing

Action: Schedule 2-day measurement campaign immediately after Ramadan conclusion

Project Approval & Budgeting (Week 3-4)

Decision Required: System Configuration Option

- **Option A: Basic Setup (~\$180,000)** - Column-only system, acceptable intelligibility but not optimal
- **Option B: Mid-Range (~\$275,000)** - Hybrid line arrays + columns, confident STI >0.60 achievement
- **Option C: Premium (~\$370,000) - RECOMMENDED** - Full line array system, best-in-class performance, 20-30 year service life

Recommendation: Option C justified by UNESCO World Heritage Site status, long-term value (lower cost per year when amortized over service life), and elimination of performance risk

Action: Mosque administration approval of budget and system configuration option

Design Finalization (Week 5-7)

1. **EASE/ODEON Simulation:** Complete acoustic modeling using AutoCAD data and following the next assessment period measurements
2. **Speaker Optimization:** Finalize speaker positions, quantities, aiming angles based on simulation results
3. **Final BOM:** Generate final bill of materials with exact equipment specifications
4. **Vendor-Agnostic RFP:** Prepare Request for Proposal document for competitive bidding

Procurement & Installation (Week 8-24)

1. **Competitive Bidding (Week 8-9):** Issue RFP, receive bids, evaluate, select vendor
2. **Equipment Procurement (Week 10-15):** 6-week lead time for line arrays and specialized equipment
3. **Installation (Week 16-19):** 4-week installation period (infrastructure, interior speakers, exterior, control room)
4. **Commissioning (Week 20-21):** DSP programming, calibration, comprehensive testing
5. **Training & Handover (Week 22-23):** 5-day training program, practical examination, certification
6. **Final Acceptance (Week 24):** Live testing across all use cases, documentation delivery, formal acceptance

16.4 Long-Term Success Factors

Keys to Sustainable System Performance

1. **Designated Accountability:** Formal appointment of sound system administrator and trained operators with written responsibilities
2. **Operational Discipline:** Adherence to scene presets, volume limits, anti-tampering protocols
3. **Routine Maintenance:** Weekly cleaning, monthly audits, quarterly inspections, annual professional recalibration
4. **Documentation Rigor:** Equipment change logging, inventory tracking, measurement archiving
5. **Training Continuity:** Replacement operator training when staff turnover occurs, annual refresher courses
6. **Professional Support:** Relationship with qualified audio engineer for annual calibration and emergency troubleshooting

16.5 Final Recommendation

The Umayyad Mosque deserves a sound reinforcement system befitting its status as one of the world's most significant Islamic monuments. The current fragmented, aging, poorly maintained system fails to serve the mosque's spiritual, educational, and cultural mission.

The proposed unified, modern, professionally designed system will:

- Transform speech intelligibility from "Poor/Bad" (STI 0.28-0.45) to "Good" (STI >0.60)
- Provide uniform coverage throughout the 136m prayer hall, courtyard, and minarets

- Serve reliably for 20-30 years with proper maintenance (vs. current system's 15-35 year age with multiple failures)
- Withstand operational challenges through password protection, brick-wall limiters, and operator training
- Respect the mosque's UNESCO World Heritage architectural integrity through slim-profile speakers and concealed infrastructure

Investment Justification: The recommended Option C (\$370,000) represents approximately \$14,800 per year when amortized over a conservative 25-year service life. For a mosque serving thousands of daily worshippers and millions of annual visitors, this investment in clear, intelligible communication of religious teachings, lectures, and prayers is both spiritually and fiscally justified.

Next Step: Project Approval & AutoCAD File Provision

To proceed with implementation:

1. **Mosque Administration:** Review this comprehensive report and approve project budget (Option A, B, or C)
2. **Provide AutoCAD File:** Submit complete architectural drawings to enable final acoustic simulation
3. **Schedule Follow-Up Assessment (TBD) Measurements:** Coordinate 2-day testing window for carpet impact assessment
4. **Designate Responsible Personnel:** Formally appoint sound system administrator and operators who will receive training

Upon receipt of project approval and AutoCAD data, design finalization and competitive bidding can commence immediately.

End of Report

Comprehensive Umayyad Mosque Sound System Assessment & Redesign Proposal

Presented by Obai Sukar

obaisukar.com - Audio Engineering & Sound System Design

Assessment Report