

## Hyundai VERNA standard safety equipment





## PRIMARY SAFETY

80%

Electronic Stability Control	<b>8.0</b> max. 8
system name ESC	
Driver Monitoring System	<b>0.0</b> max. 2
system name —	
Tyre Pressure Monitoring	<b>2.0</b> max. 2

system name TPMS Highline

warning •

readout 🔸

Blind Spot Monitoring **0.0** max. 2

system name input

driver side

passenger side

Physical Controls

**6.0** max. 6

hazard lights

gear

climate

music and navigation (

turn indicators •

windscreen wipers

## **SECONDARY SAFETY**

50%

Rear Seatbelts			<b>4.0</b> max. 4	
•	outboard	centre	third row	
three-point	•		Ο	
Rear Seatbelt	Reminders		<b>2.0</b> max. 10	

Rear Seatbelt Ren	2.	<b>0</b> max. 10	
position	outboard	centre	third row
visual signal			0
acoustic signal			0
occupant detection	•	•	0
passive activation	•	•	0

Head Protection Devices			<b>5.0</b> max.	6
position	front	rear	third row	
curtain airbag			0	
centre airbag	•	0	0	
Chest Protection [	)evices	5	<b>2.0</b> max.	3

position front rear thorax airbag

Neck Restra	ints		<b>0.0</b> max.	4_
position	rear outboard	centre	third row	
$sufficient^1$			0	

Child Readi	ness		<b>2.0</b> r	max. 3
position	rear	rear	front	third
	outboard	centre	passenger	row
ISOFIX		•	•	0
i-Size	•	•	•	0
Top Tether			•	0

## **COMMENTS**

The Verna narrowly earns a three-star rating, hurt by its basic seatbelt reminders and the fact that it does not have a centre head restraint.

primary	secondary	overall		
safety	safety	result		
80%	50%			
****				
Evaluated variant: EX 1.5 MPI MT				
Evaluated on: September 12, 2025				
Protocol: FleetSure v1.0				

<sup>&</sup>lt;sup>1</sup>subjective judgment